




CAUTION LABEL ATTACHMENT POSITION

- 1 After using a degreasing agent to clean the surfaces of the body where the caution labels will be attached, attach the caution labels to the positions shown in the illustration.



HINT:

- Attach each caution label with its orientation the same as the numbers shown in the illustration.
- Make sure the caution label is not attached over a spot weld.
- When attaching the caution label, make sure not to touch the label's adhesive surface.
- To prevent the edges of the caution label from peeling, apply extra pressure to the label's periphery.
- If the work area's temperature is 5°C or less, the caution label's adhesive will deteriorate. It is recommended that you heat the label to 20 to 40°C.





[LHD]



[RHD]

