```
Landrams :-
Drive a Steppar Motor interface to rotate the motor in
 Anticlokwise by N Steps. Introduce Suitable delay blo
  Successive Steps.
-> Progam'. -
     It include < stdio.h>
     # include < reg 51.h>
       char xdate post -at- 0xe803;
        cher Xdata poroda - at - ox e 800;
        Char idata acc - at - 0x30%
        delay ()
          intj;
          for (j=0; j<860; j++)
            es .
         3
      void main ()
         Port = 0x 80;
           While (1)
         acc = 0x11;
           Porta = acc;
            delay ();
            acc = 0x22
             porta = acc',
              delay();
             acc = 0x44;
              porta = acc;
               delay ();
            acc = 0x 88
             Porta = acc
              delaye);
```