

<u>Close-up:</u> Spill due to illegal fitting on 10" Ogini-Eriemu delivery line at Ogini. Picture taken during Joint Investigation of 22nd July, 2011

1