


Overview: Part of spill impact on Opukushi Well24T flowline right of way at Agbemo-Angalebiri. Picture was taken during Joint Investigation of 30th June 2012.



<u>Close up:</u> Spill due to corrosion on Opukushi Well24T flowline at Agbemo-Angalebiri. Picture was taken during Joint Investigation of 30th June 2012.

1



Close up: Spill due to corrosion at 6 o'clock position on Opukushi Well24T flowline at Agbemo-Angalebiri.