

Overview: Awoba Well5L flowline riser at Bille. Picture taken during Joint Investigation of 21st July, 2011



<u>Close-up:</u> Spill due to corrosion on Awoba Well5L flowline riser at Bille. Picture taken during Joint Investigation of 21st July, 2011

1