

<u>Close up:</u> Spill and resulting fire caused by tempering of the isolation valve control system by unknown persons. Previous location of missing isolation valve control system on 24" Cawthorne Channel-Bonny Ball Valve Station at Kalibiama.