

Overview: Part of spill impact on Batan Well 4T 6" Flowline at Batan. Picture taken during Joint Investigation of 12th September, 2011



<u>Close-up:</u> Spill due to corrosion on Batan Well 4T 6" Flowline at Batan. Picture was taken during Joint Investigation of 12th September, 2011

1