

<u>Close-up:</u> Failed clamp point on Awoba NorthWest Well 1 L/S flow line at Boro. Picture was taken during JIV of 19th May, 2011

1