

<u>Close-up:</u> Spill due to corrosion on Cawthorne Channel 2 Well 51T flowline at Mbiama. Picture taken during Joint Investigation of 17th October, 2011.

1