

Overview: Part of spill impact on 28 inch Trans Forcados Pipeline at Batan . Picture taken during Joint Investigation of 23rd September, 2011



<u>Close-up:</u> Spill due to External Corrosion on 28 inch Trans Forcados Pipeline at Batan. Picture taken during Joint Investigation of 23rd September, 2011.

1