

<u>Close up:</u> Failed clamp on Imo River Well5 flowline at Igrukwu. Picture was taken during Joint Investigation of 26th June 2012.

1