

ID	Name	Type	Constraint	Quality	Fallback	Access	Conformance
0	RangeMin	int64	-2^{62} to 2^{62}				M
1	RangeMax	int64	-2^{62} to 2^{62}				M
2	Percent-Max	percent100ths	all				O.a+
3	Percent-Min	percent100ths	max PercentTypical				[Percent-Max]
4	Percent-Typical	percent100ths	Percent-Min to PercentMax				[Percent-Min]
5	FixedMax	uint64	$\max 2^{62} - 1$				O.a+
6	FixedMin	uint64	max Fixed-Max				[FixedMax]
7	FixedTypical	uint64	FixedMin to Fixed-Max				[FixedMin]

- If both [PercentMax](#) and [FixedMax](#) are indicated, then for a given true value in the range between [RangeMin](#) and [RangeMax](#),
 - the reported value SHALL be less than or equal to the sum of the true value, [FixedMax](#) and [PercentMax](#) percent of the true value.
 - the reported value SHALL be greater than or equal to the true value minus the sum of [FixedMax](#) and [PercentMax](#) percent of the true value.
- If only [PercentMax](#) is indicated, then for a given true value in the range between [RangeMin](#) and [RangeMax](#),
 - the reported value SHALL be less than or equal to the sum of the true value and [PercentMax](#) percent of the true value.
 - the reported value SHALL be greater than or equal to the true value minus [PercentMax](#) percent of the true value.
- If only [FixedMax](#) is indicated, then for a given true value in the range between [RangeMin](#) and [RangeMax](#),
 - the reported value SHALL be less than or equal to the sum of the true value and [FixedMax](#).
 - the reported value SHALL be greater than or equal to the true value minus [FixedMax](#).

2.12.5.1.1.1. RangeMin Field

This field SHALL indicate the minimum measurement value for the specified level of accuracy.

The value of this field SHALL be greater than or equal to the value of the [MinMeasuredValue](#) field on the encompassing [MeasurementAccuracyStruct](#).