

ID	Name	Type	Constraint	Quality	Fallback	Conformance
1	StepSize	uint16	all			M
2	Transition-Time	uint16	max 65534			M
3	ColorTemperatureMinimumMireds	uint16	max 65279			M
4	ColorTemperatureMaximumMireds	uint16	max 65279			M
5	Options-Mask	Options-Bitmap	desc			M
6	OptionsOverride	Options-Bitmap	desc			M

3.2.8.22.1. StepMode Field

This field SHALL indicate the mode of the step to be performed, as described in the [StepHue](#) command.

3.2.8.22.2. StepSize Field

This field SHALL indicate the change to be added to (or subtracted from) the current value of the device's color temperature.

3.2.8.22.3. TransitionTime Field

This field SHALL indicate, in units of 1/10ths of a second, the time that SHALL be taken to perform the step. A step is a change to the device's color temperature of a magnitude corresponding to the StepSize field.

3.2.8.22.4. ColorTemperatureMinimumMireds Field

This field SHALL indicate a lower bound on the ColorTemperatureMireds attribute ($\equiv$ an upper bound on the color temperature in kelvins) for the current step operation such that:

$\text{ColorTempPhysicalMinMireds} \leq \text{ColorTemperatureMinimumMireds field} \leq \text{ColorTemperatureMireds}$

As such if the step operation takes the ColorTemperatureMireds attribute towards the value of the ColorTemperatureMinimumMireds field it SHALL be clipped so that the above invariant is satisfied. If the ColorTemperatureMinimumMireds field is set to 0, ColorTempPhysicalMinMireds SHALL be used as the lower bound for the ColorTemperatureMireds attribute.