

Bit number		31 30 29 28 27 26 25 24 23 22 21 20 19 18 17 16 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1 0			
ID		A			
Reset 0x00000000		0 0			
ID	R/W	Field	Value ID	Value	Description
A	W	TASKS_STOP			Stop the ADC and terminate any on-going conversion
		Trigger	1		Trigger task

8.18.11.4 TASKS_CALIBRATEOFFSET

Address offset: 0x00C

Starts offset auto-calibration

Bit number		31 30 29 28 27 26 25 24 23 22 21 20 19 18 17 16 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1 0			
ID		A			
Reset 0x00000000		0 0			
ID	R/W	Field	Value ID	Value	Description
A	W	TASKS_CALIBRATEOFFSET			Starts offset auto-calibration
		Trigger	1		Trigger task

8.18.11.5 SUBSCRIBE_START

Address offset: 0x080

Subscribe configuration for task **START**

Bit number		31 30 29 28 27 26 25 24 23 22 21 20 19 18 17 16 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1 0			
ID		A A A A A A A A			
Reset 0x00000000		0 0			
ID	R/W	Field	Value ID	Value	Description
A	RW	CHIDX	[0..255]		DPPI channel that task START will subscribe to
B	RW	EN			
		Disabled	0		Disable subscription
		Enabled	1		Enable subscription

8.18.11.6 SUBSCRIBE_SAMPLE

Address offset: 0x084

Subscribe configuration for task **SAMPLE**

Bit number		31 30 29 28 27 26 25 24 23 22 21 20 19 18 17 16 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1 0			
ID		A A A A A A A A			
Reset 0x00000000		0 0			
ID	R/W	Field	Value ID	Value	Description
A	RW	CHIDX	[0..255]		DPPI channel that task SAMPLE will subscribe to
B	RW	EN			
		Disabled	0		Disable subscription
		Enabled	1		Enable subscription

8.18.11.7 SUBSCRIBE_STOP

Address offset: 0x088

Subscribe configuration for task **STOP**