Manufacturing Production Report

Production Output

The factory produces 1200 units per day across three production shifts.

Quality Control

The acceptable product defect rate is below 2 percent. Products with cracks, incorrect dimensions, or faulty components must be rejected.

Machine Maintenance

CNC machines must receive preventive maintenance every 30 days. Operators must inspect temperature, lubrication, and vibration before each shift.

Safety Procedures

Workers must wear safety helmets, protective gloves, and safety shoes. Machines must be switched off before maintenance.

Inventory Management

The warehouse must maintain a minimum stock of 500 raw material units. The inventory manager must record incoming materials and report shortages.