

Photo:2

Date:06/16/2022

Location:WL: 3, FL: 4

Condition Description: DETERIORATED BRICK
MASONRY

Recommendation: REPLACE DETERIORATED
BRICKS

Causes: IMPROPER WINDOW AC UNIT SUPPORT

Quantity: 67

