

MAINTENANCE INCIDENT REPORT

Casablanca Fleet Depot

Report date: 27 September 2026
Facility: Casablanca Fleet Depot
Vehicle: TRK-88 (Thermo King refrigerated unit)
Reported by: Depot maintenance crew

Inspection findings

Inspection performed 26 September 2026 at 09:30 following an in-transit temperature alarm on the reefer trailer. The Thermo King reefer compressor was examined and severe drive-belt wear was observed: glazing, cracking and reduced belt tension, consistent with overheating and intermittent loss of cooling capacity.

Corrective action status

Replacement drive belts are currently ON BACKORDER with the parts supplier. No repair is possible until the part arrives.

Operational decision

Vehicle TRK-88 has been CLEARED FOR SHORT-RUN SERVICE ONLY under a deferred maintenance notice. Long-haul dispatch is prohibited until the compressor drive belt is replaced and the reefer unit passes a full cool-down check. Any in-transit temperature excursion on this vehicle must be reported to fleet control immediately.

Report ref: WKL-20260927-TRK88