F2 **Esc** F1 F3 F4 **F**5 F6 **F7** F8 F9 F10 F11 Unselect **Options** tool menu 2 3 5 6 7 8 9 Delete probes Add probe Wide lw Ε Ascend R P Y U 0 Editor wire read Tab **Descend** Display **Properties Rotate** Undo Pin Wire **Edit text Instance** settinas read S D F G Н J K Caps Lock Fit-to-Find Label marker screen Check X Ν Text М Shift Z C V В < > Note Note Save Copy **Block** Move shape Win Alt Ctrl Alt Create nets and labels automatically AnalogHub.ie

Default bindkeys (schematic)

F12

Switch

view

Zoom in

Shift

公

Zoom out

ш

Win

?

Del

Comment

Delete component

Backspace

Enter

Ctrl