

and the tool is called drill bit. The job is to be drilled is held firmly in a vice or in any other clamping device on the table of the machine.

(vi) Scraping

This is ^{the} operation for removing for convex surfaces left after filing.

Fitting Tools

1) Holding Tools :-

These are the tools and are used for holding the job to be worked

(a) Bench vice

This is most commonly used holding device called Engineer's parallel low bench vice or fitter's vice.

It basically consist of a cast iron body, a fixed jaw of a movable jaw of cast steel. A handle square threaded screw and nut made of solid steel, the size of the vice is designated by the width of jaw which is from 80 to 140mm and its maximum opening from 95 to 180mm

(b) Leg Vice

It is secured firmly at bench top. Its leg is attached to the leg of the bench and its end goes into the hole made up at the floor. It is used for hammering, clipping and cutting in the fitting shop