

		M T W T F S S						
EXPT. NO.	NAME	Page No.:		Date:				
				YOUVA				
		holder						
	Surface cleaning	Clean joint area for proper welding		Wire Brush				
	Edge Preparation	Make angle of 45° by creating a V-shape structure, one edge of metal and place them together		Welding table Electrode Holder				
	Tack welding	Apply tack welds at both ends of the joint		Tongs, Clamp, gloves helmet Electrode holder				
	Welding Operation	Work pieces are kept in required position and arc welding is performed on both sides sequentially		Tongs, gloves, Helmet Electrode holder				
	Finishing and Inspection	Allow to cool, inspect weld quality and remove slugs		Chipping Hammer				

Precautions

- Working area and floors should be kept clean and dry
- Before starting welding ensure that welding equipment is adequately earthed
- One should not look at an electric arc with naked eye
- To prevent from radiation slag spatter a helmet or

Teacher's Signature: _____