Q1 Production Logs | 1 Mar 26

February 26 Logs

2-3 Quality Control implemented Dir 77: The primary CNC router (Mach #4) must halt immediately if the downstream thermal cooling buffer exceeds 20 units to prevent thermal warping of the plastic casings. SCADA is programmed to record these specific buffer halts as Fault Code 404: Spindle Idle.

2-11 Bearing pneumatic valve on Mach 2. Unplanned outage. DT 180 min

2-17 Shift supervisor files critical report: Mach 4 is constantly pulling out. Formally requesting $2.5M capex to replace Mach #4 due to chronic spindle faults destroying our cycle time.

2-26 Catastrophic blade shatter on Mach #1. Unplanned outage: D/T 1 hr 40 min