



B-1 Lancer



Supplying Warfighter Dominance



Hydraulic Filter: Market Research

Tinker AFB – 423rd SCMS



MD:	B-1
TMS:	N/A
Noun:	Hydraulic Filter
NSN:	1650-01-187-5462
P/N:	426676
Forecasted Buy Price:	\$8736.72
Forecasted Repair Cost:	N/A
AAC:	C
Unserv. Assets Avail:	N/A
QPA/APPL Rate:	1 100%

AMC/AMSC:	4	P
RMC/RMSC:	N/A	N/A
Material:	Aluminum Alloy	
Dimensions:	8.0"L x 4.0"W	
Drawings Releasable:	N/A	
Drawing #:	N/A	
Drawing Cage Code:	N/A	
T.O. Releasable:	N/A	
T.O. #:	N/A	
Budget Code:	8	
Next Higher Asmbly:	N/A	

Out Year Requirements: BUY									
FY26:	3	FY27:	0	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Not Available	RDL:	Not Available
Tinker	-----	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- Market research for a potential procurement source and/or finding a manufacturer to produce the Hydraulic Filter.
- If interested, please submit capabilities statement to our workflow at 429SCMS.SASPO.Workflow@us.af.mil

Supplying Warfighter Dominance



Miter Gear Bevel: AS – New Buy

Tinker AFB – 422nd SCMS



MD:	B-1	
TMS:	N/A	
Noun:	Miter Gear Bevel	
NSN:	3020-01-204-7592	
P/N:	474743-001	
Forecasted Buy Price:	\$361.15	
Forecasted Repair Cost:	N/A	
AAC:	Z	
Unserv. Assets Avail:	N/A	
QPA/APPL Rate:	N/A	N/A

AMC/AMSC:	2	G
RMC/RMSC:	N/A	N/A
Material:	Steel, Corrosion Resisting Overall	
Dimensions:	N/A	
Drawings Releasable:	Yes	
Drawing #:	474743	
Drawing Cage Code:	89305	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	9	
Next Higher Asmbly:	Indicator, Liquid	

Out Year Requirements: BUY									
FY26:	2	FY27:	0	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Available	RDL:	Not Available
Tinker	-----	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- Interested vendors should submit a Capabilities Statement to 429SCMS.SASPO.Workflow@us.af.mil
- No Source Approval Request (SAR) Package required due to AMSC code of G (full and open competition)
- Visit dibbs.bsm.dla.mil for solicitation

Supplying Warfighter Dominance



B-52H Bomber



Supplying Warfighter Dominance



No. 3 Pilot LH Windshield: Rev. Engineering

Tinker AFB – AFLCMC



MD:	B-52		
TMS:	N/A		
Noun:	No. 3 Pilot LH, Windshield, Aircraft		
NSN:	1560-01-576-3458		
P/N:	520-14072-3		
Forecasted Buy Price:	\$7143.55		
Forecasted Repair Cost:	\$0.00		
AAC:	Z		
Unserv. Assets Avail:	0		
QPA/APPL Rate:	1		100

AMC/AMSC:	3	B
RMC/RMSC:	N/A	N/A
Material:	GLASS, LAMINATED, AIRCRAFT GLAZING AMS-G-25871 ASSN STD SINGLE MATERIAL RESPONSE	
Dimensions:	Not Available	
Drawings Releasable:	No	
Drawing #:	Not Available	
Drawing Cage Code:	Not Available	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	9	
Next Higher Asmbly:	520-14787	

Out Year Requirements: BUY									
FY26:	9	FY27:	9	FY28:	9	FY29:	9	FY30:	9

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Available	RDL:	Not Available
Tinker	8/7/2025	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Complete Technical Data Package, Prototype, 3D Modeling Data, Specification Control Drawing Testing and Evaluation
- Interested vendors should submit a White Paper to 429SCMS.SASPO.Workflow@us.af.mil
- RSVP for Technical Discussion

Supplying Warfighter Dominance



No. 3 Pilot LH Windshield: Rev. Engineering Tinker AFB – AFLCMC



Additional Comments

- B-52 has experienced a common problem over the past several years, with the problem increasing significantly within the past seven months – not having serviceable replacement windows available from supply. B-52 windows are routinely evaluated while the aircraft is operating in the field and when the aircraft returns to Tinker AFB for Programmed Depot Maintenance (PDM). Windows #1, #2LH, #2RH, #3LH, #3RH, #4LH, #4RH, #5LH, and #5RH are electrically heated and constructed of two layers of laminated glass sandwiching a vinyl core. Replacement worthy structural defects commonly found include delamination between layers, vinyl core cracking, permanent vinyl core cloudiness, and glass pane cracking, scratching, and chipping. Contracts for new window deliveries have been allowed to go delinquent for years with the main manufacturer citing a variety of excuses. This lack of contract delivery has come to the forefront now that supply has been all but depleted and forced B-52 engineering to inspect discrepant windows on a case-by-case basis to determine capability to fly as-is in order to avoid grounding aircraft. A sustainable alternative to get B-52 windows back on the shelf is imperative if the fleet is to continue to operate through 2050+.

If you would like to participate in the Technical Discussion on:

Tuesday, May 5, 2026, 2:00 PM – 3:00 PM CT.

provide the following, NLT

Monday, April 20, 2026

429SCMS.SASPO.Workflow@us.af.mil

-Company, -Address, -Name(s), -Email(s), -Phone,

-Your questions for Engineering, and

-Statement of Capabilities

Supplying Warfighter Dominance



No. 2 Pilot LH Windshield: Rev. Engineering Tinker AFB – AFLCMC



MD:	B-52		
TMS:	N/A		
Noun:	No. 2 Pilot LH, Windshield, Aircraft		
NSN:	1560-01-576-3475		
P/N:	520-14072-1		
Forecasted Buy Price:	\$9713.56		
Forecasted Repair Cost:	\$0.00		
AAC:	Z		
Unserv. Assets Avail:	0		
QPA/APPL Rate:	1		100

AMC/AMSC:	3	B
RMC/RMSC:	N/A	N/A
Material:	GLASS, LAMINATED, AIRCRAFT GLAZING AMS-G-25871 ASSN STD SINGLE MATERIAL RESPONSE	
Dimensions:	Not Available	
Drawings Releasable:	No	
Drawing #:	Not Available	
Drawing Cage Code:	Not Available	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	9	
Next Higher Asmbly:	520-14781	

Out Year Requirements: BUY									
FY26:	8	FY27:	8	FY28:	8	FY29:	8	FY30:	8

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Available	RDL:	Not Available
Tinker	8/7/2025	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Complete Technical Data Package, Prototype, 3D Modeling Data, Specification Control Drawing Testing and Evaluation
- Interested vendors should submit a White Paper to 429SCMS.SASPO.Workflow@us.af.mil
- RSVP for Technical Discussion

Supplying Warfighter Dominance



No. 2 Pilot LH Windshield: Rev. Engineering Tinker AFB – AFLCMC



Additional Comments

- B-52 has experienced a common problem over the past several years, with the problem increasing significantly within the past seven months – not having serviceable replacement windows available from supply. B-52 windows are routinely evaluated while the aircraft is operating in the field and when the aircraft returns to Tinker AFB for Programmed Depot Maintenance (PDM). Windows #1, #2LH, #2RH, #3LH, #3RH, #4LH, #4RH, #5LH, and #5RH are electrically heated and constructed of two layers of laminated glass sandwiching a vinyl core. Replacement worthy structural defects commonly found include delamination between layers, vinyl core cracking, permanent vinyl core cloudiness, and glass pane cracking, scratching, and chipping. Contracts for new window deliveries have been allowed to go delinquent for years with the main manufacturer citing a variety of excuses. This lack of contract delivery has come to the forefront now that supply has been all but depleted and forced B-52 engineering to inspect discrepant windows on a case-by-case basis to determine capability to fly as-is in order to avoid grounding aircraft. A sustainable alternative to get B-52 windows back on the shelf is imperative if the fleet is to continue to operate through 2050+.

If you would like to participate in the Technical Discussion on:

Tuesday, May 5, 2026, 2:00 PM – 3:00 PM CT.

provide the following, NLT

Monday, April 20, 2026

429SCMS.SASPO.Workflow@us.af.mil

-Company, -Address, -Name(s), -Email(s), -Phone,

-Your questions for Engineering, and

-Statement of Capabilities

Supplying Warfighter Dominance



No. 5 LH & RH Windshield: Rev. Engineering Tinker AFB – AFLCMC



MD:	B-52	
TMS:	N/A	
Noun:	No. 5 LH & RH Windshield, Aircraft	
NSN:	1560-01-575-1517	
P/N:	520-14072-7	
Forecasted Buy Price:	\$7,008.28	
Forecasted Repair Cost:	\$0.00	
AAC:	Z	
Unserv. Assets Avail:	0	
QPA/APPL Rate:	1	100

AMC/AMSC:	3	B
RMC/RMSC:	N/A	N/A
Material:	GLASS, LAMINATED, AIRCRAFT GLAZING AMS-G-25871 ASSN STD SINGLE MATERIAL RESPONSE	
Dimensions:	Not Available	
Drawings Releasable:	No	
Drawing #:	Not Available	
Drawing Cage Code:	Not Available	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	9	
Next Higher Asmbly:	520-14784	

Out Year Requirements: BUY									
FY26:	15	FY27:	15	FY28:	15	FY29:	15	FY30:	15

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Available	RDL:	Not Available
Tinker	8/7/2025	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Complete Technical Data Package, Prototype, 3D Modeling Data, Specification Control Drawing Testing and Evaluation
- Interested vendors should submit a White Paper to 429SCMS.SASPO.Workflow@us.af.mil
- RSVP for Technical Discussion

Supplying Warfighter Dominance



No. 5 LH & RH Windshield: Rev. Engineering Tinker AFB – AFLCMC



Additional Comments

- B-52 has experienced a common problem over the past several years, with the problem increasing significantly within the past seven months – not having serviceable replacement windows available from supply. B-52 windows are routinely evaluated while the aircraft is operating in the field and when the aircraft returns to Tinker AFB for Programmed Depot Maintenance (PDM). Windows #1, #2LH, #2RH, #3LH, #3RH, #4LH, #4RH, #5LH, and #5RH are electrically heated and constructed of two layers of laminated glass sandwiching a vinyl core. Replacement worthy structural defects commonly found include delamination between layers, vinyl core cracking, permanent vinyl core cloudiness, and glass pane cracking, scratching, and chipping. Contracts for new window deliveries have been allowed to go delinquent for years with the main manufacturer citing a variety of excuses. This lack of contract delivery has come to the forefront now that supply has been all but depleted and forced B-52 engineering to inspect discrepant windows on a case-by-case basis to determine capability to fly as-is in order to avoid grounding aircraft. A sustainable alternative to get B-52 windows back on the shelf is imperative if the fleet is to continue to operate through 2050+.

If you would like to participate in the Technical Discussion on:

Tuesday, May 5, 2026, 2:00 PM – 3:00 PM CT.

provide the following, NLT

Monday, April 20, 2026

429SCMS.SASPO.Workflow@us.af.mil

-Company, -Address, -Name(s), -Email(s), -Phone,

-Your questions for Engineering, and

-Statement of Capabilities

Supplying Warfighter Dominance



No. 4 Copilot RH Windshield: Rev. Engineering Tinker AFB – AFLCMC



MD:	B-52		
TMS:	N/A		
Noun:	No. 4 Copilot RH, Windshield, Aircraft		
NSN:	1560-01-576-3483		
P/N:	520-14072-6		
Forecasted Buy Price:	\$8916.86		
Forecasted Repair Cost:	\$0.00		
AAC:	Z		
Unserv. Assets Avail:	0		
QPA/APPL Rate:	1		100

AMC/AMSC:	1	B
RMC/RMSC:	N/A	N/A
Material:	GLASS, LAMINATED, AIRCRAFT GLAZING AMS-G-25871 ASSN STD SINGLE MATERIAL RESPONSE	
Dimensions:	Not Available	
Drawings Releasable:	No	
Drawing #:	Not Available	
Drawing Cage Code:	Not Available	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	9	
Next Higher Asmbly:	520-14783	

Out Year Requirements: BUY									
FY26:	9	FY27:	9	FY28:	9	FY29:	9	FY30:	9

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Available	RDL:	Not Available
Tinker	8/7/2025	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Complete Technical Data Package, Prototype, 3D Modeling Data, Specification Control Drawing Testing and Evaluation
- Interested vendors should submit a White Paper to 429SCMS.SASPO.Workflow@us.af.mil
- RSVP for Technical Discussion

Supplying Warfighter Dominance



No. 4 Copilot RH Windshield: Rev. Engineering Tinker AFB – AFLCMC



Additional Comments

- B-52 has experienced a common problem over the past several years, with the problem increasing significantly within the past seven months – not having serviceable replacement windows available from supply. B-52 windows are routinely evaluated while the aircraft is operating in the field and when the aircraft returns to Tinker AFB for Programmed Depot Maintenance (PDM). Windows #1, #2LH, #2RH, #3LH, #3RH, #4LH, #4RH, #5LH, and #5RH are electrically heated and constructed of two layers of laminated glass sandwiching a vinyl core. Replacement worthy structural defects commonly found include delamination between layers, vinyl core cracking, permanent vinyl core cloudiness, and glass pane cracking, scratching, and chipping. Contracts for new window deliveries have been allowed to go delinquent for years with the main manufacturer citing a variety of excuses. This lack of contract delivery has come to the forefront now that supply has been all but depleted and forced B-52 engineering to inspect discrepant windows on a case-by-case basis to determine capability to fly as-is in order to avoid grounding aircraft. A sustainable alternative to get B-52 windows back on the shelf is imperative if the fleet is to continue to operate through 2050+.

If you would like to participate in the Technical Discussion on:

Tuesday, May 5, 2026, 2:00 PM – 3:00 PM CT.

provide the following, NLT

Monday, April 20, 2026

429SCMS.SASPO.Workflow@us.af.mil

-Company, -Address, -Name(s), -Email(s), -Phone,

-Your questions for Engineering, and

-Statement of Capabilities

Supplying Warfighter Dominance



No. 3 Copilot RH Windshield: Rev. Engineering Tinker AFB – AFLCMC



MD:	B-52	
TMS:	N/A	
Noun:	No. 3 Copilot LH, Windshield, Aircraft	
NSN:	1560-01-576-3498	
P/N:	520-14072-4	
Forecasted Buy Price:	\$5822.12	
Forecasted Repair Cost:	\$0.00	
AAC:	Z	
Unserv. Assets Avail:	0	
QPA/APPL Rate:	1	100

AMC/AMSC:	3	B
RMC/RMSC:	N/A	N/A
Material:	GLASS, LAMINATED, AIRCRAFT GLAZING AMS-G-25871 ASSN STD SINGLE MATERIAL RESPONSE	
Dimensions:	Not Available	
Drawings Releasable:	No	
Drawing #:	Not Available	
Drawing Cage Code:	Not Available	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	9	
Next Higher Asmbly:	520-14787	

Out Year Requirements: BUY									
FY26:	16	FY27:	16	FY28:	16	FY29:	16	FY30:	16

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Available	RDL:	Not Available
Tinker	8/7/2025	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Complete Technical Data Package, Prototype, 3D Modeling Data, Specification Control Drawing Testing and Evaluation
- Interested vendors should submit a White Paper to 429SCMS.SASPO.Workflow@us.af.mil
- RSVP for Technical Discussion

Supplying Warfighter Dominance



No. 3 Copilot RH Windshield: Rev. Engineering Tinker AFB – AFLCMC



Additional Comments

- B-52 has experienced a common problem over the past several years, with the problem increasing significantly within the past seven months – not having serviceable replacement windows available from supply. B-52 windows are routinely evaluated while the aircraft is operating in the field and when the aircraft returns to Tinker AFB for Programmed Depot Maintenance (PDM). Windows #1, #2LH, #2RH, #3LH, #3RH, #4LH, #4RH, #5LH, and #5RH are electrically heated and constructed of two layers of laminated glass sandwiching a vinyl core. Replacement worthy structural defects commonly found include delamination between layers, vinyl core cracking, permanent vinyl core cloudiness, and glass pane cracking, scratching, and chipping. Contracts for new window deliveries have been allowed to go delinquent for years with the main manufacturer citing a variety of excuses. This lack of contract delivery has come to the forefront now that supply has been all but depleted and forced B-52 engineering to inspect discrepant windows on a case-by-case basis to determine capability to fly as-is in order to avoid grounding aircraft. A sustainable alternative to get B-52 windows back on the shelf is imperative if the fleet is to continue to operate through 2050+.

If you would like to participate in the Technical Discussion on:

Tuesday, May 5, 2026, 2:00 PM – 3:00 PM CT.

provide the following, NLT

Monday, April 20, 2026

429SCMS.SASPO.Workflow@us.af.mil

-Company, -Address, -Name(s), -Email(s), -Phone,

-Your questions for Engineering, and

-Statement of Capabilities

Supplying Warfighter Dominance



No. 4 Pilot LH Windshield: Rev. Engineering Tinker AFB – AFLCMC



MD:	B-52		
TMS:	N/A		
Noun:	No. 4 Pilot LH, Windshield, Aircraft		
NSN:	1560-01-576-3500		
P/N:	520-14072-6		
Forecasted Buy Price:	\$9061.44		
Forecasted Repair Cost:	\$0.00		
AAC:	Z		
Unserv. Assets Avail:	0		
QPA/APPL Rate:	1		100

AMC/AMSC:	3	B
RMC/RMSC:	N/A	N/A
Material:	GLASS, LAMINATED, AIRCRAFT GLAZING AMS-G-25871 ASSN STD SINGLE MATERIAL RESPONSE	
Dimensions:	Not Available	
Drawings Releasable:	No	
Drawing #:	Not Available	
Drawing Cage Code:	Not Available	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	9	
Next Higher Asmbly:	520-14783	

Out Year Requirements: BUY									
FY26:	5	FY27:	5	FY28:	5	FY29:	5	FY30:	5

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Available	RDL:	Not Available
Tinker	8/7/2025	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Complete Technical Data Package, Prototype, 3D Modeling Data, Specification Control Drawing Testing and Evaluation
- Interested vendors should submit a White Paper to 429SCMS.SASPO.Workflow@us.af.mil
- RSVP for Technical Discussion

Supplying Warfighter Dominance



No. 4 Pilot LH Windshield: Rev. Engineering Tinker AFB – AFLCMC



Additional Comments

- B-52 has experienced a common problem over the past several years, with the problem increasing significantly within the past seven months – not having serviceable replacement windows available from supply. B-52 windows are routinely evaluated while the aircraft is operating in the field and when the aircraft returns to Tinker AFB for Programmed Depot Maintenance (PDM). Windows #1, #2LH, #2RH, #3LH, #3RH, #4LH, #4RH, #5LH, and #5RH are electrically heated and constructed of two layers of laminated glass sandwiching a vinyl core. Replacement worthy structural defects commonly found include delamination between layers, vinyl core cracking, permanent vinyl core cloudiness, and glass pane cracking, scratching, and chipping. Contracts for new window deliveries have been allowed to go delinquent for years with the main manufacturer citing a variety of excuses. This lack of contract delivery has come to the forefront now that supply has been all but depleted and forced B-52 engineering to inspect discrepant windows on a case-by-case basis to determine capability to fly as-is in order to avoid grounding aircraft. A sustainable alternative to get B-52 windows back on the shelf is imperative if the fleet is to continue to operate through 2050+.

If you would like to participate in the Technical Discussion on:

Tuesday, May 5, 2026, 2:00 PM – 3:00 PM CT.

provide the following, NLT

Monday, April 20, 2026

429SCMS.SASPO.Workflow@us.af.mil

-Company, -Address, -Name(s), -Email(s), -Phone,

-Your questions for Engineering, and

-Statement of Capabilities

Supplying Warfighter Dominance



No. 2 Copilot RH Windshield: Rev. Engineering Tinker AFB – AFLCMC



MD:	B-52		
TMS:	N/A		
Noun:	No. 2 Copilot RH, Windshield, Aircraft		
NSN:	1560-01-576-3466		
P/N:	520-14072-2		
Forecasted Buy Price:	\$9999.27		
Forecasted Repair Cost:	\$0.00		
AAC:	Z		
Unserv. Assets Avail:	0		
QPA/APPL Rate:	1		100

AMC/AMSC:	3	B
RMC/RMSC:	N/A	N/A
Material:	GLASS, LAMINATED, AIRCRAFT GLAZING AMS-G-25871 ASSN STD SINGLE MATERIAL RESPONSE	
Dimensions:	Not Available	
Drawings Releasable:	No	
Drawing #:	Not Available	
Drawing Cage Code:	Not Available	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	9	
Next Higher Asmbly:	520-14781	

Out Year Requirements: BUY									
FY26:	9	FY27:	9	FY28:	9	FY29:	9	FY30:	9

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Available	RDL:	Not Available
Tinker	8/7/2025	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Source Approval Request (SAR) Package.
- Interested vendors should submit a Source Approval Request (SAR) to dlaavnsmallbus@dla.mil
- **NOTE:** Send notification to 429SCMS.SASPO.Workflow@us.af.mil within 45 days of intent to submit SAR package.

Supplying Warfighter Dominance



No. 2 Copilot RH Windshield: Rev. Engineering Tinker AFB – AFLCMC



Additional Comments

- B-52 has experienced a common problem over the past several years, with the problem increasing significantly within the past seven months – not having serviceable replacement windows available from supply. B-52 windows are routinely evaluated while the aircraft is operating in the field and when the aircraft returns to Tinker AFB for Programmed Depot Maintenance (PDM). Windows #1, #2LH, #2RH, #3LH, #3RH, #4LH, #4RH, #5LH, and #5RH are electrically heated and constructed of two layers of laminated glass sandwiching a vinyl core. Replacement worthy structural defects commonly found include delamination between layers, vinyl core cracking, permanent vinyl core cloudiness, and glass pane cracking, scratching, and chipping. Contracts for new window deliveries have been allowed to go delinquent for years with the main manufacturer citing a variety of excuses. This lack of contract delivery has come to the forefront now that supply has been all but depleted and forced B-52 engineering to inspect discrepant windows on a case-by-case basis to determine capability to fly as-is in order to avoid grounding aircraft. A sustainable alternative to get B-52 windows back on the shelf is imperative if the fleet is to continue to operate through 2050+.

If you would like to participate in the Technical Discussion on:

Tuesday, May 5, 2026, 2:00 PM – 3:00 PM CT.

provide the following, NLT

Monday, April 20, 2026

429SCMS.SASPO.Workflow@us.af.mil

-Company, -Address, -Name(s), -Email(s), -Phone,

-Your questions for Engineering, and

-Statement of Capabilities

Supplying Warfighter Dominance



No. 1 Windshield: Rev. Engineering Tinker AFB – AFLCMC



MD:	B-52	
TMS:	N/A	
Noun:	No. 1 Windshield, Aircraft	
NSN:	1560-01-576-3572	
P/N:	520-14072-9	
Forecasted Buy Price:	\$6574.97	
Forecasted Repair Cost:	\$0.00	
AAC:	Z	
Unserv. Assets Avail:	0	
QPA/APPL Rate:	1	100

AMC/AMSC:	3	B
RMC/RMSC:	N/A	N/A
Material:	GLASS, LAMINATED, AIRCRAFT GLAZING AMS-G-25871 ASSN STD SINGLE MATERIAL RESPONSE	
Dimensions:	Not Available	
Drawings Releasable:	No	
Drawing #:	Not Available	
Drawing Cage Code:	Not Available	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	9	
Next Higher Asmbly:	520-14780	

Out Year Requirements: BUY									
FY26:	16	FY27:	16	FY28:	16	FY29:	16	FY30:	16

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Available	RDL:	Not Available
Tinker	8/7/2025	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Complete Technical Data Package, Prototype, 3D Modeling Data, Specification Control Drawing Testing and Evaluation
- Interested vendors should submit a White Paper to 429SCMS.SASPO.Workflow@us.af.mil
- RSVP for Technical Discussion

Supplying Warfighter Dominance



No. 1 Windshield: Rev. Engineering Tinker AFB – AFLCMC



Additional Comments

- B-52 has experienced a common problem over the past several years, with the problem increasing significantly within the past seven months – not having serviceable replacement windows available from supply. B-52 windows are routinely evaluated while the aircraft is operating in the field and when the aircraft returns to Tinker AFB for Programmed Depot Maintenance (PDM). Windows #1, #2LH, #2RH, #3LH, #3RH, #4LH, #4RH, #5LH, and #5RH are electrically heated and constructed of two layers of laminated glass sandwiching a vinyl core. Replacement worthy structural defects commonly found include delamination between layers, vinyl core cracking, permanent vinyl core cloudiness, and glass pane cracking, scratching, and chipping. Contracts for new window deliveries have been allowed to go delinquent for years with the main manufacturer citing a variety of excuses. This lack of contract delivery has come to the forefront now that supply has been all but depleted and forced B-52 engineering to inspect discrepant windows on a case-by-case basis to determine capability to fly as-is in order to avoid grounding aircraft. A sustainable alternative to get B-52 windows back on the shelf is imperative if the fleet is to continue to operate through 2050+.

If you would like to participate in the Technical Discussion on:

Tuesday, May 5, 2026, 2:00 PM – 3:00 PM CT.

provide the following, NLT

Monday, April 20, 2026

429SCMS.SASPO.Workflow@us.af.mil

-Company, -Address, -Name(s), -Email(s), -Phone,

-Your questions for Engineering, and

-Statement of Capabilities



RPU Compression Motor: Market Research

Robins AFB – 407th SCMS



MD:	AN/APQ-166 (B-52)	
TMS:	N/A	
Noun:	RPU Compression Motor	
NSN:	6105-00-870-7919	
P/N:	35YH68	
Forecasted Buy Price:	\$3,836.25	
Forecasted Repair Cost:	N/A	
AAC:	Z	
Unserv. Assets Avail:	N/A	
QPA/APPL Rate:	N/A	N/A

AMC/AMSC:	3	D
RMC/RMSC:	N/A	N/A
Material:	Not Available	
Dimensions:	OVERALL, HEIGHT 3.125 INCHES OVERALL LENGTH 5.015 INCHES	
Drawings Releasable:	No	
Drawing #:	Not Available	
Drawing Cage Code:	Not Available	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	9	
Next Higher Asmbly:	Not Available	

Out Year Requirements: BUY									
FY26:	18	FY27:	18	FY28:	18	FY29:	18	FY30:	18

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Not Available	RDL:	Not Available
Tinker	-----	Robins	3/26/2026
Hill	-----	Virtual	-----

Comments

- Interested vendors should submit a Capabilities Statement to 429SCMS.SASPO.Workflow@us.af.mil
- No Source Approval Request (SAR) Package required

Supplying Warfighter Dominance



RPU Compression Motor: Market Research

Robins AFB – 407th SCMS



Additional Comments

- The RPU compression motor is utilized to run the air compressor for the Radar Pressurization Unit for the APQ-166 system. The motor is obsolete and difficult to procure. We are highly interested in procuring a reliable replacement in order to continue to utilize the system until the RMP is deployed across the B-52 aircraft.



C-130 Hercules



Supplying Warfighter Dominance



Air Speed Indicator: Rev Eng – OTA

Robins AFB – 409th SCMS



MD:	C-130		
TMS:	N/A		
Noun:	Air Speed Indicator		
NSN:	6610-01-263-1400		
P/N:	532-38105-202		
Forecasted Buy Price:	\$72,631.75		
Forecasted Repair Cost:	\$1,852.83		
AAC:	C		
Unserv. Assets Avail:	Yes		
QPA/APPL Rate:	2		44%

AMC/AMSC:	3	R
RMC/RMSC:	1	C
Material:	N/A	
Dimensions:	WIDTH 3.190 INCHES MAXIMUM LENGTH 6.620 INCHES NOMINAL DEPTH 5.500 INCHES NOMINAL	
Drawings Releasable:	No	
Drawing #:	Not Available	
Drawing Cage Code:	Not Available	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	8	
Next Higher Asmbly:	Not Available	

Out Year Requirements: BUY									
FY26:	29	FY27:	0	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Not Available	RDL:	Available
Tinker	2024, 8/7/2025	Robins	2024, 2025, 3/26/2026
Hill		Virtual	-----

Comments

- **Deliverables:** Complete Technical Data Package, Prototype, 3D Modeling Data, Specification Control Drawing Testing and Evaluation
- **OTA Project:** Must be member of SOSSEC Consortium
- Interested vendors should submit a White Paper to 429SCMS.SASPO.Workflow@us.af.mil
- RSVP for Technical Discussion

Supplying Warfighter Dominance



Air Speed Indicator: Rev Eng – OTA Robins AFB – 409th SCMS



Additional Comments

- The Government has a need to procure NSN 6110-01-263-1400LG. The Government recently tried to award a 5-year procurement contract, but the company is unwilling to start producing these again. These assets are currently being repaired under a 5-year repair contract, If spares are not added to the supply chain, the supply will eventually run out as parts are deemed 'uneconomical to repair'.

If you would like to participate in the Technical Discussion on:

Tuesday, April 28th, 2026, 10:00AM – 11:00AM CT

provide the following, NLT

Tuesday, April 14th, 2026

429SCMS.SASPO.Workflow@us.af.mil

-Company, -Address, -Name(s), -Email(s), -Phone,

-Your questions for Engineering, and

-Statement of Capabilities

Supplying Warfighter Dominance



Digital Fuel Quantity Totalizer: Rev Eng – OTA

Robins AFB – 409th SCMS



MD:	C-130	
TMS:	N/A	
Noun:	Digital Fuel Quantity Totalizer	
NSN:	6680-01-394-2555	
P/N:	10097-0101	
Forecasted Buy Price:	\$13,351.45	
Forecasted Repair Cost:	\$4,481.00	
AAC:	C	
Unserv. Assets Avail:	No	
QPA/APPL Rate:	1	61%

AMC/AMSC:	3	B
RMC/RMSC:	3	R
Material:	Not Available	
Dimensions:	Not Available	
Drawings Releasable:	No	
Drawing #:	Not Available	
Drawing Cage Code:	Not Available	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	8	
Next Higher Asmbly:	N/A	

Out Year Requirements: BUY									
FY26:	8	FY27:	0	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Not Available	RDL:	Available
Tinker	8/7/2025	Robins	2025, 3/26/2026
Hill	-----	Virtual	-----

Comments

- **Deliverables:** Complete Technical Data Package, Prototype, 3D Modeling Data, Specification Control Drawing Testing and Evaluation
- **OTA Project:** Must be member of SOSSEC Consortium
- Interested vendors should submit a White Paper to 429SCMS.SASPO.Workflow@us.af.mil
- RSVP for Technical Discussion

Supplying Warfighter Dominance



Digital Fuel Quantity Totalizer: Rev Eng – OTA

Robins AFB – 409th SCMS



Additional Comments

- The Government has a need to procure NSN 6680-01-394-2555LG. This is an ERRC T item and currently on a repair contract, but we have minimal carcasses for repair. Government recently tried to award a procurement contract to for this part, but the company was unable to provide a proposal due to obsolescence. If spares are not added to the supply chain, the supply will eventually run out of assets to support the warfighter.

If you would like to participate in the Technical Discussion on:

Tuesday, April 28th, 2026, 10:00AM – 11:00AM CT

provide the following, NLT

Tuesday, April 14th, 2026

429SCMS.SASPO.Workflow@us.af.mil

-Company, -Address, -Name(s), -Email(s), -Phone,

-Your questions for Engineering, and

-Statement of Capabilities

Supplying Warfighter Dominance

Ground Collision Avoidance Computer: Rev Eng – OTA

Robins AFB – 409th SCMS



MD:	C-130
TMS:	N/A
Noun:	Ground Collision Avoidance Computer
NSN:	5841-01-463-3343/5841-01-449-9255
P/N:	965-0636-003-B02-B03/965-0636-B02-B02
Forecasted Buy Price:	\$47,763.54
Forecasted Repair Cost:	\$15,167.29
AAC:	
Unserv. Assets Avail:	N/A
QPA/APPL Rate:	1 100%

AMC/AMSC:	3	Z
RMC/RMSC:	5	R
Material:	Not Available	
Dimensions:	Not Available	
Drawings Releasable:	No	
Drawing #:	Not Available	
Drawing Cage Code:	Not Available	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	8	
Next Higher Asmbly:	Not Available	

Out Year Requirements: BUY									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Not Available	RDL:	Not Available
Tinker	-----	Robins	3/26/2026
Hill	-----	Virtual	-----

Comments

- **Deliverables:** Complete Technical Data Package, Prototype, 3D Modeling Data, Specification Control Drawing Testing and Evaluation
- **OTA Project:** Must be member of SOSSEC Consortium
- Interested vendors should submit a White Paper to 429SCMS.SASPO.Workflow@us.af.mil
- RSVP for Technical Discussion

Supplying Warfighter Dominance

Ground Collision Avoidance Computer: Rev Eng – OTA

Robins AFB – 409th SCMS



Additional Comments

- The NSN is currently repaired, but F condition quantities are minimal; spares required to increase inventory levels. The repair company does not have the TDP rights or the tooling from the OEM to produce more of this item. The GCAC is part of a Ground Collision Avoidance System (GCAS) that provides visual and aural warnings to the crew if the aircraft is approaching terrain too closely, essentially acting as a safety measure to prevent controlled flight into terrain (CFIT) The GCAC alerts the aircraft when a collision with the ground is likely. GCAC provides visual and aural warnings to the pilot and copilot that help identify the cause of the warning and take appropriate action.

If you would like to participate in the Technical Discussion on:

Tuesday, April 28th, 2026, 10:00AM – 11:00AM CT

provide the following, NLT

Tuesday, April 14th, 2026

429SCMS.SASPO.Workflow@us.af.mil

-Company, -Address, -Name(s), -Email(s), -Phone,

-Your questions for Engineering, and

-Statement of Capabilities

Supplying Warfighter Dominance



Navigation Data Converter: Rev Eng – OTA

Robins AFB – 409th SCMS



MD:	C-130	
TMS:	N/A	
Noun:	Navigation Data Converter	
NSN:	6605-01-417-1491	
P/N:	3336249-19	
Forecasted Buy Price:	\$15,420.91	
Forecasted Repair Cost:	\$5,938.00	
AAC:	C	
Unserv. Assets Avail:	Yes	
QPA/APPL Rate:	2	100%

AMC/AMSC:	3	R
RMC/RMSC:	3	R
Material:	Not Available	
Dimensions:	UNIT LENGTH 7.830 INCHES NOMINAL UNIT WIDTH 5.110 INCHES NOMINAL UNIT HEIGHT 2.710 INCHES NOMINAL	
Drawings Releasable:	Yes	
Drawing #:	3336249	
Drawing Cage Code:	98897	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	8	
Next Higher Asmbly:	Not Available	

Out Year Requirements: BUY									
FY26:	7	FY27:	0	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Not Available	RDL:	Available
Tinker	8/7/2025	Robins	2025, 3/26/2026
Hill	-----	Virtual	-----

Comments

- **Deliverables:** Complete Technical Data Package, Prototype, 3D Modeling Data, Specification Control Drawing Testing and Evaluation
- **OTA Project:** Must be member of SOSSEC Consortium
- Interested vendors should submit a White Paper to 429SCMS.SASPO.Workflow@us.af.mil
- RSVP for Technical Discussion

Supplying Warfighter Dominance



Navigation Data Converter: Rev Eng – OTA

Robins AFB – 409th SCMS



Additional Comments

- The Government has a need to procure NSN 6605-01-417-1491 LG. The Government previously tried to award a 5-year procurement contract, but the company is unwilling to start producing these again due to parts obsolescence issues. These assets are currently being repaired, but if spares are not added to the supply chain, the supply will eventually run out as parts are condemned or deemed “uneconomical to repair”.

If you would like to participate in the Technical Discussion on:

Tuesday, April 28th, 2026, 10:00AM – 11:00AM CT

provide the following, NLT

Tuesday, April 14th, 2026

429SCMS.SASPO.Workflow@us.af.mil

-Company, -Address, -Name(s), -Email(s), -Phone,

-Your questions for Engineering, and

-Statement of Capabilities

Supplying Warfighter Dominance



Intraform Indicator: Rev Eng – OTA

Robins AFB – 409th SCMS



MD:	C-130
TMS:	N/A
Noun:	Intraform Indicator
NSN:	5841-01-394-8312
P/N:	8321-7000-2
Forecasted Buy Price:	\$24,925.48
Forecasted Repair Cost:	\$8,158.00
AAC:	C
Unserv. Assets Avail:	
QPA/APPL Rate:	1 30%

AMC/AMSC:	3	R
RMC/RMSC:	N/A	N/A
Material:	Not Available	
Dimensions:	Not Available	
Drawings Releasable:	No	
Drawing #:	Not Available	
Drawing Cage Code:	Not Available	
T.O. Releasable:	Yes	
T.O. #:	12P5-2APN169-54-1	
Budget Code:	8	
Next Higher Asmbly:	AN/APN-169C(V)	

Out Year Requirements: BUY									
FY26:	18	FY27:	0	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Not Available	RDL:	Not Available
Tinker	8/8/2024	Robins	2024, 3/26/2026
Hill	-----	Virtual	-----

Comments

- **Deliverables:** Complete Technical Data Package, Prototype, 3D Modeling Data, Specification Control Drawing Testing and Evaluation
- **OTA Project:** Must be member of SOSSEC Consortium
- Interested vendors should submit a White Paper to 429SCMS.SASPO.Workflow@us.af.mil
- RSVP for Technical Discussion

Supplying Warfighter Dominance



Intraform Indicator: Rev Eng – OTA Robins AFB – 409th SCMS



Additional Comments

- This item is currently Depot repaired, however, due to age of item DLA is unable to procure subcomponent PN 1835-0021 since 2022. Reduced inventory requires procurement of additional assets to improve readiness for major weapon system. Flight Command Indicator is required for aircraft mission capability when flying in formation.

If you would like to participate in the Technical Discussion on:

Tuesday, April 28th, 2026, 10:00AM – 11:00AM CT

provide the following, NLT

Tuesday, April 14th, 2026

429SCMS.SASPO.Workflow@us.af.mil

-Company, -Address, -Name(s), -Email(s), -Phone,

-Your questions for Engineering, and

-Statement of Capabilities

Supplying Warfighter Dominance



Multi Type II Indicator: Rev Eng – OTA

Robins AFB – 409th SCMS



MD:	C-130		
TMS:	N/A		
Noun:	Multi Type II Indicator		
NSN:	6620-01-619-7737		
P/N:	201219500		
Forecasted Buy Price:	\$8,150.63		
Forecasted Repair Cost:	N/A		
AAC:	D		
Unserv. Assets Avail:	No		
QPA/APPL Rate:	8	10%	

AMC/AMSC:	2	G
RMC/RMSC:	N/A	N/A
Material:	Not Available	
Dimensions:	Not Available	
Drawings Releasable:	Yes	
Drawing #:	20129500	
Drawing Cage Code:	98752	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	8	
Next Higher Asmbly:	Not Available	

Out Year Requirements: BUY									
FY26:	114	FY27:	28	FY28:	29	FY29:	30	FY30:	29

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Available	RDL:	Not Available
Tinker	8/7/2025	Robins	2025, 3/26/2025
Hill	-----	Virtual	-----

Comments

- **Deliverables:** Complete Technical Data Package, Prototype, 3D Modeling Data, Specification Control Drawing Testing and Evaluation
- **OTA Project:** Must be member of SOSSEC Consortium
- Interested vendors should submit a White Paper to 429SCMS.SASPO.Workflow@us.af.mil
- RSVP for Technical Discussion

Supplying Warfighter Dominance



Multi Type II Indicator: Rev Eng – OTA Robins AFB – 409th SCMS



Additional Comments

- The Government has a need to procure NSN 6620-01-619-7737LG. This is an ERRC N item and cannot be repaired. Current procurement contract is expired. NSN has multiple obsolescence parts and needs to be refreshed with a new Technical Data Package (TDP). We currently have an engineering project approved and pending funding to produce new TDP. We have backorders we cannot fill and need assets in order to support the warfighter.

If you would like to participate in the Technical Discussion on:

Tuesday, April 28th, 2026, 10:00AM – 11:00AM CT

provide the following, NLT

Tuesday, April 14th, 2026

429SCMS.SASPO.Workflow@us.af.mil

-Company, -Address, -Name(s), -Email(s), -Phone,

-Your questions for Engineering, and

-Statement of Capabilities

Supplying Warfighter Dominance



Pilot Warning: Rev Eng – OTA

Robins AFB – 409th SCMS



MD:	N/A		
TMS:	N/A		
Noun:	Pilot Warning		
NSN:	6340-01-394-9780		
P/N:	2500-005		
Forecasted Buy Price:	\$9,542.27		
Forecasted Repair Cost:	\$2,885.74		
AAC:	C		
Unserv. Assets Avail:	Yes		
QPA/APPL Rate:	1		13%

AMC/AMSC:	3	H
RMC/RMSC:	1	R
Material:	Not Available	
Dimensions:	Not Available	
Drawings Releasable:	No	
Drawing #:	Not Available	
Drawing Cage Code:	Not Available	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	8	
Next Higher Asmbly:	Not Available	

Out Year Requirements: BUY									
FY26:	14	FY27:	0	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Not Available	RDL:	Not Available
Tinker	8/7/2025	Robins	2025, 3/26/2026
Hill	-----	Virtual	-----

Comments

- **Deliverables:** Complete Technical Data Package, Prototype, 3D Modeling Data, Specification Control Drawing Testing and Evaluation
- **OTA Project:** Must be member of SOSSEC Consortium
- Interested vendors should submit a White Paper to 429SCMS.SASPO.Workflow@us.af.mil
- RSVP for Technical Discussion

Supplying Warfighter Dominance



Pilot Warning: Rev Eng – OTA Robins AFB – 409th SCMS



Additional Comments

- This item is currently on a 5-year repair contract although OEM no longer has production files or tooling to manufacture asset. Reduced inventory requires procurement of additional assets to improve readiness for major weapon system. This item is a complete electrical warning unit specifically designed to provide an aural message/warning through pilot's earphones and/or visual message on pilot's heads-up visor display or a control panel indicating an unsafe aircraft attitude, such as altitude, fire, canopy, pressurization, engine and/or rotor rpms, etc. Item does not provide facilities for bells, buzzers, horns, sirens and/or lights. Excludes alarm set, personnel hazard.

If you would like to participate in the Technical Discussion on:

Tuesday, April 28th, 2026, 10:00AM – 11:00AM CT

provide the following, NLT

Tuesday, April 14th, 2026

429SCMS.SASPO.Workflow@us.af.mil

-Company, -Address, -Name(s), -Email(s), -Phone,

-Your questions for Engineering, and

-Statement of Capabilities

Supplying Warfighter Dominance



Power Switching Unit: Rev Eng – OTA

Robins AFB – 409th SCMS



MD:	C-130	
TMS:	N/A	
Noun:	Power Switching Unit	
NSN:	6110-01-432-0353	
P/N:	CSV4160-4	
Forecasted Buy Price:	\$74,379.25	
Forecasted Repair Cost:	\$3,316.00	
AAC:	C	
Unserv. Assets Avail:	Yes	
QPA/APPL Rate:	2	30%

AMC/AMSC:	3	B
RMC/RMSC:	1	R
Material:	Not Available	
Dimensions:	OVERALL DEPTH 13.420 INCHES NOMINAL OVERALL HEIGHT 6.480 INCHES NOMINAL OVERALL WIDTH 11.280 INCHES NOMINAL	
Drawings Releasable:	Yes	
Drawing #:	697873	
Drawing Cage Code:	07639	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	8	
Next Higher Asmbly:	Not Available	

Out Year Requirements: BUY									
FY26:	19	FY27:	1	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Not Available	RDL:	Available
Tinker	2024, 8/7/2025	Robins	2024, 2025, 3/26/2026
Hill	-----	Virtual	-----

Comments

- **Deliverables:** Complete Technical Data Package, Prototype, 3D Modeling Data, Specification Control Drawing Testing and Evaluation
- **OTA Project:** Must be member of SOSSEC Consortium
- Interested vendors should submit a White Paper to 429SCMS.SASPO.Workflow@us.af.mil
- RSVP for Technical Discussion

Supplying Warfighter Dominance



Power Switching Unit: Rev Eng – OTA

Robins AFB – 409th SCMS



Additional Comments

- The Government has a need to procure NSN 6110-01-432-0353 LG. The Government previously tried to award a 3-year procurement contract, but the company is unwilling to start producing these again due to parts obsolescence issues. These assets are currently being repaired, but if spares are not added to the supply chain, the supply will eventually run out as parts are condemned or deemed “uneconomical to repair”.

If you would like to participate in the Technical Discussion on:

Tuesday, April 28th, 2026, 10:00AM – 11:00AM CT

provide the following, NLT

Tuesday, April 14th, 2026

429SCMS.SASPO.Workflow@us.af.mil

-Company, -Address, -Name(s), -Email(s), -Phone,

-Your questions for Engineering, and

-Statement of Capabilities

Supplying Warfighter Dominance



Pressure Indicator: Rev Eng – OTA

Robins AFB – 409th SCMS



MD:	C-130	
TMS:	N/A	
Noun:	Pressure Indicator	
NSN:	6220-01-394-4019	
P/N:	10401N01P00	
Forecasted Buy Price:	\$1,122.28	
Forecasted Repair Cost:	N/A	
AAC:	C	
Unserv. Assets Avail:	Yes	
QPA/APPL Rate:	2	44%

AMC/AMSC:	3	R
RMC/RMSC:	N/A	N/A
Material:	Not Available	
Dimensions:	Not Available	
Drawings Releasable:	No	
Drawing #:	Not Available	
Drawing Cage Code:	Not Available	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	8	
Next Higher Asmbly:	Not Available	

Out Year Requirements: BUY									
FY26:	20	FY27:	2	FY28:	3	FY29:	3	FY30:	3

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Not Available	RDL:	Not Available
Tinker	8/8/2024	Robins	2024, 3/26/2026
Hill	-----	Virtual	-----

Comments

- **Deliverables:** Complete Technical Data Package, Prototype, 3D Modeling Data, Specification Control Drawing Testing and Evaluation
- **OTA Project:** Must be member of SOSSEC Consortium
- Interested vendors should submit a White Paper to 429SCMS.SASPO.Workflow@us.af.mil
- RSVP for Technical Discussion

Supplying Warfighter Dominance



Pressure Indicator: Rev Eng – OTA Robins AFB – 409th SCMS



Additional Comments

- The Government has a need to procure NSN 6620-01-394-4019 LG. This is an ERRC N item, so repairs cannot be performed. The Government previously attempted to award a 5-year procurement contract for this part, but the company is unwilling to start producing these again.
- Without a viable manufacturing source to induct new spares into the supply system, inventory levels will inevitably be depleted as existing components are condemned. This will result in a critical supply shortage and impact system readiness

If you would like to participate in the Technical Discussion on:

Tuesday, April 28th, 2026

provide the following, NLT

Tuesday, April 14th, 2026

429SCMS.SASPO.Workflow@us.af.mil

-Company, -Address, -Name(s), -Email(s), -Phone,

-Your questions for Engineering, and

-Statement of Capabilities

Supplying Warfighter Dominance



C-5 Galaxy



Supplying Warfighter Dominance



NLG Outer Cylinder: AS – Repair

Hill AFB – 417th SCMS



MD:	C-5	
TMS:	N/A	
Noun:	NLG Outer Cylinder	
NSN:	1620-00-403-5249	
P/N:	4G51436-107B	
Forecasted Buy Price:	\$105,166.05	
Forecasted Repair Cost:	\$34,407.41	
AAC:	M	
Unserv. Assets Avail:	N/A	
QPA/APPL Rate:	1	100%

AMC/AMSC:	1	C
RMC/RMSC:	N/A	N/A
Material:	300M steel	
Dimensions:	60" X 60" X 14"	
Drawings Releasable:	Yes	
Drawing #:	4G51436	
Drawing Cage Code:	98897	
T.O. Releasable:	Yes	
T.O. #:	4S2-67-3, 4S2-67-4, 4S-1-182	
Budget Code:	8	
Next Higher Asmbly:	4G51403-103G	

Out Year Requirements: BUY									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	4	FY27:	4	FY28:	4	FY29:	4	FY30:	4

EDL:	Available	RDL:	Not Available
Tinker	-----	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Source Approval Request (SAR) Package
- Interested vendors should submit a Source Approval Request (SAR) to AFSC.OL.SB@us.af.mil and include your email address and "request a drop off". A request for drop off will be returned, use this to submit your SAR package.

Supplying Warfighter Dominance



NLG Outer Cylinder: AS – Repair Hill AFB – 417th SCMS



Additional Comments

- C-5 Nose Landing Gear (1620004325651) is repaired at HAFB, Utah. Currently the organic shop struggles to meet the MPS plan and is currently scheduled to only meet 50% of the FY25 MPS. This is due in part to the extensive shop flow days of 510.63 through the repair shop to repair the wear surfaces of sub-component Outer Cylinder (1620004035249). Combined with a 38.5% condemn rate for the -5249 the shop cannot produce enough Outer Cylinders annually to support the MPS (10 per year), of the Next Higher Assembly (NHA).



NLG Piston Axle: AS – Repair

Hill AFB – 417th SCMS



MD:	C-5	
TMS:	N/A	
Noun:	NLG Piston Axle	
NSN:	1620-00-409-4739	
P/N:	4G51427-101A	
Forecasted Buy Price:	\$348,625.80	
Forecasted Repair Cost:	\$72,076.00	
AAC:	M	
Unserv. Assets Avail:	N/A	
QPA/APPL Rate:	1	100%

AMC/AMSC:	1	C
RMC/RMSC:	N/A	N/A
Material:	300M Steel	
Dimensions:	102" X 61" X 20"	
Drawings Releasable:	Yes	
Drawing #:	4G51427	
Drawing Cage Code:	98897	
T.O. Releasable:	Yes	
T.O. #:	4S2-67-3, 4S2-67-4, 4S-1-182	
Budget Code:	8	
Next Higher Asmbly:	4G51403-103G	

Out Year Requirements: BUY									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	4	FY27:	4	FY28:	4	FY29:	4	FY30:	4

EDL:	Available	RDL:	Not Available
Tinker	-----	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Source Approval Request (SAR) Package
- Interested vendors should submit a Source Approval Request (SAR) to AFSC.OL.SB@us.af.mil and include your email address and "request a drop off". A request for drop off will be returned, use this to submit your SAR package.

Supplying Warfighter Dominance



NLG Piston Axle: AS – Repair Hill AFB – 417th SCMS



Additional Comments

- As of September 15th, 2025, the C-5 Nose Landing Gear (1620004325651) is repaired at HAFB, Utah. Currently the organic shop struggles to meet the MPS plan and is currently scheduled to only meet 50% of the FY25 MPS. This is due to the extensive lead time of 649 days through the repair shop to repair the wear surfaces of sub-component Piston Axle (1620004094739). Combined with a 33% condemn rate for the -4739 the shop cannot produce enough piston axles annually to support the MPS (10 per year), of the Next Higher Assembly (NHA).



MLG Strut Piston: AS – Repair

Hill AFB – 417th SCMS



MD:	C-5	
TMS:	N/A	
Noun:	MLG Strut Piston	
NSN:	1620-00-417-6249	
P/N:	4G11414-107A	
Forecasted Buy Price:	\$270,484.82	
Forecasted Repair Cost:	\$190,187.61	
AAC:	M	
Unserv. Assets Avail:	N/A	
QPA/APPL Rate:	1	100%

AMC/AMSC:	1	C
RMC/RMSC:	N/A	N/A
Material:	Chrome/HVOF Plated 300M (Tricent)	
Dimensions:	71" Length x 11" OD	
Drawings Releasable:	Yes	
Drawing #:	4G51436	
Drawing Cage Code:	98897	
T.O. Releasable:	Yes	
T.O. #:	4S1-93-3	
Budget Code:	8	
Next Higher Asmbly:		

Out Year Requirements: BUY									
FY26:	0	FY27:	26	FY28:	49	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	16	FY27:	16	FY28:	16	FY29:	16	FY30:	16

EDL:	Available	RDL:	Not Available
Tinker	-----	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Source Approval Request (SAR) Package
- Interested vendors should submit a Source Approval Request (SAR) to AFSC.OL.SB@us.af.mil and include your email address and "request a drop off". A request for drop off will be returned, use this to submit your SAR package.

Supplying Warfighter Dominance



MLG Strut Piston: AS – Repair ***Hill AFB – 417th SCMS***



Additional Comments

- C-5 Main Landing Gear (LH/RH Aft. Struts 1620012046224 & 1620012050901 & LH/RH Fwd. Struts 1620012056281 & 1620012056282) are repaired at HAFB, Utah. Currently the organic shop struggles to meet the MPS plan and is currently scheduled to only meet 50% of the FY25 MPS. This is due in part to the extensive shop flow days of 594.74 through the repair shop to repair the wear surfaces of sub-component Piston (1620004176249). Combined with a 13% condemn rate for the -6249 the shop cannot produce enough Pistons annually to support the MPS (9 ship sets per year (36 ea. pistons)), of the Next Higher Assembly (NHA).



MLG Strut Outer Cylinder: AS – Repair

Hill AFB – 417th SCMS



MD:	C-5	
TMS:	N/A	
Noun:	MLG Outer Cylinder	
NSN:	1620-00-446-3776	
P/N:	4G11415-107A	
Forecasted Buy Price:	\$216,798.75	
Forecasted Repair Cost:	\$59,056.23	
AAC:	C	
Unserv. Assets Avail:	N/A	
QPA/APPL Rate:	1	100%

AMC/AMSC:	1	C
RMC/RMSC:	N/A	N/A
Material:	Chrome/HVOF Plated 300M (Tricent)	
Dimensions:	T-Shaped – 60” Across x 62” Tall, 12.5” OD Cylinder	
Drawings Releasable:	Yes	
Drawing #:	4G11415	
Drawing Cage Code:	98897	
T.O. Releasable:	Yes	
T.O. #:	4S1-93-3	
Budget Code:	8	
Next Higher Asmbly:		

Out Year Requirements: BUY									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	16	FY27:	16	FY28:	16	FY29:	16	FY30:	16

EDL:	Available	RDL:	Not Available
Tinker	-----	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Source Approval Request (SAR) Package
- Interested vendors should submit a Source Approval Request (SAR) to AFSC.OL.SB@us.af.mil and include your email address and “request a drop off”. A request for drop off will be returned, use this to submit your SAR package.

Supplying Warfighter Dominance



MLG Strut Outer Cylinder: AS – Repair Hill AFB – 417th SCMS



Additional Comments

- C-5 Main Landing Gear (LH/RH Aft. Struts 1620012046224 & 1620012050901 & LH/RH Fwd. Struts 1620012056281 & 1620012056282) are repaired at HAFB, Utah. Currently the organic shop struggles to meet the MPS plan and is currently scheduled to only meet 50% of the FY25 MPS. This is due in part to the extensive shop flow days of 634.48 through the repair shop to repair the wear surfaces of sub-component Outer Cylinder (1620004463776). Combined with a 38% condemn rate for the -3776 the shop cannot produce enough Outer Cylinders annually to support the MPS (9 ship sets per year (36 ea. outers), of the Next Higher Assembly (NHA).



Remote Control Unit: Market Research

JBSA Lackland AFB – AFLCMC

MD:	C-130
TMS:	N/A
Noun:	Remote Control Unit
NSN:	5810-01-463-2312
P/N:	0N460510-510
Forecasted Buy Price:	\$837.00
Forecasted Repair Cost:	N/A
AAC:	V
Unserv. Assets Avail:	N/A
QPA/APPL Rate:	1 100%

AMC/AMSC:	N/A	N/A
RMC/RMSC:	N/A	N/A
Material:	N/A	
Dimensions:	N/A	
Drawings Releasable:	N/A	
Drawing #:	N/A	
Drawing Cage Code:	N/A	
T.O. Releasable:	N/A	
T.O. #:	N/A	
Budget Code:	K	
Next Higher Asmbly:	N/A	

Out Year Requirements: BUY									
FY26:	23	FY27:	23	FY28:	23	FY29:	23	FY30:	23

Out Year Requirements: REPAIR									
FY26:	1	FY27:	12	FY28:	20	FY29:	8	FY30:	0

EDL:	Not Available	RDL:	Not Available
Tinker	-----	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- Market research for a potential procurement source and/or finding a manufacturer to produce the remote control unit.
- If interested, please submit capabilities statement to our workflow at 429SCMS.SASPO.Workflow@us.af.mil

Supplying Warfighter Dominance



Light Source Control: Market Research

JBSA Lackland AFB – AFLCMC



MD:	C-130
TMS:	N/A
Noun:	Control, Light Source
NSN:	6110-01-465-6522
P/N:	0N460520-510
Forecasted Buy Price:	\$1,067.54
Forecasted Repair Cost:	N/A
AAC:	V
Unserv. Assets Avail:	N/A
QPA/APPL Rate:	%

AMC/AMSC:	N/A	N/A
RMC/RMSC:	N/A	N/A
Material:	N/A	
Dimensions:	N/A	
Drawings Releasable:	N/A	
Drawing #:	N/A	
Drawing Cage Code:	N/A	
T.O. Releasable:	N/A	
T.O. #:	N/A	
Budget Code:	K	
Next Higher Asmbly:	N/A	

Out Year Requirements: BUY									
FY26:	17	FY27:	17	FY28:	17	FY29:	17	FY30:	17

Out Year Requirements: REPAIR									
FY26:	4	FY27:	4	FY28:	4	FY29:	4	FY30:	0

EDL:	Not Available	RDL:	Not Available
Tinker	-----	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- Market research for a potential procurement source and/or finding a manufacturer to produce the Light Source Control unit.
- If interested, please submit capabilities statement to our workflow at 429SCMS.SASPO.Workflow@us.af.mil

Supplying Warfighter Dominance



Support Structural : Market Research

Robins AFB – 409th SCMS



MD:	C-5	
TMS:	N/A	
Noun:	Support, Structural Component, (Drag Strut)	
NSN:	1500-01-288-2240	
P/N:	4F23218-105A	
Forecasted Buy Price:	\$150K	
Forecasted Repair Cost:	\$7,135.00	
AAC:	C	
Unserv. Assets Avail:	14	
QPA/APPL Rate:	4	100%

AMC/AMSC:	1	G
RMC/RMSC:	2	G
Material:	4340 Steel Forgings Machined and Welded	
Dimensions:	L-58.5 IN, W-5 IN, D-5 IN; WT LBS-45	
Drawings Releasable:	N/A	
Drawing #:	N/A	
Drawing Cage Code:	N/A	
T.O. Releasable:	N/A	
T.O. #:	N/A	
Budget Code:	8	
Next Higher Asmbly:		

Out Year Requirements: BUY									
FY26:	3	FY27:	2	FY28:	3	FY29:	2	FY30:	2

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Available	RDL:	Available
Tinker	8/7/2025	Robins	2025, 3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- Interested vendors should submit a Capabilities Statement to 429SCMS.SASPO.Workflow@us.af.mil
- No Source Approval Request (SAR) Package required
- Single Production run to clear backlog may be considered



Aircraft Door: Market Research

Robins AFB – 409th SCMS



MD:	C-5		
TMS:	N/A		
Noun:	Main Landing Gear Door, Outboard, RH FWD		
NSN:	1560-01-093-9089		
P/N:	4F72100-110A		
Forecasted Buy Price:	\$950K		
Forecasted Repair Cost:	\$650K		
AAC:	C		
Unserv. Assets Avail:	6		
QPA/APPL Rate:	1		100%

AMC/AMSC:	1	C
RMC/RMSC:	1	G
Material:	Non-metallic core aluminum skin panel bonded to aluminum frame, forged steel fittings	
Dimensions:	L-169, W-79, D-80 ½ ; WT LBS-450	
Drawings Releasable:	N/A	
Drawing #:	N/A	
Drawing Cage Code:	N/A	
T.O. Releasable:	N/A	
T.O. #:	N/A	
Budget Code:	8	
Next Higher Asmbly:		

Out Year Requirements: BUY									
FY26:	3	FY27:	0	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Available	RDL:	Available
Tinker	8/7/2025	Robins	2025, 3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- Interested vendors should submit a Capabilities Statement to 429SCMS.SASPO.Workflow@us.af.mil
- No Source Approval Request (SAR) Package required
- Single Production run to clear backlog may be considered



Aircraft Door: Market Research

Robins AFB – 409th SCMS



MD:	C-5	
TMS:	N/A	
Noun:	Main Landing Gear Door, Outboard, LH FWD	
NSN:	1560-01-202-3261	
P/N:	4F72100-109A	
Forecasted Buy Price:	\$950K	
Forecasted Repair Cost:	\$650K	
AAC:	C	
Unserv. Assets Avail:	6	
QPA/APPL Rate:	1	100%

AMC/AMSC:	1	C
RMC/RMSC:	1	G
Material:	Non-metallic core aluminum skin panel bonded to aluminum frame, forged steel fittings	
Dimensions:	L-169, W-79, D-80 ½ ; WT LBS-450	
Drawings Releasable:	N/A	
Drawing #:	N/A	
Drawing Cage Code:	N/A	
T.O. Releasable:	N/A	
T.O. #:	N/A	
Budget Code:	8	
Next Higher Asmbly:		

Out Year Requirements: BUY									
FY26:	3	FY27:	0	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Available	RDL:	Available
Tinker	8/7/2025	Robins	2025, 3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- Interested vendors should submit a Capabilities Statement to 429SCMS.SASPO.Workflow@us.af.mil
- No Source Approval Request (SAR) Package required
- Single Production run to clear backlog may be considered



Aircraft Door: Market Research

Robins AFB – 409th SCMS



MD:	C-5	
TMS:	N/A	
Noun:	Main Landing Gear Door, Outboard, RH Aft	
NSN:	1560-01-113-9489	
P/N:	4F72100-111A	
Forecasted Buy Price:	\$950K	
Forecasted Repair Cost:	\$650K	
AAC:	C	
Unserv. Assets Avail:	10	
QPA/APPL Rate:	1	100%

AMC/AMSC:	1	C
RMC/RMSC:	1	G
Material:	Non-metallic core aluminum skin panel bonded to aluminum frame, forged steel fittings	
Dimensions:	L-169IN, W-79IN, D-80 ½IN ; WT LBS-450	
Drawings Releasable:	N/A	
Drawing #:	N/A	
Drawing Cage Code:	N/A	
T.O. Releasable:	N/A	
T.O. #:	N/A	
Budget Code:	8	
Next Higher Asmbly:		

Out Year Requirements: BUY							
FY26:	3	FY27:	0	FY28:	0	FY29:	0
FY30:	0						

Out Year Requirements: REPAIR							
FY26:	0	FY27:	0	FY28:	0	FY29:	0
FY30:	0						

EDL:	Available	RDL:	Available
Tinker	8/7/2025	Robins	2025, 3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- Interested vendors should submit a Capabilities Statement to 429SCMS.SASPO.Workflow@us.af.mil
- No Source Approval Request (SAR) Package required
- Single Production run to clear backlog may be considered



Aircraft Door: Market Research

Robins AFB – 409th SCMS



MD:	C-5	
TMS:	N/A	
Noun:	Main Landing Gear Door, Outboard, LH Aft	
NSN:	1560-01-093-9090	
P/N:	4F72100-112A	
Forecasted Buy Price:	\$950K	
Forecasted Repair Cost:	\$650K	
AAC:	C	
Unserv. Assets Avail:	9	
QPA/APPL Rate:	1	100%

AMC/AMSC:	1	C
RMC/RMSC:	1	G
Material:	Non-metallic core aluminum skin panel bonded to aluminum frame, forged steel fittings	
Dimensions:	L-169, W-79, D-80 ½ ; WT LBS-450	
Drawings Releasable:	N/A	
Drawing #:	N/A	
Drawing Cage Code:	N/A	
T.O. Releasable:	N/A	
T.O. #:	N/A	
Budget Code:	8	
Next Higher Asmbly:		

Out Year Requirements: BUY									
FY26:	3	FY27:	0	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Available	RDL:	Available
Tinker	8/7/2025	Robins	2025, 3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- Interested vendors should submit a Capabilities Statement to 429SCMS.SASPO.Workflow@us.af.mil
- No Source Approval Request (SAR) Package required
- Single Production run to clear backlog may be considered



Aircraft Floor: AS – New Buy

Robins AFB – 409th SCMS



MD:	C-5	
TMS:	N/A	
Noun:	Aircraft Floor	
NSN:	1560-00-008-9491	
P/N:	4F50202-131A	
Forecasted Buy Price:	\$3,199.59	
Forecasted Repair Cost:	\$3,508.17	
AAC:	Z	
Unserv. Assets Avail:	N/A	
QPA/APPL Rate:	1	100%

AMC/AMSC:	2	G
RMC/RMSC:	2	G
Material:	Aluminum Alloy	
Dimensions:	Not Available	
Drawings Releasable:	Yes	
Drawing #:	4F50202	
Drawing Cage Code:	98897	
T.O. Releasable:	Yes	
T.O. #:	1C-5M-4-1	
Budget Code:	8	
Next Higher Asmbly:		

Out Year Requirements: BUY									
FY26:	0	FY27:	1	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Available	RDL:	Not Available
Tinker	8/7/2025	Robins	2025, 3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- Interested vendors should submit a Capabilities Statement to 429SCMS.SASPO.Workflow@us.af.mil
- No Source Approval Request (SAR) Package required due to AMSC code of G (full and open competition)
- Visit dibbs.bsm.dla.mil for solicitation



Aircraft Floor: AS – New Buy

Robins AFB – 409th SCMS



MD:	C-5	
TMS:	N/A	
Noun:	Aircraft Floor	
NSN:	1560-00-009-0798	
P/N:	4F50303-138A	
Forecasted Buy Price:	\$1661,440.87	
Forecasted Repair Cost:	N/A	
AAC:	C	
Unserv. Assets Avail:	No	
QPA/APPL Rate:	1	100%

AMC/AMSC:	2	G
RMC/RMSC:	2	G
Material:	Aluminum Alloy	
Dimensions:	Not Available	
Drawings Releasable:	Yes	
Drawing #:	4F50303	
Drawing Cage Code:	98897	
T.O. Releasable:	Yes	
T.O. #:	1C-5M-4-1	
Budget Code:	8	
Next Higher Asmbly:		

Out Year Requirements: BUY							
FY26:	0	FY27:	1	FY28:	0	FY29:	0
FY30:	0						

Out Year Requirements: REPAIR							
FY26:	0	FY27:	0	FY28:	0	FY29:	0
FY30:	0						

EDL:	Available	RDL:	Not Available
Tinker	8/7/2025	Robins	2025, 3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- Interested vendors should submit a Capabilities Statement to 429SCMS.SASPO.Workflow@us.af.mil
- No Source Approval Request (SAR) Package required due to AMSC code of G (full and open competition)
- Visit dibbs.bsm.dla.mil for solicitation



Aircraft Floor: AS – New Buy

Robins AFB – 409th SCMS



MD:	C-5	
TMS:	N/A	
Noun:	Aircraft Floor	
NSN:	1560-00-463-1235	
P/N:	4F52014-123A	
Forecasted Buy Price:	\$30,096.73	
Forecasted Repair Cost:	\$11,181.81	
AAC:	C	
Unserv. Assets Avail:	N/A	
QPA/APPL Rate:	1	100%

AMC/AMSC:	1	G
RMC/RMSC:	2	G
Material:	Aluminum	
Dimensions:	101.7500" L X 25.6500" W X 2.0000" H, 54 LBS	
Drawings Releasable:	Yes	
Drawing #:	4F52014	
Drawing Cage Code:	98897	
T.O. Releasable:	Yes	
T.O. #:	1C-5M-4-1	
Budget Code:	8	
Next Higher Asmbly:		

Out Year Requirements: BUY									
FY26:	0	FY27:	1	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Available	RDL:	Not Available
Tinker	8/7/2025	Robins	2025, 3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- Interested vendors should submit a Capabilities Statement to 429SCMS.SASPO.Workflow@us.af.mil
- No Source Approval Request (SAR) Package required due to AMSC code of G (full and open competition)
- Visit dibbs.bsm.dla.mil for solicitation



Aircraft Floor: AS – New Buy

Robins AFB – 409th SCMS



MD:	C-5	
TMS:	N/A	
Noun:	Aircraft Floor	
NSN:	1560-00-494-7728	
P/N:	4F53451-119B	
Forecasted Buy Price:	\$13,177.13	
Forecasted Repair Cost:	N/A	
AAC:	C	
Unserv. Assets Avail:	Not Available	
QPA/APPL Rate:	1	100%

AMC/AMSC:	2	G
RMC/RMSC:	2	G
Material:	Aluminum Alloy	
Dimensions:	Not Available	
Drawings Releasable:	Yes	
Drawing #:	4F53451	
Drawing Cage Code:	98897	
T.O. Releasable:	Yes	
T.O. #:	1C-5M-4-1	
Budget Code:	8	
Next Higher Asmbly:		

Out Year Requirements: BUY							
FY26:	0	FY27:	1	FY28:	0	FY29:	0
FY30:	0						

Out Year Requirements: REPAIR							
FY26:	0	FY27:	0	FY28:	0	FY29:	0
FY30:	0						

EDL:	Available	RDL:	Not Available
Tinker	8/7/2025	Robins	2025, 3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- Interested vendors should submit a Capabilities Statement to 429SCMS.SASPO.Workflow@us.af.mil
- No Source Approval Request (SAR) Package required due to AMSC code of G (full and open competition)
- Visit dibbs.bsm.dla.mil for solicitation



Aircraft Floor: AS – New Buy

Robins AFB – 409th SCMS



MD:	C-5	
TMS:	N/A	
Noun:	Aircraft Floor	
NSN:	1560-01-188-8705	
P/N:	4F50158-126A	
Forecasted Buy Price:	\$250,051.71	
Forecasted Repair Cost:	\$73,225.52	
AAC:	C	
Unserv. Assets Avail:	N/A	
QPA/APPL Rate:	1	100%

AMC/AMSC:	2	G
RMC/RMSC:	2	G
Material:	Aluminum	
Dimensions:	37.000"L X 24.0000"W X 2.5000"H, 23 LBS	
Drawings Releasable:	Yes	
Drawing #:	4F50158	
Drawing Cage Code:	98897	
T.O. Releasable:	Yes	
T.O. #:	1C-5M-4-1	
Budget Code:	8	
Next Higher Asmbly:		

Out Year Requirements: BUY									
FY26:	0	FY27:	1	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Available	RDL:	Not Available
Tinker	8/7/2025	Robins	2025, 3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- Interested vendors should submit a Capabilities Statement to 429SCMS.SASPO.Workflow@us.af.mil
- No Source Approval Request (SAR) Package required due to AMSC code of G (full and open competition)
- Visit dibbs.bsm.dla.mil for solicitation



Aircraft Floor: AS – New Buy

Robins AFB – 409th SCMS



MD:	C-5	
TMS:	N/A	
Noun:	Aircraft Floor	
NSN:	1560-01-189-1503	
P/N:	4F50158-125A	
Forecasted Buy Price:	\$524,874.08	
Forecasted Repair Cost:	\$213,273.82	
AAC:	Z	
Unserv. Assets Avail:	N/A	
QPA/APPL Rate:	1	100%

AMC/AMSC:	2	G
RMC/RMSC:	2	G
Material:	Aluminum	
Dimensions:	37.0000"L X 24.0000"W X 2.5000"H, 23 LBS	
Drawings Releasable:	Yes	
Drawing #:	4F50158	
Drawing Cage Code:	98897	
T.O. Releasable:	Yes	
T.O. #:	1C-5M-4-1	
Budget Code:	8	
Next Higher Asmbly:		

Out Year Requirements: BUY									
FY26:	0	FY27:	1	FY28:	0`	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Available	RDL:	Not Available
Tinker	8/7/2025	Robins	2025, 3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- Interested vendors should submit a Capabilities Statement to 429SCMS.SASPO.Workflow@us.af.mil
- No Source Approval Request (SAR) Package required due to AMSC code of G (full and open competition)
- Visit dibbs.bsm.dla.mil for solicitation



Aircraft Floor: AS – New Buy

Robins AFB – 409th SCMS



MD:	C-5
TMS:	N/A
Noun:	Aircraft Floor
NSN:	1560-01-300-5471
P/N:	4F59251-119A
Forecasted Buy Price:	\$6,695.05
Forecasted Repair Cost:	N/A
AAC:	C
Unserv. Assets Avail:	N/A
QPA/APPL Rate:	1 100%

AMC/AMSC:	2	G
RMC/RMSC:	2	G
Material:	Aluminum Alloy	
Dimensions:	34"L X 10"W X 0.0820"Thickness	
Drawings Releasable:	Yes	
Drawing #:	4F59251	
Drawing Cage Code:	98897	
T.O. Releasable:	Yes	
T.O. #:	1C-5M-4-1	
Budget Code:	8	
Next Higher Asmbly:		

Out Year Requirements: BUY							
FY26:	0	FY27:	1	FY28:	0	FY29:	0
FY30:	0						

Out Year Requirements: REPAIR							
FY26:	0	FY27:	0	FY28:	0	FY29:	0
FY30:	0						

EDL:	Available	RDL:	Not Available
Tinker	8/7/2025	Robins	2025, 3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- Interested vendors should submit a Capabilities Statement to 429SCMS.SASPO.Workflow@us.af.mil
- No Source Approval Request (SAR) Package required due to AMSC code of G (full and open competition)
- Visit dibbs.bsm.dla.mil for solicitation



F-16 Fighting Falcon



Supplying Warfighter Dominance



Phase Shifter Driver (PSDU): AS – Repair

Hill AFB – 416th SCMS



MD:	F-16	
TMS:	N/A	
Noun:	Phase Shifter Driver (PSDU)	
NSN:	1270-01-561-6088	
P/N:	562R218H01	
Forecasted Buy Price:	\$88,326.73	
Forecasted Repair Cost:	\$28,529.29	
AAC:	C	
Unserv. Assets Avail:	N/A	
QPA/APPL Rate:	1	100%

AMC/AMSC:	2	B
RMC/RMSC:	1	C
Material:	(Please fill in if available)	
Dimensions:	8.5"L X 2.2"W X 4.785"H, 2LBS	
Drawings Releasable:	Yes	
Drawing #:	562R218	
Drawing Cage Code:	97942	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	8	
Next Higher Asmbly:	1270-01-561-6089WF	

Out Year Requirements: BUY									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	17	FY27:	6	FY28:	6	FY29:	6	FY30:	7

EDL:	Available	RDL:	Available
Tinker	-----	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Source Approval Request (SAR) Package
- Interested vendors should submit a Source Approval Request (SAR) to AFSC.OL.SB@us.af.mil and include your email address and “request a drop off”. A request for drop off will be returned, use this to submit your SAR package.

Supplying Warfighter Dominance



Phase Shifter Driver (PSDU): AS – Repair ***Hill AFB – 416th SCMS***



Additional Comments

- The phase shifter goes on F-16 C/D radar systems AN/APG-68. This is a new requirement. The phase shifters have never been repaired before by contractor or organic facilities. Northrop Grumman Systems Corporation (97942) is OEM for the radar, Herley Industries (32187) acquired by CAES Mission Systems LLC formerly Cobham Advanced Electronics Solution (32187) in 2023 and on Honeywell September 4, 2024, purchased CAES and became the OEM for the part. The Joint Certification Program shows CAES has Herley cage code (32187). The Joint Certification does not show Honeywell established Herley or CAES cage code (32187). These are the only known sources with specialized expertise, facilities, and equipment necessary to refurbish the phase shifters. Risk is medium Northrop Grumman and CAES may not bid when solicitation is posted because the quantities are low.



T-38 Talon



Supplying Warfighter Dominance



Cap Assembly: AS – New Buy

Hill AFB – 419th SCMS



MD:	T-38
TMS:	N/A
Noun:	Cap Assembly
NSN:	1560-00-613-5669
P/N:	14-51204-1
Forecasted Buy Price:	\$4,352.75
Forecasted Repair Cost:	N/A
AAC:	D
Unserv. Assets Avail:	N/A
QPA/APPL Rate:	

AMC/AMSC:	2	G
RMC/RMSC:	N/A	N/A
Material:	Magnesium	
Dimensions:	Not Available	
Drawings Releasable:	Yes	
Drawing #:	14-51204	
Drawing Cage Code:	76833	
T.O. Releasable:	Yes	
T.O. #:	16G1-102-4	
Budget Code:	9	
Next Higher Asmbly:		

Out Year Requirements: BUY									
FY26:	480	FY27:	480	FY28:	480	FY29:	480	FY30:	480

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Available	RDL:	Not Available
Tinker	-----	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- Interested vendors should submit a Capabilities Statement to 429SCMS.SASPO.Workflow@us.af.mil
- No Source Approval Request (SAR) Package required due to AMSC code of G (full and open competition)
- Visit dibbs.bsm.dla.mil for solicitation
- The Cap Assembly requires magnesium casting and machining

Supplying Warfighter Dominance



Gear Box: AS – New Buy

Hill AFB – 419th SCMS



MD:	T-38	
TMS:	N/A	
Noun:	Gear Box	
NSN:	1680-01-440-5106	
P/N:	14-51100-501 / -503	
Forecasted Buy Price:	\$137,795.29	
Forecasted Repair Cost:	\$49,614.89	
AAC:	C	
Unserv. Assets Avail:	N/A	
QPA/APPL Rate:	2	100%

AMC/AMSC:	3	R
RMC/RMSC:	1	C
Material:	Magnesium	
Dimensions:	Not Available	
Drawings Releasable:	Yes	
Drawing #:	14-51100	
Drawing Cage Code:	76823	
T.O. Releasable:	Yes	
T.O. #:	16G1-102-4	
Budget Code:	8	
Next Higher Asmbly:		

Out Year Requirements: BUY									
FY26:	40	FY27:	40	FY28:	40	FY29:	40	FY30:	40

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Available	RDL:	Available
Tinker	-----	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Source Approval Request (SAR) Package
- Interested vendors should submit a Source Approval Request (SAR) to AFSC.OL.SB@us.af.mil and include your email address and “request a drop off”. A request for drop off will be returned, use this to submit your SAR package.
- Licensing agreement may be required for data request

Supplying Warfighter Dominance



Idler Gear Spur: AS – New Buy

Hill AFB – 419th SCMS



MD:	T-38
TMS:	N/A
Noun:	Idler Gear Spur
NSN:	3020-00-495-4481
P/N:	14-51151-1
Forecasted Buy Price:	\$452.86
Forecasted Repair Cost:	N/A
AAC:	D
Unserv. Assets Avail:	N/A
QPA/APPL Rate:	

AMC/AMSC:	1	C
RMC/RMSC:	N/A	N/A
Material:	Bar Steel 4620	
Dimensions:	Length: 0.918 Diameter: 3.815 Width: 0.360	
Drawings Releasable:	Yes	
Drawing #:	14-51151	
Drawing Cage Code:	76823	
T.O. Releasable:	Yes	
T.O. #:	16G1-102-4	
Budget Code:	9	
Next Higher Asmbly:		

Out Year Requirements: BUY									
FY26:	480	FY27:	480	FY28:	480	FY29:	480	FY30:	480

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Available	RDL:	Not Available
Tinker	-----	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Source Approval Request (SAR) Package
- Interested vendors should submit a Source Approval Request (SAR) to dlaavnsmallbus@dla.mil

Supplying Warfighter Dominance



Gear Spur: AS – New Buy

Hill AFB – 419th SCMS



MD:	T-38
TMS:	N/A
Noun:	Gear Spur
NSN:	3020-00-763-3094
P/N:	14-51155-1
Forecasted Buy Price:	\$706.20
Forecasted Repair Cost:	N/A
AAC:	D
Unserv. Assets Avail:	N/A
QPA/APPL Rate:	

AMC/AMSC:	2	C
RMC/RMSC:	N/A	N/A
Material:	Steel Overall 4620	
Dimensions:	Length: 1.690 Diameter: 3.181 Width: 0.444	
Drawings Releasable:	Yes	
Drawing #:	14-51155	
Drawing Cage Code:	76823	
T.O. Releasable:	Yes	
T.O. #:	16G1-102-4	
Budget Code:	9	
Next Higher Asmbly:		

Out Year Requirements: BUY									
FY26:	480	FY27:	480	FY28:	480	FY29:	480	FY30:	480

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Available	RDL:	Not Available
Tinker	-----	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Source Approval Request (SAR) Package
- Interested vendors should submit a Source Approval Request (SAR) to dlaavnsmlbus@dla.mil

Supplying Warfighter Dominance



Gear Cluster: AS – New Buy

Hill AFB – 419th SCMS



MD:	T-38
TMS:	N/A
Noun:	Gear Cluster
NSN:	3020-00-887-3386
P/N:	3-51147-1
Forecasted Buy Price:	\$704.59
Forecasted Repair Cost:	N/A
AAC:	D
Unserv. Assets Avail:	N/A
QPA/APPL Rate:	

AMC/AMSC:	1	G
RMC/RMSC:	N/A	N/A
Material:	Steel Bar 4620	
Dimensions:	Length: 1.437	
Drawings Releasable:	Yes	
Drawing #:	3-51147	
Drawing Cage Code:	76823	
T.O. Releasable:	Yes	
T.O. #:	16G1-102-4	
Budget Code:	9	
Next Higher Asmbly:		

Out Year Requirements: BUY									
FY26:	480	FY27:	480	FY28:	480	FY29:	480	FY30:	480

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Available	RDL:	Not Available
Tinker	-----	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- Interested vendors should submit a Capabilities Statement to 429SCMS.SASPO.Workflow@us.af.mil
- No Source Approval Request (SAR) Package required due to AMSC code of G (full and open competition)
- Visit dibbs.bsm.dla.mil for solicitation

Supplying Warfighter Dominance



Gear Spur: AS – New Buy

Hill AFB – 419th SCMS



MD:	T-38
TMS:	N/A
Noun:	Gear Spur
NSN:	3020-00-888-0130
P/N:	3-51145-1
Forecasted Buy Price:	\$1,953.40
Forecasted Repair Cost:	N/A
AAC:	D
Unserv. Assets Avail:	N/A
QPA/APPL Rate:	

AMC/AMSC:	1	C
RMC/RMSC:	N/A	N/A
Material:	Steel Overall 4620	
Dimensions:	Length: 1.690 Diameter: 3.181 Width: 0.444	
Drawings Releasable:	Yes	
Drawing #:	3-51145	
Drawing Cage Code:	76823	
T.O. Releasable:	Yes	
T.O. #:	16G1-102-4	
Budget Code:	9	
Next Higher Asmbly:		

Out Year Requirements: BUY									
FY26:	480	FY27:	480	FY28:	480	FY29:	480	FY30:	480

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Available	RDL:	Not Available
Tinker	-----	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Source Approval Request (SAR) Package
- Interested vendors should submit a Source Approval Request (SAR) to dlaavnsmlbus@dla.mil

Supplying Warfighter Dominance



Space and C3I Radar Systems



Supplying Warfighter Dominance



Antenna Control Unit: Market Research

Hill AFB – 415th SCMS



MD:	AN/FRC-178	
TMS:	N/A	
Noun:	Antenna Control Unit	
NSN:	5985-01-551-5043	
P/N:	1262806/ 1262802/ 3883/ RTL-S200008	
Forecasted Buy Price:	\$34,503.20	
Forecasted Repair Cost:	\$15,665.87	
AAC:	V	
Unserv. Assets Avail:	N/A	
QPA/APPL Rate:	1	100%

AMC/AMSC:	N/A	N/A
RMC/RMSC:	1	C
Material:	Assorted electronic components	
Dimensions:	28.5"L X 27.5"W X 20.75"H, 36LBS	
Drawings Releasable:	N/A	
Drawing #:	N/A	
Drawing Cage Code:	N/A	
T.O. Releasable:	N/A	
T.O. #:	N/A	
Budget Code:	N/A	
Next Higher Asmbly:		

Out Year Requirements: BUY									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	4	FY27:	4	FY28:	4	FY29:	4	FY30:	4

EDL:	Not Available	RDL:	Available
Tinker	-----	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- Interested vendors should submit a Capabilities Statement to 429SCMS.SASPO.Workflow@us.af.mil
- No Source Approval Request (SAR) Package required
- Seeking qualified vendors with the technical expertise and capabilities to provide reliable and cost-effective repair solutions

Supplying Warfighter Dominance



Power Supply Assembly: Market Research

Hill AFB – 415th SCMS



MD:	AN/FPS-123
TMS:	N/A
Noun:	Power Supply Assembly
NSN:	6130-01-214-9929
P/N:	168084A / 953099
Forecasted Buy Price:	\$11,649.56
Forecasted Repair Cost:	\$6,143.11
AAC:	V
Unserv. Assets Avail:	N/A
QPA/APPL Rate:	

AMC/AMSC:	1	H
RMC/RMSC:	N/A	N/A
Material:	Metal	
Dimensions:	21.31" x 19.00" x 5.19"	
Drawings Releasable:	N/A	
Drawing #:	N/A	
Drawing Cage Code:	N/A	
T.O. Releasable:	N/A	
T.O. #:	N/A	
Budget Code:	8	
Next Higher Asmbly:		

Out Year Requirements: BUY									
FY26:	0	FY27:	5	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	0	FY27:	5	FY28:	0	FY29:	0	FY30:	0

EDL:	Not Available	RDL:	Not Available
Tinker	-----	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- Interested vendors should submit a Capabilities Statement to 429SCMS.SASPO.Workflow@us.af.mil
- No Source Approval Request (SAR) Package required

Supplying Warfighter Dominance



Power Supply: Market Research

Hill AFB – 415th SCMS



MD:	AN/FPS-123
TMS:	N/A
Noun:	Power Supply
NSN:	6130-01-215-8099
P/N:	168085 / 953098
Forecasted Buy Price:	\$7,638.54
Forecasted Repair Cost:	\$5,370.94
AAC:	V
Unserv. Assets Avail:	N/A
QPA/APPL Rate:	

AMC/AMSC:	3	H
RMC/RMSC:	N/A	N/A
Material:	Metal	
Dimensions:	22.50" x 19.00" x 5.25"	
Drawings Releasable:	N/A	
Drawing #:	N/A	
Drawing Cage Code:	N/A	
T.O. Releasable:	N/A	
T.O. #:	N/A	
Budget Code:	8	
Next Higher Asmbly:		

Out Year Requirements: BUY							
FY26:	0	FY27:	2	FY28:	0	FY29:	0
FY30:	0						

Out Year Requirements: REPAIR							
FY26:	0	FY27:	2	FY28:	0	FY29:	0
FY30:	0						

EDL:	Not Available	RDL:	Not Available
Tinker	-----	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- Interested vendors should submit a Capabilities Statement to 429SCMS.SASPO.Workflow@us.af.mil
- No Source Approval Request (SAR) Package required

Supplying Warfighter Dominance



Electrical Power Strip: Market Research

Hill AFB – 415th SCMS



MD:	AN/FRC-178	
TMS:	N/A	
Noun:	Electrical Power Strip	
NSN:	6150-01-551-0754	
P/N:	PTXL-V016-1-05 / RTL-S200018	
Forecasted Buy Price:	\$2,339.32	
Forecasted Repair Cost:	\$1,200.00	
AAC:	V	
Unserv. Assets Avail:	N/A	
QPA/APPL Rate:	2	100%

AMC/AMSC:	N/A	N/A
RMC/RMSC:	5	R
Material:	Metal with copper	
Dimensions:	69"L X 7"W X 3"H, 17.3000LBS	
Drawings Releasable:	N/A	
Drawing #:	N/A	
Drawing Cage Code:	N/A	
T.O. Releasable:	N/A	
T.O. #:	N/A	
Budget Code:	8	
Next Higher Asmbly:		

Out Year Requirements: BUY									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	2	FY27:	2	FY28:	2	FY29:	2	FY30:	2

EDL:	Not Available	RDL:	Available
Tinker	-----	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- Interested vendors should submit a Capabilities Statement to 429SCMS.SASPO.Workflow@us.af.mil
- No Source Approval Request (SAR) Package required
- Seeking qualified vendors with the technical expertise and capabilities to provide reliable and cost-effective repair solutions

Supplying Warfighter Dominance



Server Dell R520: Market Research

Hill AFB – 415th SCMS



MD:	AN/FRC-178	
TMS:	N/A	
Noun:	Server Dell R520	
NSN:	7021-01-645-0467	
P/N:	A000102-01-REV-A00 / 480-09-01859	
Forecasted Buy Price:	\$21,267.57	
Forecasted Repair Cost:	\$3,636.73	
AAC:	V	
Unserv. Assets Avail:	N/A	
QPA/APPL Rate:	1	100%

AMC/AMSC:	N/A	N/A
RMC/RMSC:	2	R
Material:	Electronic	
Dimensions:	25.55"L X 17.08"W X 3.41"H, 62LBS	
Drawings Releasable:	N/A	
Drawing #:	N/A	
Drawing Cage Code:	N/A	
T.O. Releasable:	N/A	
T.O. #:	N/A	
Budget Code:	N/A	
Next Higher Asmbly:		

Out Year Requirements: BUY									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	1	FY27:	1	FY28:	1	FY29:	1	FY30:	1

EDL:	Not Available	RDL:	Available
Tinker	-----	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- Interested vendors should submit a Capabilities Statement to 429SCMS.SASPO.Workflow@us.af.mil
- No Source Approval Request (SAR) Package required
- Seeking qualified vendors with the technical expertise and capabilities to provide reliable and cost-effective repair solutions

Supplying Warfighter Dominance



Control Indicator: AS – New Buy Hill AFB – 415th SCMS



MD:	AN/FPS-85	
TMS:	N/A	
Noun:	Control Indicator	
NSN:	5895-00-442-8694	
P/N:	2056351-0501	
Forecasted Buy Price:	\$877,200.00	
Forecasted Repair Cost:	\$252,189.07	
AAC:	C	
Unserv. Assets Avail:	N/A	
QPA/APPL Rate:	16	100%

AMC/AMSC:	3	H
RMC/RMSC:	N/A	N/A
Material:	Electronic Components	
Dimensions:	20.5" x 19" X 12.22"	
Drawings Releasable:	See note on Slide 2	
Drawing #:	Not Available	
Drawing Cage Code:	Not Available	
T.O. Releasable:	Yes	
T.O. #:	31P1-2FPS85-22	
Budget Code:	8	
Next Higher Asmbly:	Control Indicator Group PN 2058146-0502	

Out Year Requirements: BUY									
FY26:	1-2	FY27:	0	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Not Available	RDL:	Not Available
Tinker	8/07/2025	Robins	2025, 3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Source Approval Request (SAR)
- Interested vendors should submit a Source Approval Request (SAR) to AFSC.OL.SB@us.af.mil and include your email address and "request a drop off." A request for drop off will be returned, use this to submit your SAR package.



Control Indicator: AS – New Buy ***Hill AFB – 415th SCMS***



Additional Comments

- We are facing obsolescence issues with this NSN. The OEM is no longer interested in manufacturing this item and/or has gone out of business. No form-fit-function replacement for this item exists and all attempts to find one via independent market research have failed. We are looking for a vendor who would be willing to manufacture and/or repair this item for us.
- Drawings not present in A-TEAM, but can be provided under certain conditions



Circuit Card Assembly: AS – New Buy/Repair

Hill AFB – 415th SCMS



MD:	AN/FPS-85
TMS:	N/A
Noun:	Circuit Card Assembly
NSN:	5998-01-464-3866
P/N:	2052607-0501
Forecasted Buy Price:	\$5,406.32
Forecasted Repair Cost:	\$2,773.28
AAC:	V
Unserv. Assets Avail:	N/A
QPA/APPL Rate:	

AMC/AMSC:	3	H
RMC/RMSC:	2	R
Material:	Electronic Components	
Dimensions:	9.5"L X 6.5"W X 4"H, 4LBS	
Drawings Releasable:	See note on Slide 2	
Drawing #:	Not Available	
Drawing Cage Code:	Not Available	
T.O. Releasable:	Yes	
T.O. #:	31P1-2FPS85-22	
Budget Code:	8	
Next Higher Asmbly:	Transmitter, Radar - 5840014540012	

Out Year Requirements: BUY									
FY26:	20-50	FY27:	20-50	FY28:	20-50	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	10	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Not Available	RDL:	Available
Tinker	8/07/2025	Robins	2025, 3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Source Approval Request (SAR)
- Interested vendors should submit a Source Approval Request (SAR) to AFSC.OL.SB@us.af.mil and include your email address and "request a drop off." A request for drop off will be returned, use this to submit your SAR package.



Circuit Card Assembly: AS – New Buy ***Hill AFB – 415th SCMS***



Additional Comments

- We are facing obsolescence issues with this NSN. The OEM is no longer interested in manufacturing this item and/or has gone out of business. No form-fit-function replacement for this item exists and all attempts to find one via independent market research have failed. We are looking for a vendor who would be willing to manufacture and/or repair this item for us.
- Drawing not in A-TEAM, but can be provided under certain conditions.



I/O Module: Market Research

Hill AFB – 415th SCMS



MD:	AN/FPS-85
TMS:	N/A
Noun:	I/O Module
NSN:	5998-01-586-6701
P/N:	R106247-01 or 778800-01
Forecasted Buy Price:	\$3,178.72
Forecasted Repair Cost:	\$1,630.59
AAC:	C
Unserv. Assets Avail:	N/A
QPA/APPL Rate:	

AMC/AMSC:	N/A	N/A
RMC/RMSC:	N/A	N/A
Material:	Electronic Components	
Dimensions:	12.5" L x 8.3" W x 3" D, 3 LBS	
Drawings Releasable:	No	
Drawing #:	Not Available	
Drawing Cage Code:	Not Available	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	8	
Next Higher Asmbly:	Monitor Controller, Transmitter - R104019-01	

Out Year Requirements: BUY									
FY26:	1-2	FY27:	0	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Not Available	RDL:	Not Available
Tinker	8/7/2025	Robins	2025, 3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- Interested vendors should submit a Capabilities Statement to 429SCMS.SASPO.Workflow@us.af.mil
- No Source Approval Request (SAR) Package required



I/O Module: Market Research

Hill AFB – 415th SCMS



Additional Comments

- This is a COTS item, and we don't have any data on it. We are facing obsolescence issues with this NSN. The OEM is no longer interested in manufacturing this item and/or has gone out of business. No form-fit-function replacement for this item exists and all attempts to find one via independent market research have failed. We are looking for a vendor who would be willing to manufacture or sell us this item for us.



Multiplexer Switch Module: Market Research

Hill AFB – 415th SCMS



MD:	AN/FPS-85
TMS:	N/A
Noun:	Multiplexer Switch Module
NSN:	6030-01-582-8092
P/N:	R106255-01 or 778572-94
Forecasted Buy Price:	\$2,161.94
Forecasted Repair Cost:	\$1,109.01
AAC:	C
Unserv. Assets Avail:	N/A
QPA/APPL Rate:	

AMC/AMSC:	N/A	N/A
RMC/RMSC:	N/A	N/A
Material:	Electronic Components	
Dimensions:	8.5" X 5.1" X.8"	
Drawings Releasable:	No	
Drawing #:	Not Available	
Drawing Cage Code:	Not Available	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	8	
Next Higher Asmbly:	Chassis Assembly, PXI, Diagnostic - PN R103864-01	

Out Year Requirements: BUY									
FY26:	1-2	FY27:	0	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Not Available	RDL:	Not Available
Tinker	8/07/2025	Robins	2025, 3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- Interested vendors should submit a Capabilities Statement to 429SCMS.SASPO.Workflow@us.af.mil
- No Source Approval Request (SAR) Package required



Multiplexer Switch Module: Market Research

Hill AFB – 415th SCMS



Additional Comments

- This is a COTS item. We are facing obsolescence issues with this NSN. The OEM is no longer interested in manufacturing this item and/or has gone out of business. No form-fit-function replacement for this item exists and all attempts to find one via independent market research have failed. We are looking for a vendor who would be willing to manufacture or sell us this item.



Electric Brake: AS – New Buy

Hill AFB – 415th SCMS



MD:	AN/FSD-3
TMS:	N/A
Noun:	Electric Brake
NSN:	6110-01-523-0228
P/N:	501420-2
Forecasted Buy Price:	\$29,944.68
Forecasted Repair Cost:	N/A
AAC:	D
Unserv. Assets Avail:	N/A
QPA/APPL Rate:	

AMC/AMSC:	4	R
RMC/RMSC:	1	C
Material:	Metal	
Dimensions:	15.4'L X 13.4'W X 15.8'H 32 LBS	
Drawings Releasable:	No	
Drawing #:	Not Available	
Drawing Cage Code:	Not Available	
T.O. Releasable:	Yes	
T.O. #:	31S1-2FSD3-62	
Budget Code:	8	
Next Higher Asmbly:	501341-1 Brake Assembly	

Out Year Requirements: BUY									
FY26:	2	FY27:	0	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Available	RDL:	Not Available
Tinker	8/7/2025	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Source Approval Request (SAR)
- Interested vendors should submit a Source Approval Request (SAR) to AFSC.OL.SB@us.af.mil and include your email address and "request a drop off." A request for drop off will be returned, use this to submit your SAR package.
- Licensing agreement may be required for data request



Electric Brake: AS – New Buy ***Hill AFB – 415th SCMS***



Additional Comments

- This item is currently sole source. We are looking for additional vendors who would be willing to manufacture and/or repair this item for us.



Oscillating Group: AS – New Buy

Hill AFB – 415th SCMS

MD:	AN/FPS-85
TMS:	N/A
Noun:	Oscillating Group
NSN:	5955-00-054-5924
P/N:	2052607-0501
Forecasted Buy Price:	\$1,671.81
Forecasted Repair Cost:	N/A
AAC:	V
Unserv. Assets Avail:	N/A
QPA/APPL Rate:	

AMC/AMSC:	N/A	N/A
RMC/RMSC:	2	C
Material:	Metal	
Dimensions:	12.5"L X 12.5"W X 18.5"H, 5LBS	
Drawings Releasable:	See note on Slide 2	
Drawing #:	Not Available	
Drawing Cage Code:	Not Available	
T.O. Releasable:	Yes	
T.O. #:	31P1-2FPS85-06	
Budget Code:	8	
Next Higher Asmbly:	Pulse Generator PN 2052609-0501	

Out Year Requirements: BUY									
FY26:	1-2	FY27:	0	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Not Available	RDL:	Available
Tinker	8/07/2025	Robins	2025, 3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Source Approval Request (SAR)
- Interested vendors should submit a Source Approval Request (SAR) to AFSC.OL.SB@us.af.mil and include your email address and "request a drop off." A request for drop off will be returned, use this to submit your SAR package.



Oscillating Group: AS – New Buy Hill AFB – 415th SCMS



Additional Comments

- We are facing obsolescence issues with this NSN. The OEM is no longer interested in manufacturing this item and/or has gone out of business. No form-fit-function replacement for this item exists and all attempts to find one via independent market research have failed. We are looking for a vendor who would be willing to manufacture this item for us.
- Drawings not in A-TEAM, but can be provided under certain conditions.



Radio Frequency Amplifier: Reverse Engineering

Hill AFB – 415th SCMS



MD:	AN/FPS-85	
TMS:	N/A	
Noun:	Radio Frequency Amplifier	
NSN:	5996-01-499-6546	
P/N:	D0412897-2 or BHE5819-300/3159A	
Forecasted Buy Price:	\$116,034.60	
Forecasted Repair Cost:	N/A	
AAC:	C	
Unserv. Assets Avail:	No	
QPA/APPL Rate:	3	100%

AMC/AMSC:	4	R
RMC/RMSC:	1	C
Material:	Metal, wires, electrical connectors, microcircuit devices	
Dimensions:	27"L X 19"W X 9"H, 30 LBS	
Drawings Releasable:	No	
Drawing #:	Not Available	
Drawing Cage Code:	Not Available	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	8	
Next Higher Asmby:	Amplifier-Power Supply PN 2017666-0506	

Out Year Requirements: BUY							
FY26:	6	FY27:	0	FY28:	0	FY29:	0
FY30:	0						

Out Year Requirements: REPAIR							
FY26:	0	FY27:	0	FY28:	0	FY29:	0
FY30:	0						

EDL:	Not Available	RDL:	Not Available
Tinker	8/7/2025	Robins	2025, 3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Complete Technical Data Package, Prototype, 3D Modeling Data, Testing Procedures
- Interested vendors should submit a White Paper to 429SCMS.SASPO.Workflow@us.af.mil
- RSVP for Technical Discussion



Radio Frequency Amplifier: Reverse Engineering

Hill AFB – 415th SCMS



Additional Comments

- We are facing obsolescence issues with this NSN. We do not have the data for this item. The OEM is no longer interested in manufacturing this item and/or has gone out of business. No form fit function replacement for this item exists and all attempts to find one via independent market research have failed. We are looking for a vendor who would be willing to manufacture this item for us.

**The Technical Discussion for this item
has already taken place. If you have questions regarding this item,
please submit them to**

429SCMS.SASPO.Workflow@us.af.mil



Power Supply Assembly: AS – New Buy/Repair

Hill AFB – 415th SCMS



MD:	AN/FPS-115
TMS:	N/A
Noun:	Power Supply Assembly
NSN:	6130-01-591-5129
P/N:	8325044
Forecasted Buy Price:	\$66,070.60
Forecasted Repair Cost:	N/A
AAC:	C
Unserv. Assets Avail:	N/A
QPA/APPL Rate:	

AMC/AMSC:	2	C
RMC/RMSC:	N/A	N/A
Material:	Metal, wiring	
Dimensions:	31"L X 28"W X 15"H, 53 LBS	
Drawings Releasable:	Yes	
Drawing #:	8325044	
Drawing Cage Code:	53711	
T.O. Releasable:	Yes	
T.O. #:	31P6-2FPS115-14	
Budget Code:	8	
Next Higher Asmbly:	Missile Tracking Receiver/Transmitter Antenna	

Out Year Requirements: BUY									
FY26:	0	FY27:	5	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	0	FY27:	5	FY28:	0	FY29:	0	FY30:	0

EDL:	Available	RDL:	Not Available
Tinker	8/7/2025	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Source Approval Request (SAR)
- Interested vendors should submit a Source Approval Request (SAR) to AFSC.OL.SB@us.af.mil and include your email address and "request a drop off." A request for drop off will be returned, use this to submit your SAR package.



Power Supply Assembly: AS – New Buy/Repair Hill AFB – 415th SCMS



Additional Comments

- This item is sole source. We are looking for additional vendors who would be willing to manufacture and/or repair this item for us.



Power Supply: AS – New Buy/Repair

Hill AFB – 415th SCMS



MD:	AN/FPS-115
TMS:	N/A
Noun:	Power Supply
NSN:	6130-01-591-5130
P/N:	8325054
Forecasted Buy Price:	\$46,282.12
Forecasted Repair Cost:	N/A
AAC:	C
Unserv. Assets Avail:	N/A
QPA/APPL Rate:	

AMC/AMSC:	2	C
RMC/RMSC:	2	C
Material:	Metal, wiring	
Dimensions:	31"L X 28"W X 15"H, 53 lbs	
Drawings Releasable:	Yes	
Drawing #:	8325054	
Drawing Cage Code:	53711	
T.O. Releasable:	Yes	
T.O. #:	31P6-2FPS115-14	
Budget Code:	8	
Next Higher Asmbly:	Missile Tracking Receiver/Transmitter Antenna	

Out Year Requirements: BUY									
FY26:	0	FY27:	2	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	0	FY27:	2	FY28:	0	FY29:	0	FY30:	0

EDL:	Available	RDL:	Available
Tinker	8/7/2025	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Source Approval Request (SAR)
- Interested vendors should submit a Source Approval Request (SAR) to AFSC.OL.SB@us.af.mil and include your email address and "request a drop off." A request for drop off will be returned, use this to submit your SAR package.



Power Supply: AS – New Buy/Repair Hill AFB – 415th SCMS



Additional Comments

- This item is sole source. We are looking for additional vendors who would be willing to manufacture and/or repair this item for us.



Fixed Attenuator: AS – New Buy/Repair

Hill AFB – 415th SCMS



MD:	AN/FPS-123
TMS:	N/A
Noun:	Fixed Attenuator
NSN:	5895-01-053-6204
P/N:	953426-2
Forecasted Buy Price:	\$194,074.59
Forecasted Repair Cost:	\$83,170.00
AAC:	C
Unserv. Assets Avail:	N/A
QPA/APPL Rate:	

AMC/AMSC:	1	H
RMC/RMSC:	5	C
Material:	Metal body with inner wiring	
Dimensions:	24.5"L X 16.5"W X 4"H, 8LBS	
Drawings Releasable:	Yes	
Drawing #:	953426-2	
Drawing Cage Code:	49956	
T.O. Releasable:	Yes	
T.O. #:	31P6-2FPS132-4	
Budget Code:	8	
Next Higher Asmbly:	G774545-1/453425-1	

Out Year Requirements: BUY									
FY26:	2	FY27:	0	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	2	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Available	RDL:	Available
Tinker	8/7/2025	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Source Approval Request (SAR)
- Interested vendors should submit a Source Approval Request (SAR) to AFSC.OL.SB@us.af.mil and include your email address and "request a drop off." A request for drop off will be returned, use this to submit your SAR package.



Fixed Attenuator: AS – New Buy/Repair Hill AFB – 415th SCMS



Additional Comments

- This item is sole source. We are looking for additional vendors who would be willing to manufacture and/or repair this item for us.



Amplifier Assembly: AS – Repair

Hill AFB – 415th SCMS



MD:	AN/FPQ-16
TMS:	N/A
Noun:	Amplifier Assembly
NSN:	5996-01-433-3730
P/N:	9378602-10
Forecasted Buy Price:	\$7,797.72
Forecasted Repair Cost:	\$4000.00
AAC:	C
Unserv. Assets Avail:	N/A
QPA/APPL Rate:	

AMC/AMSC:	2	C
RMC/RMSC:	1	C
Material:	Machine screws, Insulated wire, Resistors, Capacitors	
Dimensions:	12.5"L X 12.5"W X 14.5"H, 6 LBS	
Drawings Releasable:	Yes	
Drawing #:	11259445	
Drawing Cage Code:	17773	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	8	
Next Higher Asmbly:	11259442-3 Trigger Pulse Amplifier	

Out Year Requirements: BUY									
FY26:	0	FY27:	5	FY28:	5	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Available	RDL:	Available
Tinker	8/7/2025	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Source Approval Request (SAR)
- Interested vendors should submit a Source Approval Request (SAR) to AFSC.OL.SB@us.af.mil and include your email address and "request a drop off." A request for drop off will be returned, use this to submit your SAR package.



Amplifier Assembly: AS – Repair ***Hill AFB – 415th SCMS***



Additional Comments

- This NSN is currently sole source. We are looking for additional vendors who would be willing to manufacture and/or repair this item for us.



Electron Tube: AS – New Buy/Repair

Hill AFB – 415th SCMS



MD:	AN/FPQ-16
TMS:	N/A
Noun:	Electron Tube
NSN:	5960-01-058-6272
P/N:	L-4920
Forecasted Buy Price:	\$508,829.68
Forecasted Repair Cost:	\$234,301.10
AAC:	C
Unserv. Assets Avail:	N/A
QPA/APPL Rate:	

AMC/AMSC:	N/A	N/A
RMC/RMSC:	3	R
Material:	Various electronic and metal materials	
Dimensions:	12'L X 3'W X 3'H, 2,620LBS	
Drawings Releasable:	Yes	
Drawing #:	11260971	
Drawing Cage Code:	17773	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	8	
Next Higher Asmbly:	11259442-3 Amplifier-Modulator	

Out Year Requirements: BUY									
FY26:	47	FY27:	0	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	47	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Not Available	RDL:	Available
Tinker	8/7/2025	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Source Approval Request (SAR)
- Interested vendors should submit a Source Approval Request (SAR) to AFSC.OL.SB@us.af.mil and include your email address and "request a drop off." A request for drop off will be returned, use this to submit your SAR package.
- Licensing agreement may be required for data request



Electron Tube: AS – New Buy/Repair Hill AFB – 415th SCMS



Additional Comments

- This NSN is currently sole source to the OEM. We are looking for additional vendors who would be willing to manufacture and/or repair this item for us.



Phase Shifter Assembly: AS – New Buy/Repair

Hill AFB – 415th SCMS



MD:	AN/FPS-85
TMS:	N/A
Noun:	Phase Shifter Assembly
NSN:	6125-00-838-7075
P/N:	2016817-0501 or PM66194221
Forecasted Buy Price:	\$2,141.68
Forecasted Repair Cost:	\$1,025.00
AAC:	C
Unserv. Assets Avail:	N/A
QPA/APPL Rate:	

AMC/AMSC:	3	R
RMC/RMSC:	1	C
Material:	Various metals and plastics	
Dimensions:	16.5"L X 4.3"W X 4.3"H, 5 LBS	
Drawings Releasable:	Yes	
Drawing #:	2016817	
Drawing Cage Code:	06845	
T.O. Releasable:	Yes	
T.O. #:	31P1-2FPS85-12	
Budget Code:	8	
Next Higher Asmbly:	2019735-0501 Printed Circuit Assembly	

Out Year Requirements: BUY									
FY26:	0	FY27:	0	FY28:	100	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	25	FY29:	0	FY30:	0

EDL:	Available	RDL:	Available
Tinker	8/7/2025	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Source Approval Request (SAR)
- Interested vendors should submit a Source Approval Request (SAR) to AFSC.OL.SB@us.af.mil and include your email address and "request a drop off." A request for drop off will be returned, use this to submit your SAR package.
- Licensing agreement may be required for data request



Phase Shifter Assembly: AS – New Buy/Repair ***Hill AFB – 415th SCMS***



Additional Comments

- We are facing obsolescence issues with this NSN. The OEM is no longer interested in manufacturing this item and/or has gone out of business. Some vendors have shown interest, but none have qualified. We are looking for a vendor who would be willing to manufacture and/or repair this item for us.



Pulsed Amplifier: AS – New Buy/Repair

Hill AFB – 415th SCMS



MD:	AN/FPS-85
TMS:	N/A
Noun:	Pulsed Amplifier
NSN:	5996-01-454-4605
P/N:	DB060685-2 or 9477861-01
Forecasted Buy Price:	\$4,291.38
Forecasted Repair Cost:	\$475.00
AAC:	C
Unserv. Assets Avail:	N/A
QPA/APPL Rate:	

AMC/AMSC:	3	V
RMC/RMSC:	1	C
Material:	Electrical components	
Dimensions:	16.5"L X 16.5"W X 4"H X 6.5 LBS	
Drawings Releasable:	Yes	
Drawing #:	9477861	
Drawing Cage Code:	97849	
T.O. Releasable:	Yes	
T.O. #:	31P1-2FPS85-22	
Budget Code:	8	
Next Higher Asmbly:	9477861	

Out Year Requirements: BUY									
FY26:	0	FY27:	50	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	0	FY27:	50	FY28:	0	FY29:	0	FY30:	0

EDL:	Available	RDL:	Available
Tinker	8/7/2025	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Source Approval Request (SAR)
- Interested vendors should submit a Source Approval Request (SAR) to AFSC.OL.SB@us.af.mil and include your email address and "request a drop off." A request for drop off will be returned, use this to submit your SAR package.



Pulsed Amplifier: AS – New Buy/Repair Hill AFB – 415th SCMS



Additional Comments

- This item is currently sole source. We are looking for additional vendors who would be willing to manufacture and/or repair this item for us.



Power Radio Divider: AS – New Buy

Hill AFB – 415th SCMS



MD:	AN/FPS-123	
TMS:	N/A	
Noun:	Divider, Power, Radio	
NSN:	5895-01-331-4875	
P/N:	953143	
Forecasted Buy Price:	\$87,720.00	
Forecasted Repair Cost:	\$38,709.68	
AAC:	C	
Unserv. Assets Avail:	N/A	
QPA/APPL Rate:	2	100%

AMC/AMSC:	2	C
RMC/RMSC:	N/A	N/A
Material:	Metal, circuitry and brass fittings	
Dimensions:	10.5"L X 6.3"W X 4.5"H, 2.5LBS	
Drawings Releasable:	Yes	
Drawing #:	953143	
Drawing Cage Code:	49956	
T.O. Releasable:	Yes	
T.O. #:	31P6-2FPS132-4	
Budget Code:	8	
Next Higher Asmbly:	Control Test Set - 911267-1	

Out Year Requirements: BUY									
FY26:	1-2	FY27:	1-2	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Available	RDL:	Not Available
Tinker	8/7/2025	Robins	2025, 3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Source Approval Request (SAR)
- Interested vendors should submit a Source Approval Request (SAR) to AFSC.OL.SB@us.af.mil and include your email address and "request a drop off." A request for drop off will be returned, use this to submit your SAR package.



Power Radio Divider: AS – New Buy Hill AFB – 415th SCMS



Additional Comments

- We are facing obsolescence issues with this NSN. The OEM is no longer interested in manufacturing this item and/or has gone out of business. No form-fit-function replacement for this item exists and all attempts to find one via independent market research have failed. We are looking for a vendor who would be willing to manufacture this item for us.



High Power Amplifier: AS – New Buy

Hill AFB – 415th SCMS



MD:	AN/FPS-124
TMS:	N/A
Noun:	High Power Amplifier
NSN:	5840-01-365-0160
P/N:	1216950-301
Forecasted Buy Price:	\$8,966.43
Forecasted Repair Cost:	\$4,599.51
AAC:	V
Unserv. Assets Avail:	N/A
QPA/APPL Rate:	72

AMC/AMSC:	N/A	N/A
RMC/RMSC:	N/A	N/A
Material:	Copper Clad, Ceramic Filled PTFE Microstrip CCA	
Dimensions:	12.0" X 3.75"X 1.0" Approximate	
Drawings Releasable:	Yes	
Drawing #:	1216950	
Drawing Cage Code:	56232	
T.O. Releasable:	Yes	
T.O. #:	31P7-2FPS124-14, -1-1 thru -1-4, -63-1	
Budget Code:	8	
Next Higher Asmbly:	Amplifier, RF - 5840013654635	

Out Year Requirements: BUY									
FY26:	5-15	FY27:	5-10	FY28:	5	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Not Available	RDL:	Not Available
Tinker	8/7/2025	Robins	2025, 3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Source Approval Request (SAR)
- Interested vendors should submit a Source Approval Request (SAR) to AFSC.OL.SB@us.af.mil and include your email address and "request a drop off." A request for drop off will be returned, use this to submit your SAR package.



High Power Amplifier: AS – New Buy Hill AFB – 415th SCMS



Additional Comments

- Seeking vendor sources for build to print or redesign capability for the AN/FPS-124 High Power Amplifier



Modulator Subassembly: AS – Repair

Hill AFB – 415th SCMS



MD:	AN/MST-T1A	
TMS:	N/A	
Noun:	Modulator Subassembly	
NSN:	5895-01-106-3413	
P/N:	654E4660-3	
Forecasted Buy Price:	\$58,969.26	
Forecasted Repair Cost:	\$31,096.00	
AAC:	C	
Unserv. Assets Avail:	N/A	
QPA/APPL Rate:	4	100%

AMC/AMSC:	3	N
RMC/RMSC:	2	C
Material:	Various electronic parts and metal	
Dimensions:	14"L X 14"W X 14.5"H, 12LBS	
Drawings Releasable:	Yes	
Drawing #:	654E4660	
Drawing Cage Code:	81755	
T.O. Releasable:	Yes	
T.O. #:	43D7-19-2-4	
Budget Code:	8	
Next Higher Asmbly:		

Out Year Requirements: BUY									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	3	FY27:	2	FY28:	2	FY29:	2	FY30:	2

EDL:	Available	RDL:	Available
Tinker	-----	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Source Approval Request (SAR) Package
- Interested vendors should submit a Source Approval Request (SAR) to AFSC.OL.SB@us.af.mil and include your email address and “request a drop off”. A request for drop off will be returned, use this to submit your SAR package.

Supplying Warfighter Dominance



Modulator Subassembly: AS – Repair

Hill AFB – 415th SCMS



MD:	AN/MST-T1A	
TMS:	N/A	
Noun:	Modulator Subassembly	
NSN:	5895-01-106-3414	
P/N:	654E4660-5	
Forecasted Buy Price:	\$66,706.96	
Forecasted Repair Cost:	\$35,176.29	
AAC:	C	
Unserv. Assets Avail:	N/A	
QPA/APPL Rate:	2	100%

AMC/AMSC:	3	N
RMC/RMSC:	1	C
Material:	Electrical components, printer wiring board, coil	
Dimensions:	15.3"L X 14.8"W X 14"H, 18LBS	
Drawings Releasable:	Yes	
Drawing #:	654E4660	
Drawing Cage Code:	81755	
T.O. Releasable:	Yes	
T.O. #:	43D7-19-2-4	
Budget Code:	8	
Next Higher Asmbly:		

Out Year Requirements: BUY									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	13	FY27:	4	FY28:	5	FY29:	4	FY30:	5

EDL:	Available	RDL:	Available
Tinker	-----	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Source Approval Request (SAR) Package
- Interested vendors should submit a Source Approval Request (SAR) to AFSC.OL.SB@us.af.mil and include your email address and “request a drop off”. A request for drop off will be returned, use this to submit your SAR package.

Supplying Warfighter Dominance



Air Conditioner: AS - Repair

Hill AFB – 415th SCMS



MD:	AN/MST-T1A	
TMS:	N/A	
Noun:	Air Conditioner	
NSN:	4120-01-534-3871	
P/N:	MIL-AC-233 or 30P	
Forecasted Buy Price:	\$85,332.00	
Forecasted Repair Cost:	\$33,376.12	
AAC:	C	
Unserv. Assets Avail:	N/A	
QPA/APPL Rate:	1	100%

AMC/AMSC:	N/A	N/A
RMC/RMSC:	1	C
Material:	Metallic, Refrigerant, electric components	
Dimensions:	51" X 21" X 76", 300LBS	
Drawings Releasable:	Yes	
Drawing #:	654VM0002	
Drawing Cage Code:	81755	
T.O. Releasable:	Yes	
T.O. #:	43D7-19-2-4	
Budget Code:	8	
Next Higher Asmbly:		

Out Year Requirements: BUY									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	3	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Not Available	RDL:	Not Available
Tinker	-----	Robins	3/26/2026
Hill	-----	Virtual	-----

Comments

- **Deliverables:** Source Approval Request (SAR) Package
- Interested vendors should submit a Source Approval Request (SAR) to AFSC.OL.SB@us.af.mil and include your email address and "request a drop off". A request for drop off will be returned, use this to submit your SAR package.

Supplying Warfighter Dominance



Transformer Assembly: AS – New Buy

Hill AFB – 415th SCMS



MD:	AN/TPT-T1(V)	
TMS:	N/A	
Noun:	Transformer Assembly	
NSN:	5950-01-332-9063	
P/N:	8811-4350-1	
Forecasted Buy Price:	\$198,293.08	
Forecasted Repair Cost:	\$44,378.89	
AAC:	C	
Unserv. Assets Avail:	N/A	
QPA/APPL Rate:	1	100%

AMC/AMSC:	3	C
RMC/RMSC:	3	R
Material:	N/A	
Dimensions:	28" X 24" X 24", 80 LBS	
Drawings Releasable:	Yes	
Drawing #:	8811-4350	
Drawing Cage Code:	12115	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	8	
Next Higher Asmbly:		

Out Year Requirements: BUY									
FY26:	2	FY27:	0	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:		FY27:		FY28:		FY29:		FY30:	

EDL:	Available	RDL:	Available
Tinker	-----	Robins	3/26/2026
Hill	-----	Virtual	-----

Comments

- **Deliverables:** Source Approval Request (SAR) Package
- Interested vendors should submit a Source Approval Request (SAR) to AFSC.OL.SB@us.af.mil and include your email address and “request a drop off”. A request for drop off will be returned, use this to submit your SAR package.

Supplying Warfighter Dominance



Transformer Assembly: AS – New Buy ***Hill AFB – 415th SCMS***



Additional Comments

- We are facing obsolescence issues with this NSN. The OEM is no longer interested in manufacturing this item and/or has gone out of business. Some vendors have shown interest, but none have qualified. We are looking for a vendor who would be willing to manufacture and/or repair this item for us.



Filament Power Supply: AS – Repair

Hill AFB – 415th SCMS



MD:	AN/TPT-T1(V)	
TMS:	N/A	
Noun:	Filament Power Supply	
NSN:	6130-01-306-9750	
P/N:	8811-1360-2	
Forecasted Buy Price:	\$7,299.36	
Forecasted Repair Cost:	\$3,849.14	
AAC:	C	
Unserv. Assets Avail:	N/A	
QPA/APPL Rate:	1	100%

AMC/AMSC:	N/A	N/A
RMC/RMSC:	3	R
Material:	N/A	
Dimensions:	12.5" X 15" X 6", 13 LBS	
Drawings Releasable:	YES	
Drawing #:	8811-1360	
Drawing Cage Code:	12115	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	8	
Next Higher Asmby:		

Out Year Requirements: BUY									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	2	FY27:	2	FY28:	2	FY29:	2	FY30:	2

EDL:	Not Available	RDL:	Available
Tinker	-----	Robins	3/26/2026
Hill	-----	Virtual	-----

Comments

- **Deliverables:** Source Approval Request (SAR) Package
- Interested vendors should submit a Source Approval Request (SAR) to AFSC.OL.SB@us.af.mil and include your email address and “request a drop off”. A request for drop off will be returned, use this to submit your SAR package.
- Licensing agreement may be required for data request

Supplying Warfighter Dominance



Filament Power Supply: AS – Repair Hill AFB – 415th SCMS



Additional Comments

- We are facing obsolescence issues with this NSN. The OEM is no longer interested in manufacturing this item and/or has gone out of business. Some vendors have shown interest, but none have qualified. We are looking for a vendor who would be willing to manufacture and/or repair this item for us.



Electronic Aircraft Countermeasures



Supplying Warfighter Dominance



Circuit Card Assembly: Market Research

Robins AFB – 408th SCMS



MD:	ALQ-161A	
TMS:	N/A	
Noun:	Circuit Card Assembly	
NSN:	5998-01-558-6693	
P/N:	440204-5	
Forecasted Buy Price:	\$30,224.18	
Forecasted Repair Cost:	\$22,667.00	
AAC:	C	
Unserv. Assets Avail:	N/A	
QPA/APPL Rate:	1	100%

AMC/AMSC:	3	R
RMC/RMSC:	3	R
Material:	Not Available	
Dimensions:	Not Available	
Drawings Releasable:	No	
Drawing #:	Not Available	
Drawing Cage Code:	Not Available	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	8	
Next Higher Asmbly:	ALQ-161A	

Out Year Requirements: BUY							
FY26:	2	FY27:	6	FY28:	0	FY29:	0
FY30:	0						

Out Year Requirements: REPAIR					
FY26:	0	FY27:	3	FY28:	2
FY29:	2	FY30:	1		

EDL:	Not Available	RDL:	Available
Tinker	-----	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Interested vendors should submit a Capabilities Statement to 429SCMS.SASPO.Workflow@us.af.mil
- No Source Approval Request (SAR) Package required



Circuit Card Assembly: Reverse Engineering

Robins AFB – 408th SCMS



MD:	AN/ALE-24	
TMS:	N/A	
Noun:	Circuit Card Assembly	
NSN:	5998-00-015-8937	
P/N:	30-1300	
Forecasted Buy Price:	\$1,998.00	
Forecasted Repair Cost:	N/A	
AAC:	J	
Unserv. Assets Avail:	No	
QPA/APPL Rate:	N/A	N/A

AMC/AMSC:	3	C
RMC/RMSC:	N/A	N/A
Material:	Not Available	
Dimensions:	Not Available	
Drawings Releasable:	No	
Drawing #:	Not Available	
Drawing Cage Code:	Not Available	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	9	
Next Higher Asmbly:	ALE-24	

Out Year Requirements: BUY									
FY26:	10	FY27:	25	FY28:	32	FY29:	35	FY30:	45

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Not Available	RDL:	Not Available
Tinker	-----	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Complete Technical Data Package, Prototype, 3D Modeling Data, Specification Control Drawing Testing and Evaluation
- Interested vendors should submit a White Paper to 429SCMS.SASPO.Workflow@us.af.mil
- RSVP for Technical Discussion



Circuit Card Assembly: Reverse Engineering

Robins AFB – 408th SCMS



Additional Comments

- Lost testing and repair capability of CCA in 2012 due to obsolescence in the legacy tester. This led to increased obsolescence of CCA components due to lack of requisition of malfunctioned components. NHA (LRU) testing was converted to an automated tester in 2020 without individual SRU testing. We lost that capability within a year of establishment. The military is aware of these issues and that is why we have not had any demand for these assets in nearly 5 years.

If you would like to participate in the Technical Discussion on:

Monday, May 4, 2026, 9:00AM – 10:00AM CT

provide the following, NLT

Monday, April 13, 2026

429SCMS.SASPO.Workflow@us.af.mil

-Company, -Address, -Name(s), -Email(s), -Phone,

-Your questions for Engineering, and

-Statement of Capabilities



Circuit Card Assembly: Reverse Engineering

Robins AFB – 408th SCMS



MD:	AN/ALE-24	
TMS:	N/A	
Noun:	Circuit Card Assembly	
NSN:	5998-00-531-5292	
P/N:	RD32023	
Forecasted Buy Price:	\$2,750.03	
Forecasted Repair Cost:	\$1,429.64	
AAC:	C	
Unserv. Assets Avail:	Yes	
QPA/APPL Rate:	1	100%

AMC/AMSC:	N/A	N/A
RMC/RMSC:	N/A	N/A
Material:	Not Available	
Dimensions:	Not Available	
Drawings Releasable:	No	
Drawing #:	Not Available	
Drawing Cage Code:	Not Available	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	8	
Next Higher Asmbly:	ALE-24	

Out Year Requirements: BUY									
FY26:	5	FY27:	7	FY28:	12	FY29:	15	FY30:	20

Out Year Requirements: REPAIR									
FY26:	8	FY27:	15	FY28:	20	FY29:	22	FY30:	32

EDL:	Not Available	RDL:	Not Available
Tinker	-----	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Complete Technical Data Package, Prototype, 3D Modeling Data, Specification Control Drawing Testing and Evaluation
- Interested vendors should submit a White Paper to 429SCMS.SASPO.Workflow@us.af.mil
- RSVP for Technical Discussion



Circuit Card Assembly: Reverse Engineering

Robins AFB – 408th SCMS



Additional Comments

- Lost testing and repair capability of CCA in 2012 due to obsolescence in the legacy tester. This led to increased obsolescence of CCA components due to lack of requisition of malfunctioned components. NHA (LRU) testing was converted to an automated tester in 2020 without individual SRU testing. We lost that capability within a year of establishment. The military is aware of these issues and that is why we have not had any demand for these assets in nearly 5 years.

If you would like to participate in the Technical Discussion on:

Monday, May 4, 2026, 9:00AM – 10:00AM CT

provide the following, NLT

Monday, April 13, 2026

429SCMS.SASPO.Workflow@us.af.mil

-Company, -Address, -Name(s), -Email(s), -Phone,

-Your questions for Engineering, and

-Statement of Capabilities



Circuit Card Assembly: Reverse Engineering

Robins AFB – 408th SCMS



MD:	AN/ALE-24	
TMS:	N/A	
Noun:	Circuit Card Assembly	
NSN:	5998-00-531-5298	
P/N:	RD32220	
Forecasted Buy Price:	57,192.40	
Forecasted Repair Cost:	N/A	
AAC:	C	
Unserv. Assets Avail:	Yes	
QPA/APPL Rate:	1	100%

AMC/AMSC:	N/A	N/A
RMC/RMSC:	N/A	N/A
Material:	Not Available	
Dimensions:	Not Available	
Drawings Releasable:	No	
Drawing #:	Not Available	
Drawing Cage Code:	Not Available	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	8	
Next Higher Asmbly:	ALE- 24	

Out Year Requirements: BUY									
FY26:	10	FY27:	15	FY28:	17	FY29:	28	FY30:	27

Out Year Requirements: REPAIR									
FY26:	15	FY27:	18	FY28:	22	FY29:	25	FY30:	26

EDL:	Not Available	RDL:	Not Available
Tinker	-----	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Complete Technical Data Package, Prototype, 3D Modeling Data, Specification Control Drawing Testing and Evaluation
- Interested vendors should submit a White Paper to 429SCMS.SASPO.Workflow@us.af.mil
- RSVP for Technical Discussion

Supplying Warfighter Dominance



Circuit Card Assembly: Reverse Engineering

Robins AFB – 408th SCMS



Additional Comments

- Lost testing and repair capability of CCA in 2012 due to obsolescence in the legacy tester. This led to increased obsolescence of CCA components due to lack of requisition of malfunctioned components. NHA (LRU) testing was converted to an automated tester in 2020 without individual SRU testing. We lost that capability within a year of establishment. The military is aware of these issues and that is why we have not had any demand for these assets in nearly 5 years.

If you would like to participate in the Technical Discussion on:

Monday, May 4, 2026, 9:00AM – 10:00AM CT

provide the following, NLT

Monday, April 13, 2026

429SCMS.SASPO.Workflow@us.af.mil

-Company, -Address, -Name(s), -Email(s), -Phone,

-Your questions for Engineering, and

-Statement of Capabilities

Supplying Warfighter Dominance



Circuit Card Assembly: Reverse Engineering

Robins AFB – 408th SCMS



MD:	AN/ALE-24	
TMS:	N/A	
Noun:	Circuit Card Assembly	
NSN:	5998-00-531-5294	
P/N:	RD32027	
Forecasted Buy Price:	\$4,473.27	
Forecasted Repair Cost:	\$2,295.12	
AAC:	C	
Unserv. Assets Avail:	Yes	
QPA/APPL Rate:	1	100%

AMC/AMSC:	N/A	N/A
RMC/RMSC:	N/A	N/A
Material:	Not Available	
Dimensions:	Not Available	
Drawings Releasable:	No	
Drawing #:	Not Available	
Drawing Cage Code:	Not Available	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	8	
Next Higher Asmbly:	ALE-24	

Out Year Requirements: BUY									
FY26:	3	FY27:	7	FY28:	10	FY29:	15	FY30:	25

Out Year Requirements: REPAIR									
FY26:	10	FY27:	17	FY28:	25	FY29:	28	FY30:	34

EDL:	Not Available	RDL:	Not Available
Tinker	-----	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Complete Technical Data Package, Prototype, 3D Modeling Data, Specification Control Drawing Testing and Evaluation
- Interested vendors should submit a White Paper to 429SCMS.SASPO.Workflow@us.af.mil
- RSVP for Technical Discussion



Circuit Card Assembly: Reverse Engineering

Robins AFB – 408th SCMS



Additional Comments

- Lost testing and repair capability of CCA in 2012 due to obsolescence in the legacy tester. This led to increased obsolescence of CCA components due to lack of requisition of malfunctioned components. NHA (LRU) testing was converted to an automated tester in 2020 without individual SRU testing. We lost that capability within a year of establishment. The military is aware of these issues and that is why we have not had any demand for these assets in nearly 5 years.

If you would like to participate in the Technical Discussion on:

Monday, May 4, 2026, 9:00AM – 10:00AM CT

provide the following, NLT

Monday, April 13, 2026

429SCMS.SASPO.Workflow@us.af.mil

-Company, -Address, -Name(s), -Email(s), -Phone,

-Your questions for Engineering, and

-Statement of Capabilities



Circuit Card Assembly: Reverse Engineering

Robins AFB – 408th SCMS



MD:	AN/ALE-24	
TMS:	N/A	
Noun:	Circuit Card Assembly	
NSN:	5998-00-531-5300	
P/N:	RD32237	
Forecasted Buy Price:	\$59,529.93	
Forecasted Repair Cost:	\$31,391.66	
AAC:	C	
Unserv. Assets Avail:	Yes	
QPA/APPL Rate:	1	100%

AMC/AMSC:	N/A	N/A
RMC/RMSC:	N/A	N/A
Material:	Not Available	
Dimensions:	Not Available	
Drawings Releasable:	No	
Drawing #:	Not Available	
Drawing Cage Code:	Not Available	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	8	
Next Higher Asmbly:	ALE-24	

Out Year Requirements: BUY									
FY26:	15	FY27:	10	FY28:	15	FY29:	20	FY30:	28

Out Year Requirements: REPAIR									
FY26:	19	FY27:	23	FY28:	21	FY29:	25	FY30:	33

EDL:	Not Available	RDL:	Not Available
Tinker	-----	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Complete Technical Data Package, Prototype, 3D Modeling Data, Specification Control Drawing Testing and Evaluation
- Interested vendors should submit a White Paper to 429SCMS.SASPO.Workflow@us.af.mil
- RSVP for Technical Discussion



Circuit Card Assembly: Reverse Engineering

Robins AFB – 408th SCMS



Additional Comments

- Lost testing and repair capability of CCA in 2012 due to obsolescence in the legacy tester. This led to increased obsolescence of CCA components due to lack of requisition of malfunctioned components. NHA (LRU) testing was converted to an automated tester in 2020 without individual SRU testing. We lost that capability within a year of establishment. The military is aware of these issues and that is why we have not had any demand for these assets in nearly 5 years.

If you would like to participate in the Technical Discussion on:

Monday, May 4, 2026, 9:00AM – 10:00AM CT

provide the following, NLT

Monday, April 13, 2026

429SCMS.SASPO.Workflow@us.af.mil

-Company, -Address, -Name(s), -Email(s), -Phone,

-Your questions for Engineering, and

-Statement of Capabilities



Circuit Card Assembly: Reverse Engineering

Robins AFB – 408th SCMS



MD:	AN/ALE-24	
TMS:	N/A	
Noun:	Circuit Card Assembly	
NSN:	5998-00-531-5303	
P/N:	RD32241	
Forecasted Buy Price:	\$57,192.40	
Forecasted Repair Cost:	\$29,338.00	
AAC:	C	
Unserv. Assets Avail:	Yes	
QPA/APPL Rate:	1	100%

AMC/AMSC:	N/A	N/A
RMC/RMSC:	N/A	N/A
Material:	Not Available	
Dimensions:	Not Available	
Drawings Releasable:	No	
Drawing #:	Not Available	
Drawing Cage Code:	Not Available	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	8	
Next Higher Asmbly:	ALE-24	

Out Year Requirements: BUY									
FY26:	8	FY27:	15	FY28:	22	FY29:	20	FY30:	28

Out Year Requirements: REPAIR									
FY26:	16	FY27:	25	FY28:	22	FY29:	28	FY30:	30

EDL:	Not Available	RDL:	Not Available
Tinker	-----	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Complete Technical Data Package, Prototype, 3D Modeling Data, Specification Control Drawing Testing and Evaluation
- Interested vendors should submit a White Paper to 429SCMS.SASPO.Workflow@us.af.mil
- RSVP for Technical Discussion



Circuit Card Assembly: Reverse Engineering

Robins AFB – 408th SCMS



Additional Comments

- Lost testing and repair capability of CCA in 2012 due to obsolescence in the legacy tester. This led to increased obsolescence of CCA components due to lack of requisition of malfunctioned components. NHA (LRU) testing was converted to an automated tester in 2020 without individual SRU testing. We lost that capability within a year of establishment. The military is aware of these issues and that is why we have not had any demand for these assets in nearly 5 years.

If you would like to participate in the Technical Discussion on:

Monday, May 4, 2026, 9:00AM – 10:00AM CT

provide the following, NLT

Monday, April 13, 2026

429SCMS.SASPO.Workflow@us.af.mil

-Company, -Address, -Name(s), -Email(s), -Phone,

-Your questions for Engineering, and

-Statement of Capabilities



Circuit Card Assembly: Reverse Engineering

Robins AFB – 408th SCMS



MD:	AN/ALE-24	
TMS:	N/A	
Noun:	Circuit Card Assembly	
NSN:	5998-00-805-6851	
P/N:	RD32224A	
Forecasted Buy Price:	\$59,539.93	
Forecasted Repair Cost:	\$31,391.66	
AAC:	C	
Unserv. Assets Avail:	Yes	
QPA/APPL Rate:	1	100%

AMC/AMSC:	N/A	N/A
RMC/RMSC:	N/A	N/A
Material:	Not Available	
Dimensions:	Not Available	
Drawings Releasable:	No	
Drawing #:	Not Available	
Drawing Cage Code:	Not Available	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	8	
Next Higher Asmbly:	ALE-24	

Out Year Requirements: BUY									
FY26:	12	FY27:	15	FY28:	18	FY29:	20	FY30:	28

Out Year Requirements: REPAIR									
FY26:	19	FY27:	21	FY28:	22	FY29:	24	FY30:	35

EDL:	Not Available	RDL:	Not Available
Tinker	-----	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Complete Technical Data Package, Prototype, 3D Modeling Data, Specification Control Drawing Testing and Evaluation
- Interested vendors should submit a White Paper to 429SCMS.SASPO.Workflow@us.af.mil
- RSVP for Technical Discussion

Supplying Warfighter Dominance



Circuit Card Assembly: Reverse Engineering

Robins AFB – 408th SCMS



Additional Comments

- Lost testing and repair capability of CCA in 2012 due to obsolescence in the legacy tester. This led to increased obsolescence of CCA components due to lack of requisition of malfunctioned components. NHA (LRU) testing was converted to an automated tester in 2020 without individual SRU testing. We lost that capability within a year of establishment. The military is aware of these issues and that is why we have not had any demand for these assets in nearly 5 years.

If you would like to participate in the Technical Discussion on:

Monday, May 4, 2026, 9:00AM – 10:00AM CT

provide the following, NLT

Monday, April 13, 2026

429SCMS.SASPO.Workflow@us.af.mil

-Company, -Address, -Name(s), -Email(s), -Phone,

-Your questions for Engineering, and

-Statement of Capabilities

Supplying Warfighter Dominance



Dispenser Subassembly: Reverse Engineering

Robins AFB – 408th SCMS



MD:	AN/ALE-24	
TMS:	N/A	
Noun:	Dispenser Subassembly	
NSN:	5965-00-110-7078	
P/N:	RD32053	
Forecasted Buy Price:	\$5,280.06	
Forecasted Repair Cost:	\$2,784.31	
AAC:	Z	
Unserv. Assets Avail:	Yes	
QPA/APPL Rate:	1	100%

AMC/AMSC:	N/A	N/A
RMC/RMSC:	N/A	N/A
Material:	Not Available	
Dimensions:	Not Available	
Drawings Releasable:	No	
Drawing #:	Not Available	
Drawing Cage Code:	Not Available	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	8	
Next Higher Asmbly:	ALE-24	

Out Year Requirements: BUY									
FY26:	10	FY27:	5	FY28:	7	FY29:	8	FY30:	12

Out Year Requirements: REPAIR									
FY26:	15	FY27:	18	FY28:	13	FY29:	17	FY30:	12

EDL:	Not Available	RDL:	Not Available
Tinker	-----	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Complete Technical Data Package, Prototype, 3D Modeling Data, Specification Control Drawing Testing and Evaluation
- Interested vendors should submit a White Paper to 429SCMS.SASPO.Workflow@us.af.mil
- RSVP for Technical Discussion



Dispenser Subassembly: Reverse Engineering

Robins AFB – 408th SCMS



Additional Comments

- Lost testing and repair capability of CCA in 2012 due to obsolescence in the legacy tester. This led to increased obsolescence of CCA components due to lack of requisition of malfunctioned components. NHA (LRU) testing was converted to an automated tester in 2020 without individual SRU testing. We lost that capability within a year of establishment. The military is aware of these issues and that is why we have not had any demand for these assets in nearly 5 years.

If you would like to participate in the Technical Discussion on:

Monday, May 4, 2026, 9:00AM – 10:00AM CT

provide the following, NLT

Monday, April 13, 2026

429SCMS.SASPO.Workflow@us.af.mil

-Company, -Address, -Name(s), -Email(s), -Phone,

-Your questions for Engineering, and

-Statement of Capabilities



Magnetic Counter: Market Research

Robins AFB – 408th SCMS



MD:	AN/ALE-24		
TMS:	N/A		
Noun:	Magnetic Counter		
NSN:	5865-00-879-7310		
P/N:	152703-108		
Forecasted Buy Price:	\$623.10		
Forecasted Repair Cost:	N/A		
AAC:	V		
Unserv. Assets Avail:	N/A		
QPA/APPL Rate:	N/A		N/A

AMC/AMSC:	N/A	N/A
RMC/RMSC:	N/A	
Material:	N/A	
Dimensions:	N/A	
Drawings Releasable:	No	
Drawing #:	Not Available	
Drawing Cage Code:	Not Available	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	N/A	
Next Higher Asmbly:	ALE-24	

Out Year Requirements: BUY									
FY26:	12	FY27:	22	FY28:	36	FY29:	42	FY30:	60

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Not Available	RDL:	Not Available
Tinker	-----	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- Interested vendors should submit a Capabilities Statement to 429SCMS.SASPO.Workflow@us.af.mil
- No Source Approval Request (SAR) Package required



General Avionics



Supplying Warfighter Dominance



Loading Screen: AS – New Buy

Robins AFB – 407th SCMS



MD:	AN/ARC-171	
TMS:	N/A	
Noun:	Loading Screen	
NSN:	5821-01-064-8454	
P/N:	010648454	
Forecasted Buy Price:	\$89.55	
Forecasted Repair Cost:	N/A	
AAC:	Z	
Unserv. Assets Avail:	N/A	
QPA/APPL Rate:	N/A	N/A

AMC/AMSC:	2	G
RMC/RMSC:	N/A	N/A
Material:	ECCO SORB PER 820-2032-010	
Dimensions:	O/A DIM. 9.23 IN. LG,0.25 IN. W	
Drawings Releasable:	Yes	
Drawing #:	623-2799	
Drawing Cage Code:	13499	
T.O. Releasable:	N/A	
T.O. #:	N/A	
Budget Code:	9	
Next Higher Asmbly:	5996-01-212-1132	

Out Year Requirements: BUY									
FY26:	88	FY27:	10	FY28:	10	FY29:	10	FY30:	10

Out Year Requirements: REPAIR									
FY26:		FY27:		FY28:		FY29:		FY30:	

EDL:	Available	RDL:	Not Available
Tinker	-----	Robins	03/26/2026
Hill	-----	Virtual	-----

Comments

- Interested vendors should submit a Capabilities Statement to 429SCMS.SASPO.Workflow@us.af.mil
- No Source Approval Request (SAR) Package required due to AMSC code of G (full and open competition)
- Visit dibbs.bsm.dla.mil for solicitation

Supplying Warfighter Dominance



Loading Screen: AS – New Buy Robins AFB – 407th SCMS



Additional Comments

- The Robins Depot repair line needs the candidate item to repair the High-Power Amplifier (HPA): NSN: 5996-01-212-1132, PN: 622-1569-003. NSN 5821-01-064-8454 and 5821-01-064-8455 must be combined to create a unified item needed to repair the HPA. The combined component requires two Loading Screens and one Screen Retainer.



Screen Retainer: Market Research

Robins AFB – 407th SCMS



MD:	ARC-171		
TMS:	N/A		
Noun:	Screen Retainer		
NSN:	5821-01-064-8455		
P/N:	010648455		
Forecasted Buy Price:	\$31.07		
Forecasted Repair Cost:	N/A		
AAC:	V		
Unserv. Assets Avail:	N/A		
QPA/APPL Rate:	0		0%

AMC/AMSC:	3	L
RMC/RMSC:	N/A	N/A
Material:	BEYLLIUM COPPER COND A PER QQ-C-533 ALLOY HK HEAT TREAT TO 165000 LB PER SQ IN.	
Dimensions:	OVERALL DIMENSION 8.82 IN. LG BY 3.25 IN. DIAM BY 0.25 IN. W	
Drawings Releasable:	N/A	
Drawing #:	N/A	
Drawing Cage Code:	N/A	
T.O. Releasable:	N/A	
T.O. #:	N/A	
Budget Code:	9	
Next Higher Asmbly:	5996-01-212-1132	

Out Year Requirements: BUY									
FY26:	44	FY27:	5	FY28:	5	FY29:	5	FY30:	5

Out Year Requirements: REPAIR									
FY26:		FY27:		FY28:		FY29:		FY30:	

EDL:	Not Available	RDL:	Not Available
Tinker	-----	Robins	03/26/2026
Hill	-----	Virtual	-----

Comments

- Interested vendors should submit a Capabilities Statement to 429SCMS.SASPO.Workflow@us.af.mil
- No Source Approval Request (SAR) Package required

Supplying Warfighter Dominance



Screen Retainer: Market Research

Robins AFB – 407th SCMS




Additional Comments

- The Robins Depot repair line needs the candidate item to repair the High-Power Amplifier (HPA): NSN: 5996-01-212-1132, PN: 622-1569-003. NSN 5821-01-064-8454 and 5821-01-064-8455 must be combined to create a unified item needed to repair the HPA. The combined component requires two Loading Screens and one Screen Retainer.



F108 Engine



Supplying Warfighter Dominance



Power Manag. Control (PMC): Reverse Engineering Tinker AFB – 421st SCMS



MD:	N/A	
TMS:	F108	
Noun:	Power Manag. Control (PMC)	
NSN:	2915-01-286-5565	
P/N:	7157M61P06	
Forecasted Buy Price:	\$109,590.00	
Forecasted Repair Cost:	\$1,722.77	
AAC:	C	
Unserv. Assets Avail:	32	
QPA/APPL Rate:	1	100

AMC/AMSC:	1	Z
RMC/RMSC:	3	C
Material:	Not Available	
Dimensions:	Not Available	
Drawings Releasable:	No	
Drawing #:	Not Available	
Drawing Cage Code:	Not Available	
T.O. Releasable:	No	
T.O. #:	Not Available	
Budget Code:	8	
Next Higher Asmbly:	F108 Engine	

Out Year Requirements: BUY									
FY26:	17	FY27:	12	FY28:	10	FY29:	12	FY30:	11

Out Year Requirements: REPAIR									
FY26:		FY27:		FY28:		FY29:		FY30:	

EDL:	Not Available	RDL:	Not Available
Tinker	-----	Robins	3/26/2026
Hill	1/15/2026	Virtual	-----

Comments

- **Deliverables:** Complete Technical Data Package, Prototype, 3D Modeling Data, Specification Control Drawing Testing and Evaluation
- Interested vendors should submit a White Paper to 429SCMS.SASPO.Workflow@us.af.mil
- RSVP for Technical Discussion

Supplying Warfighter Dominance



Power Manag. Control (PMC): Reverse Engineering Tinker AFB – 421st SCMS



Additional Comments

- **Problem Statement:** The F108 PMC is facing obsolescence issues as the electronic components are no longer manufactured. Seeking new manufacturing sources.

If you would like to participate in the Technical Discussion on:

Thursday, April 30, 2026, 2:00 PM – 3:00 PM CT.

provide the following, NLT

Monday, April 13, 2026

429SCMS.SASPO.Workflow@us.af.mil

-Company, -Address, -Name(s), -Email(s), -Phone,

-Your questions for Engineering, and

-Statement of Capabilities

Supplying Warfighter Dominance



J85 Engine



Supplying Warfighter Dominance



Housing, Gearbox: Reverse Engineering

Tinker AFB – 421st SCMS



MD:	N/A
TMS:	J-85
Noun:	Housing, Gearbox
NSN:	2840-00-795-1513
P/N:	37R601155P104
Forecasted Buy Price:	\$26,605.10
Forecasted Repair Cost:	\$5,326.15
AAC:	C
Unserv. Assets Avail:	Yes
QPA/APPL Rate:	1 100%

AMC/AMSC:	1	C
RMC/RMSC:	1	C
Material:	Not Available	
Dimensions:	Not Available	
Drawings Releasable:	Yes	
Drawing #:	37R601155	
Drawing Cage Code:	99207	
T.O. Releasable:	Yes	
T.O. #:	2J-J85-54	
Budget Code:	8	
Next Higher Asmbly:	Gearbox Assembly	

Out Year Requirements: BUY									
FY26:	0	FY27:	148	FY28:	13	FY29:	14	FY30:	0

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Available	RDL:	Available
Tinker	-----	Robins	3/26/2026
Hill	-----	Virtual	-----

Comments

- **Deliverables:** Complete Technical Data Package, Prototype, 3D Modeling Data, Specification Control Drawing, Testing and Evaluation.
- Interested vendors should submit a White Paper to 429SCMS.SASPO.Workflow@us.af.mil
- RSVP for Technical Discussion

Supplying Warfighter Dominance



Housing, Gearbox: Reverse Engineering Tinker AFB – 421st SCMS



Additional Comments

- At this time, our current vendor has requested termination of the last 4ea on their contract due to castings and we have out year requirements; with no vendor and no bids.

If you would like to participate in the Technical Discussion on:

Monday, April 27, 2026, 2:00PM – 3:00PM CT

provide the following, NLT

Monday, April 13, 2026

429SCMS.SASPO.Workflow@us.af.mil

-Company, -Address, -Name(s), -Email(s), -Phone,

-Your questions for Engineering, and

-Statement of Capabilities

Supplying Warfighter Dominance



Nozzle Assembly, Turbine: Reverse Engineering

Tinker AFB – 421st SCMS



MD:	N/A	
TMS:	J-85	
Noun:	Nozzle Assembly, Turbine	
NSN:	2840-01-284-5408	
P/N:	6041T41G15	
Forecasted Buy Price:	\$32,416.06	
Forecasted Repair Cost:	\$12,458.88	
AAC:	C	
Unserv. Assets Avail:	Yes	
QPA/APPL Rate:	1	100%

AMC/AMSC:	1	C
RMC/RMSC:	2	C
Material:	Not Available	
Dimensions:	Not Available	
Drawings Releasable:	Yes	
Drawing #:	6041T41	
Drawing Cage Code:	92207	
T.O. Releasable:	Yes	
T.O. #:	2J-J85-54	
Budget Code:	8	
Next Higher Asmbly:	Engine Assembly	

Out Year Requirements: BUY									
FY26:	87	FY27:	7	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Available	RDL:	Available
Tinker	-----	Robins	03/26/2026
Hill	-----	Virtual	-----

Comments

- **Deliverables:** Complete Technical Data Package, Prototype, 3D Modeling Data, Specification Control Drawing, Testing and Evaluation.
- Interested vendors should submit a White Paper to 429SCMS.SASPO.Workflow@us.af.mil
- RSVP for Technical Discussion

Supplying Warfighter Dominance



Nozzle Assembly, Turbine: Reverse Engineering Tinker AFB – 421st SCMS



Additional Comments

- **Item was No Bid**

If you would like to participate in the Technical Discussion on:

Tuesday, April 28, 2026, 2:00PM – 3:00PM CT

provide the following, NLT

Tuesday, April 14, 2026

429SCMS.SASPO.Workflow@us.af.mil

-Company, -Address, -Name(s), -Email(s), -Phone,

-Your questions for Engineering, and

-Statement of Capabilities

Supplying Warfighter Dominance



Valve, Fuel Pressurizing: Reverse Engineering

Tinker AFB – 421st SCMS



MD:	N/A	
TMS:	J-85	
Noun:	Valve, Fuel Pressurizing and Drain	
NSN:	2915-00-896-0173	
P/N:	37C301344G002	
Forecasted Buy Price:	\$ 20,184.36	
Forecasted Repair Cost:	\$ 15,137.51	
AAC:	C	
Unserv. Assets Avail:	Yes	
QPA/APPL Rate:	1	100%

AMC/AMSC:	3	R
RMC/RMSC:	1	C
Material:	Not Available	
Dimensions:	Not Available	
Drawings Releasable:	Yes	
Drawing #:	37C301344	
Drawing Cage Code:	99207	
T.O. Releasable:	Yes	
T.O. #:	2J-J85-54	
Budget Code:	8	
Next Higher Asmbly:	Engine Assembly	

Out Year Requirements: BUY									
FY26:	26	FY27:	0	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Not Available	RDL:	Available
Tinker	-----	Robins	3/26/2026
Hill	-----	Virtual	-----

Comments

- **Deliverables:** Complete Technical Data Package, Prototype, 3D Modeling Data, Specification Control Drawing, Testing and Evaluation.
- Interested vendors should submit a White Paper to 429SCMS.SASPO.Workflow@us.af.mil
- RSVP for Technical Discussion

Supplying Warfighter Dominance



Valve, Fuel Pressurizing: Reverse Engineering Tinker AFB – 421st SCMS



Additional Comments

- **Item is No Bid**

If you would like to participate in the Technical Discussion on:

Wednesday, April 29, 2026, 2:00PM – 3:00PM CT

provide the following, NLT

Wednesday, April 15, 2026

429SCMS.SASPO.Workflow@us.af.mil

-Company, -Address, -Name(s), -Email(s), -Phone,

-Your questions for Engineering, and

-Statement of Capabilities

Supplying Warfighter Dominance



Actuator, Mechanical: Reverse Engineering

Tinker AFB – 421st SCMS



MD:	N/A	
TMS:	J-85	
Noun:	Actuator, Mechanical	
NSN:	3010-00-911-4336	
P/N:	5002T48P01	
Forecasted Buy Price:	\$16856.21	
Forecasted Repair Cost:	\$12641.52	
AAC:	C	
Unserv. Assets Avail:	Yes	
QPA/APPL Rate:	1	100%

AMC/AMSC:	3	B
RMC/RMSC:	1	C
Material:		
Dimensions:	7.8" X 6.7" X 3.4"	
Drawings Releasable:	Yes	
Drawing #:	5002T48	
Drawing Cage Code:	99207	
T.O. Releasable:	Yes	
T.O. #:	2J-J85-54	
Budget Code:	8	
Next Higher Asmbly:	Engine Assembly	

Out Year Requirements: BUY									
FY26:	360	FY27:	0	FY28:	0	FY29:	0	FY30:	0

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0

EDL:	Not Available	RDL:	Available
Tinker	-----	Robins	3/26/2026
Hill	-----	Virtual	-----

Comments

- **Deliverables:** Complete Technical Data Package, Prototype, 3D Modeling Data, Specification Control Drawing, Testing and Evaluation.
- Interested vendors should submit a White Paper to 429SCMS.SASPO.Workflow@us.af.mil
- RSVP for Technical Discussion

Supplying Warfighter Dominance



Actuator, Mechanical: Reverse Engineering Tinker AFB – 421st SCMS



Additional Comments

- **Item was No Bid**

If you would like to participate in the Technical Discussion on:

Tuesday, May 5, 2026, 10:00AM – 11:00AM CT

provide the following, NLT

Tuesday, April 21, 2026

429SCMS.SASPO.Workflow@us.af.mil

-Company, -Address, -Name(s), -Email(s), -Phone,

-Your questions for Engineering, and

-Statement of Capabilities

Supplying Warfighter Dominance



Housing, Mechanical: Reverse Engineering

Tinker AFB – 421st SCMS



MD:	N/A	
TMS:	J-85	
Noun:	Housing, Mechanical	
NSN:	3040-00-011-0704	
P/N:	175R122P009	
Forecasted Buy Price:	\$ 14,457.12	
Forecasted Repair Cost:	\$ 5,816.33	
AAC:	C	
Unserv. Assets Avail:	Yes	
QPA/APPL Rate:	1	100%

AMC/AMSC:	3	R
RMC/RMSC:	1	C
Material:	Not Available	
Dimensions:	Not Available	
Drawings Releasable:	Yes	
Drawing #:	175R122	
Drawing Cage Code:	99207	
T.O. Releasable:	Yes	
T.O. #:	2J-J85-54	
Budget Code:	8	
Next Higher Asmbly:	Gearbox Assembly	

Out Year Requirements: BUY									
FY26:	43	FY27:	8	FY28:	2	FY29:	3	FY30:	4

Out Year Requirements: REPAIR									
FY26:	0	FY27:	0	FY28:	0	FY29:	0	FY30:	0F

EDL:	Not Available	RDL:	Available
Tinker	-----	Robins	3/26/2026
Hill	-----	Virtual	-----

Comments

- **Deliverables:** Complete Technical Data Package, Prototype, 3D Modeling Data, Specification Control Drawing, Testing and Evaluation.
- Interested vendors should submit a white paper to 429SCMS.SASPO.Workflow@us.af.mil
- RSVP for Technical Discussion

Supplying Warfighter Dominance



Housing, Mechanical: Reverse Engineering Tinker AFB – 421st SCMS



Additional Comments

- Item was No Bid

If you would like to participate in the Technical Discussion on:

Monday, May 4, 2026, 2:00PM – 3:00PM CT

provide the following, NLT

Monday, April 20, 2026

429SCMS.SASPO.Workflow@us.af.mil

-Company, -Address, -Name(s), -Email(s), -Phone,

-Your questions for Engineering, and

-Statement of Capabilities

Supplying Warfighter Dominance



Acronym Legend



AAC – Acquisition Advice Code
AMC – Acquisition Method Code
AMSC – Acquisition Method Suffix Code
APPL – Application Rate
AS – Alternate Source
Asmbly – Assembly
Eng - Engineer
MD – Mission Designation (Aircraft Type)
N/A – Not Applicable
NSN – National Stock Number
OTA – Other Transactional Authority



Acronym Legend



QPA – Quantity Per Assembly

Rep - Repair

Rev Eng – Reverse Engineer

RMC – Repair Method Code

RMSC – Repair Method Suffix Code

TMS – Type, Model and Series (Engines Only)

T.O. – Technical Order

Unserv. Assets Avail – Unserviceable Assets Available