

RFI's For WWYK250088 MAC BOA WWYK250088 ~ Repair Interior Walls, B8400

Q1. Will you be providing updated drawings for all the locations that were identified during the walk, and give an opportunity for trade partners to re-walk the project?

Response: No drawings will be updated. Project documents were provided at a WRC scope level. Project documents were accurate at time of original survey and damage could have occurred since that time. Provide proposals based on project documents. Provide additional proposal for items identified in field that were not shown in the documents. Walk through photos and map are attached.

Lance Luke, PE,SE 72ABW/CEEN (Tepa)

Q2. Have you taken photos of the room we were unable to get into due to security during the walk?

Response: Photos of the secured office are attached.

Lance Luke, PE,SE 72ABW/CEEN (Tepa)

HO.PETER.HAO.1123729591
O.1123729591

Digitally signed by
HO.PETER.HAO.1123729591
Date: 2026.03.09 13:19:38
-05'00'