

Inspection Summary

Customer Information

Name VA Outpatient Clinic

Building Information

Name Veterans Admin Outpatient Clinic

Address 4303 Pittman St, Lawton, OK, 73503

Contact Information

Name Nathaniel Eastham

Role Engineering

E-Mail nathaniel.eastham@va.gov

Phone 4054561755

Account Information

Service Provider Johnson Controls North America

Office Address 2835 S. Utah ave. OKC OK

Office Phone 405-246-1000

Office License 0731

Inspector Name Randy Reece

Inspector License 6392

Inspection Information

Start Date 01/20/2026

Date 01/20/2026

Inspection Type Joint Commission

Work Order# 60694676

Timezone GMT-06:00

Inspection Summary

The following Tests and Inspections have been covered in this inspection

[EP 2-3 - Duct, Heat, Flame, Optical, Smoke Detectors, Pull Stations](#)

[EP 2-4 - Audible and Visual Notification Appliances, and Door Releasing Devices](#)

[EP 2-5 - Supervising Station Fire Alarm Systems — Transmission Equipment](#)

[EP 2-19 - Air Handler Shut Down Annual](#)

[NFPA 72 - 2010](#)

General Inspection Notes

1. Completed the annual fire alarm inspection.
2. Tested audio visual signals with 5 failures. EST 792-7A-600.
3. Two duct detectors failed due to new fire alarm panel doesn't have enough zones to install them. firelite MS-10UD
4. The batteries in the main facp failed.
5. The system is yellow tagged.

CANNOT INSPECT REPORT									
LOCATION	DESCRIPTION	ADDRESS	DEVICE	MAKE	MODEL	BARCODE	DATE OF TEST	TYPE	IMAGES
1st Floor	AHU-3 ROOFTOP	—	AHU Fan Shutdown	—	—	—	01/20/2026	Cannot Inspect	—
Reason cannot inspect: Cannot test due to duct detector trouble.									