

Inspection Summary

Customer Information

Name Veterans Medical Center OKC

Building Information

Name Oklahoma VA Health Care System

Address 921 NE 13th St, Oklahoma City, OK 73104

Contact Information

Name Nate Eastham

Role Electrical Mechanical Supervisor

E-Mail nathaniel.eastham@va.gov

Phone 4056256464

Account Information

Service Provider Johnson Controls North America

Office Address 2835 S. Utah OKC, OK

Office Phone 405-246-1000

Office License 0731/280

Inspector Name Michael Evans

Inspector License 4880

Inspection Information

Start Date 02/25/2026

Date 02/27/2026

Inspection Type Joint Commission

Work Order# 61113850

Timezone GMT-06:00

Inspection Summary

The following Tests and Inspections have been covered in this inspection

[EP 2-2 - Valve Tamper Switches and Water Flow devices](#)

[EP 2-9 - Main Drains](#)

[EP 2-10 - Fire Department Connections](#)

[NFPA 25 - 2011](#)

General Inspection Notes

1. Performed Quarterly Sprinkler Test and Inspection.
Systems are Green Tagged.
Sub basement area at electric fire pump devices were not tested due to asbestos abatement procedures.

DEVICE DEFICIENCIES

No device deficiencies in this inspection.

CANNOT INSPECT REPORT									
LOCATION	DESCRIPTION	ADDRESS	DEVICE	MAKE	MODEL	BARCODE	DATE OF TEST	TYPE	IMAGES
Sub-basement	Bldg. 1 Electric Pump Discharge Check Valve	—	Check Valve	Swing Check	—	—	02/27/2026	Cannot Inspect	—
Reason cannot inspect: Sub-basement area is cordoned off due to asbestos abatement procedures.									
Sub-basement	BLD. 1 FIRE PUMP Suction	—	Control Valve	—	OS&Y	—	02/27/2026	Cannot Inspect	—
Reason cannot inspect: Sub-basement area is cordoned off due to asbestos abatement procedures.									
Sub-basement	BLD. 1 PRIMARY BACK FLOW @ F PUMP Upper	—	Control Valve	—	Butterfly	—	02/27/2026	Cannot Inspect	—
Reason cannot inspect: Sub-basement area is cordoned off due to asbestos abatement procedures.									
Sub-basement	BLD. 1 PRIMARY BACK FLOW @ F PUMP Lower	—	Control Valve	—	Butterfly	—	02/27/2026	Cannot Inspect	—
Reason cannot inspect: Sub-basement area is cordoned off due to asbestos abatement procedures.									
Sub-basement	BLD. 1 SECONDARY BACK FLOW @ F PUMP Lower	—	Control Valve	—	Butterfly	—	02/27/2026	Cannot Inspect	—
Reason cannot inspect: Sub-basement area is cordoned off due to asbestos abatement procedures.									
Sub-basement	BLD. 1 SECONDARY BACK FLOW @ F PUMP Upper	—	Control Valve	—	Butterfly	—	02/27/2026	Cannot Inspect	—
Reason cannot inspect: Sub-basement area is cordoned off due to asbestos abatement procedures.									
Sub-basement	BLD. 1 MECH. ROOM	—	Control Valve	—	Butterfly	—	02/27/2026	Cannot Inspect	—
Reason cannot inspect: Sub-basement area is cordoned off due to asbestos abatement procedures.									
Sub-basement	BLD. 1 MECH. ROOM TO LAUNDRY	—	Control Valve	—	Butterfly	—	02/27/2026	Cannot Inspect	—
Reason cannot inspect: Sub-basement area is cordoned off due to asbestos abatement procedures.									
Sub-basement	BLD. 1 Basement Laundry	—	Control Valve	—	Butterfly	—	02/27/2026	Cannot Inspect	—
Reason cannot inspect: Sub-basement area is cordoned off due to asbestos abatement procedures.									
Sub-basement	BLD. 1 MECH. ROOM @ DOUBLE DOORS	—	Control Valve	—	Butterfly	—	02/27/2026	Cannot Inspect	—
Reason cannot inspect: Sub-basement area is cordoned off due to asbestos abatement procedures.									
Sub-basement	BLD. 1 FIRE PUMP Discharge	—	Control Valve	—	Butterfly	—	02/27/2026	Cannot Inspect	—
Reason cannot inspect: Sub-basement area is cordoned off due to asbestos abatement procedures.									
Sub-basement	Electric Pump City Bypass	—	Control Valve	—	Butterfly	—	02/27/2026	Cannot Inspect	—
Reason cannot inspect: Sub-basement area is cordoned off due to asbestos abatement procedures.									
Sub-basement	Electric Pump Flow Meter Test	—	Control Valve	Butterfly	—	—	02/27/2026	Cannot Inspect	—
Reason cannot inspect: Sub-basement area is cordoned off due to asbestos abatement procedures.									
Sub-basement	Main Riser	—	Water Flow Switch	Paddle	—	—	02/27/2026	Cannot Inspect	—
Reason cannot inspect: Sub-basement area is cordoned off due to asbestos abatement procedures.									

CANNOT INSPECT REPORT									
LOCATION	DESCRIPTION	ADDRESS	DEVICE	MAKE	MODEL	BARCODE	DATE OF TEST	TYPE	IMAGES
Sub-basement	BLD. 1 MECH. ROOM	—	Water Flow Switch	Paddle	VSR	—	02/27/2026	Cannot Inspect	—
Reason cannot inspect: Sub-basement area is cordoned off due to asbestos abatement procedures.									
Sub-basement	BLD. 1 MECH. ROOM TO LAUNDRY	—	Water Flow Switch	Paddle	WFD30	—	02/27/2026	Cannot Inspect	—
Reason cannot inspect: Sub-basement area is cordoned off due to asbestos abatement procedures.									
Sub-basement	MECH. ROOM TO BSMT LAUNDRY	—	Water Flow Switch	Paddle	WFD30	—	02/27/2026	Cannot Inspect	—
Reason cannot inspect: Sub-basement area is cordoned off due to asbestos abatement procedures.									
Sub-basement	ELECTRIC FIRE PUMP SUCTION	—	Tamper Switch	—	OSY2	—	02/27/2026	Cannot Inspect	—
Reason cannot inspect: Sub-basement area is cordoned off due to asbestos abatement procedures.									
Sub-basement	ELECTRIC FIRE PUMP DISCHARGE	—	Tamper Switch	—	PCVS-2	—	02/27/2026	Cannot Inspect	—
Reason cannot inspect: Sub-basement area is cordoned off due to asbestos abatement procedures.									
Sub-basement	Upper Backflow Inlet	—	Tamper Switch	Butterfly	—	—	02/27/2026	Cannot Inspect	—
Reason cannot inspect: Sub-basement area is cordoned off due to asbestos abatement procedures.									
Sub-basement	Upper Backflow Outlet	—	Tamper Switch	Butterfly	—	—	02/27/2026	Cannot Inspect	—
Reason cannot inspect: Sub-basement area is cordoned off due to asbestos abatement procedures.									
Sub-basement	Lower Backflow Inlet	—	Tamper Switch	Butterfly	—	—	02/27/2026	Cannot Inspect	—
Reason cannot inspect: Sub-basement area is cordoned off due to asbestos abatement procedures.									
Sub-basement	Lower Backflow Outlet	—	Tamper Switch	Butterfly	—	—	02/27/2026	Cannot Inspect	—
Reason cannot inspect: Sub-basement area is cordoned off due to asbestos abatement procedures.									
Sub-basement	MECH. ROOM	—	Tamper Switch	Butterfly	—	—	02/27/2026	Cannot Inspect	—
Reason cannot inspect: Sub-basement area is cordoned off due to asbestos abatement procedures.									
Sub-basement	MECH. ROOM TO LAUNDRY	—	Tamper Switch	Butterfly	—	—	02/27/2026	Cannot Inspect	—
Reason cannot inspect: Sub-basement area is cordoned off due to asbestos abatement procedures.									
Sub-basement	MECH. ROOM TO BSMT Laundry	—	Tamper Switch	Butterfly	—	—	02/27/2026	Cannot Inspect	—
Reason cannot inspect: Sub-basement area is cordoned off due to asbestos abatement procedures.									
Sub-basement	MECH. ROOM @ DOUBLE DOORS	—	Tamper Switch	Butterfly	—	—	02/27/2026	Cannot Inspect	—
Reason cannot inspect: Sub-basement area is cordoned off due to asbestos abatement procedures.									