



Mechanical Repairs
Building 113
at the
UNITED STATES MARINE CORPS BASE CAMP
LEJEUNE, NORTH CAROLINA

A/E Contract: N40085-22-D-0005
Task Order No.: N40085-24-F-5940
Constr. Contr. No.: N40085-23-B-0044

Termite Inspection Report

Final Report



317-C Pollock Street | New Bern, NC 28560 | T: 252-637-6373 | F: 252.637.3259
www.mbfarchitects.com

OFFICIAL NORTH CAROLINA WOOD-DESTROYING INSECT INFORMATION REPORT

This is to report that a qualified inspector employed by the below-named firm has carefully inspected readily accessible areas of the property located at the address below for wood-destroying insects. This report specifically excludes hidden areas and areas not readily accessible (see section 2 below) and the undersigned pest control operator has not made any inspection of such hidden areas or of such areas not readily accessible. **This is not a warranty as to the total absence of wood-destroying insects or damage from same.** The inspection described herein was made on the basis of visible evidence. **This report is submitted without warranty, guarantee, or representation as to concealed evidence of infestation or damage or as to any future infestation.**

1.

Seller's Name(s) MBF Architechs

Buyer's Name(s) MBF Architechs

Address of Property Saipan Dr, Building TT113, Jacksonville, NC, 28543

Structure(s) Inspected: A. Main Residence Only X B. Other _____

FINDINGS

2. Areas of the property which are deemed to be obstructed or inaccessible: All areas of floors, walls, wall coverings, and ceilings as well as all insulated areas are obstructed from inspection. All areas of stored items, appliances/furniture attic areas are. Exterior Siding _____

Note: Certain areas of all structures are obstructed or inaccessible (see numbers 2 & 3 on reverse side for conditions governing this report).

If there is evidence of a previous or an active infestation of subterranean termites and/or other wood-destroying insects in the **wooden members**, it must be assumed that there is some damage to the **wooden members** caused by this infestation, no matter how slight. If this is the case, the structural integrity of this property should be evaluated by a qualified building expert. (For the purpose of completing the report "infestation" means evidence of past or present activity by a wood-destroying insect visible in, on, or under a structure, or in or on debris under the structure.)

3. Inspection revealed visible evidence of:

Location of visible evidence of infestation:

- ☐ A. Subterranean termites
- ☐ 1. Control measures were performed.
 - ☐ 2. No control measures were performed.
 - ☐ 3. Visible evidence of a previously treated infestation, which now appears to be inactive.

- ☐ B. Powder post Beetles
- ☐ 1. Control measures were performed.
 - ☐ 2. No control measures were performed.
 - ☐ 3. An infestation which now appears to be inactive

- ☐ C. Old House Borers
- ☐ 1. Control measures were performed.
 - ☐ 2. No control measures were performed.
 - ☐ 3. An infestation which now appears to be inactive


- ☐ D. Others _____
- ☐ 1. Control measures were performed.
 - ☐ 2. No control measures were performed.
 - ☐ 3. An infestation which now appears to be inactive

☒ 4. No visible evidence of infestation from wood-destroying insects was observed.

☐ 5. The following conditions conducive to subterranean termites were noted in this property:

FIRM: Terminix

Address: 420 White Street, Unit 3, Jacksonville, NC, 28546

Signature of Authorized Company Rep. 

Purchaser's signature is required on reverse side.

PCO Lic No. 1079 PW Date 11/11/2024

Telephone: (910) 347-6978

Title: Managers Signature

OVER

CONDITIONS GOVERNING THIS REPORT

1. This report is based on observations and opinions of the inspector. It must be noted that all buildings have some structural wood members which are not visible or accessible for inspection. It is not always possible to determine the presence of infestations without extensive probing and, in some cases, actual dismantling of parts of the structure being inspected. Extensive probing and dismantling have not been performed.
2. This inspection and report are made on the basis of what was visible at the time of the inspection. An opinion is not given on areas that were enclosed or not readily accessible: finished areas of ground level rooms (basement and split level); areas concealed by wall coverings, floor coverings, furniture, equipment, stored articles; or any portion of the structure in which inspection would necessitate tearing out or marring finished work. Furniture, appliances, equipment, insulation, fixed ceilings, etc. were not moved for inspection purposes.
3. Inspection did not include any area to which visible access would require the use of ladders or drills. Such areas are not considered to be readily accessible.
4. Detached garages, sheds, lean-tos, other buildings or fences on the property are not included in this inspection report unless specifically noted.
5. Neither I, nor the company for which I am acting, have had, presently have, or contemplate having any interest in this property. I do further state that neither I nor the company for which I am acting is associated in any way with any party to this transaction.

REMARKS

This space should be used to clarify any statement made above.

The inspection of this property was not an inspection for fungi or mold (other than wood-destroying fungi in the Class Hymenomycetes). This report does not include identification of or control measures or other remediation for visible fungi or mold (other than visible mold-destroying fungi in the Class Hymenomycetes.)

IT IS THE RESPONSIBILITY OF THE CLOSING AGENT TO OBTAIN PROPER SIGNATURES.


Purchaser's Signature(s) _____ Date Acknowledged _____

WDIR 100 As approved by the North Carolina Pest Control Association and Structural Pest Control Committee, North Carolina Department of Agriculture and Consumer Services.

Revised July 1, 1992

TERMINIX INSPECTION GRAPH

Purchaser Name MBF Architects Location # 1032204
 Property Address TT113 Iwo Jima Blvd City Jacksonville State NC Zip 28543-1234
 Square Footage 31,475 Crawl Square Footage 0 Lineal Footage 975 Year Built 12/1/2011
 SCALE: ☐ 1:1 ☒ OTHER 5 : 5
 TYPE OF FOUNDATION: ☒ CONCRETE ☐ HOLLOW BLOCK ☐ BRICK ☐ STONE ☐ OTHER _____
 PROPERTY HAS A: 1. SUMP PUMP ☐ YES ☒ NO 2. FRENCH DRAIN ☐ YES ☒ NO



Note "Hazard" Locations on Graph:

- ☒ Cables – power, telephone, television (CB) ☒ Water Shut-off Valve (WS) ☐ Gas Meter (GM)
☐ Sprinkler System Shut-off Valve (SSP) ☐ Exterior Gas BBQ Grill/Fixture (NGF)

KEY TO EVIDENCE OF:

- | | | |
|---|---|---|
| ☐ EARTH-WOOD CONTACTS = EC | ☐ ACTIVE SUBTERRANEAN TERMITES = X | ☐ INACTIVE SUBTERRANEAN TERMITES = (X) |
| ☐ DIRT FILLED PORCH = DP | ☐ WOOD DECAY FUNGUS = WDF | ☐ EXISTING WOOD DECAY FUNGUS DAMAGE = (WDF) |
| ☐ POSSIBLE HIDDEN DAMAGE = PHD | ☐ POWDER-POST BEETLES = PPB | ☐ EXISTING POWDER-POST BEETLE DAMAGE = (PPB) |
| ☐ PATIO = PA | ☐ WOOD BORING BEETLES = WB | ☐ EXISTING WOOD BORING BEETLE DAMAGE = (WB) |
| ☐ INACCESSIBLE AREAS = IA | ☐ NON DECAY FUNGUS = NDF | ☐ STANDING WATER IN CRAWL SPACE = SW |
| ☐ CELLULOSE DEBRIS = CD | ☐ PROPOSED BAIT LOCATION = B | ☐ TERMITE SWARMERS = S |
| ☐ WELL/CISTERN = W/C | ☐ MOISTURE > 19% = EM | ☐ EXISTING MOISTURE DAMAGE = (EM) |
| ☐ OPEN PORCH = OP | | ☐ EXISTING TERMITE DAMAGE = (TD) |

INSPECTOR'S STATEMENT OF VISIBLE DAMAGE

None

CONTROL TECHNICIAN'S STATEMENT OF VISIBLE DAMAGE

Terminix Rep Signature _____ Date: _____

Termite Tech Signature _____ Date: _____

THE ABOVE GRAPH, AND THE AREAS CONTAINING VISIBLE EVIDENCE OR DAMAGE, HAVE BEEN DESCRIBED TO ME AND ARE AFFIRMED BY ME AS OWNER OR AGENT OF THE ABOVE PROPERTY. I ALSO AFFIRM THAT I UNDERSTAND THAT TERMINIX IS NOT LIABLE FOR HIDDEN DAMAGE WHICH IS CONCEALED, OBSTRUCTED OR INACCESSIBLE TO THE INSPECTOR, AND I AGREE TO THE TERMS AND CONDITIONS GIVEN.

Purchaser Signature: _____ Date: _____

INSPECTION GRAPH

Terms and Conditions

This graph is a record of a visual, non-destructive inspection by Terminix of certain readily accessible visible areas of the identified property for visible termite infestation/damage. Terminix is not responsible for repairs to damages disclosed above. In addition, hidden damage may exist in concealed, obstructed or inaccessible areas. No attempt to remove siding, plastic or sheetrock insulation, carpeting, paneling, etc. to search for hidden damage was made. Terminix cannot guarantee that the damage disclosed by visual inspection of the premises shown above represents the entirety of the damage which may exist as of the date of the initial control application. Terminix shall not be responsible for repair of any existing damage, including without limitation, any damage which existed in areas or in structural members which were not accessible for visual inspection as of the date of this graph. If X (circled or not) appears on the graph, it is advisable that a