

STATEMENT OF WORK

1. Objective/Requirements

NASA Armstrong conducted a borescope inspection of the C-20A left engine, a Rolls Royce Spey Mk. 511-8 engine, serial number 11265, and identified a nick in a Stage 7 high pressure compressor blade. The applicable maintenance manual requires removal from service when damage of this type is detected. A Technical Variance (TV) is being requested to determine whether continued operation is technically supportable.

2. Characteristics, Scope, and Specs

The contractor shall perform the following duties:

- Per quotation OSD 70251, provide a TV for the Left Hand, High Pressure Compressor (HPC) Stage 7 Blade that was found to be nicked. The TV being sought is for return to flight with engine remaining “on aircraft.”

During the borescope inspection, a 0.041 in nick was discovered on a high-pressure compressor stage 7 blade, at the leading edge near the tip (where the leading tip radius meets the LE).

Following this discovery, the damage was photographed (see images below).:





3. Period of Performance

Contract award date by March 10, 2026. Estimated completion of Technical Variance is 3 days.