

ASBESTOS INSPECTION REPORT of:

Building # FC574

MCB CAMP LEJEUNE



Print Date

Thursday, March 19, 2026

INSPECTION SUMMARY

BLDG #: FC574

YEAR BUILT: 1986

OCCUPANT: BEQ

ASBESTOS MANAGER: 910-451-5837

BUILDING COMMENTS:

HAZ RANK 0/BUE [AH SEPT2019]
NO KNOWN ACM ID'D

SEPT2019
NO CHANGES, NO ACM ID'D

JUN2016
MAJOR RENOVATIONS 2014/15, ALL KNOWN ACM REMOVED; ROOFING SYSTEM STRIPPED AND REPLACED

DEC2013
TPM DEBRIS REMOVED/ NOT ID'D, ACM ROOFING MATERIALS REMAIN

SEPT2012
MAJOR RENOVATIONS, ACM ROOFING MATL'S REMAIN, ADDL ACM ID'D INCLUDES:
TRANSITE PANEL MATERIAL DEBRIS

NOV08:
PVS. ACM REMAINS, ADDL ACM INCLUDES:
THRESHOLD MASTIC
ROOFING SEALANTS, GRAY, BLACK

SEPT05:
PVS. ACM REMAINS, NO SAMPLING

INSPECT JUL02 AES
NON FRIABLE ACM INCLUDES:
12" BEIGE FLOOR TILE AND ADHESIVE (VARIOUS TYPES)

NOTIFICATION OF ACM IN BUILDING

NOTICE: The following asbestos-containing materials have been identified in this structure. Refer to survey findings for additional information or contact the Asbestos Program Manager. Please note ACM that is intact and undisturbed is not considered a significant health hazard to building occupants.

Friable ACM(s) identified

<i>DESCRIPTION</i>	<i>LOCATION</i>	<i>Date</i>	<i>Quantity</i>
--------------------	-----------------	-------------	-----------------

No friable ACM records found in database

Non-friable ACM(s) identified

<i>DESCRIPTION</i>	<i>LOCATION</i>	<i>Date</i>	<i>Quantity</i>
--------------------	-----------------	-------------	-----------------

MEMBRANE-TYPE ROOFING	MAIN ROOFING SYSTEM AT PERIMETER FLASHINGS (SEE ALSO HM32, 34, 38)	9/17/2019	800 SF
-----------------------	---	-----------	--------

Tested Non ACM or REMOVED Materials

<i>DESCRIPTION</i>	<i>LOCATION</i>	<i>Date</i>
--------------------	-----------------	-------------

ROOFING SEALANT, BLACK	ROOF VENTS AND PERIMETER FLASHINGS (SEE ALSO HM34, 36, 38)	11/5/2008
TEXTURED CEILING MATERIAL	THROUGHOUT HOMOGENOUS BUILDINGS	9/20/2005
MISCELLANEOUS SEALANT	MECHANICAL ROOMS AND CHASES ON HVAC DUCTS	11/5/2008
DUCT SEALANT, GRAY	MECHANICAL ROOMS AND CHASES ON HVAC DUCTS	11/5/2008
ROOFING MATERIAL,	ROOF SYSTEM EXPANSION JOINT SEAMS	11/5/2008
MEMBRANE-TYPE ROOFING	MAIN ROOFING SYSTEM AT PERIMETER FLASHINGS (SEE ALSO HM32, 34, 38)	11/5/2008
JOINT MATERIAL	WALLS THROUGHOUT	11/5/2008
12" BEIGE FLOOR TILE AND ADHESIVE	THIRD FLOOR LOUNGE	7/18/2002
DUCT SEALANT, RED	MECHANICAL ROOMS, PIPE CHASES	7/18/2002
PITCH POCKET TAR	ROOF CONDUIT PENETRATIONS	11/5/2008
HVAC DUCT INSULATION	DORM ROOMS HVAC HEAT-AC UNITS INTERNAL INSULATION	11/5/2008
FLOOR TILE	PIPE CHASE ENTRANCE	11/5/2008
CONCRETE EXPANSION JOINT MATERIAL	AROUND EXTERIOR DECKING OF HOMOGENOUS BUILDINGS	9/20/2005
EXTERIOR CAULKING,	DOORS TO CHASES THROUGHOUT	9/20/2005
DUCT SEALANT, GRAY	CHASES AND ATTIC/OLD ROOF DUCTS THROUGHOUT HOMOGENOUS BUILDINGS	9/20/2005
MISCELLANEOUS SEALANT	MECHANICAL ROOMS AND CHASES AT CABLE/ PIPE PENETRATIONS	11/5/2008
FIBROUS DEBRIS	THIRD FLOOR NORTH PIPE CHASE	11/5/2008
INTERIOR CAULKING,	DORM ROOMS	11/5/2008
FIBROUS DEBRIS	FIRST FLOOR SOUTH PIPE CHASE	11/5/2008
MISCELLANEOUS FLOOR COVERINGS,	DORM ROOMS	11/5/2008
DUCT SEALANT, BROWN	MECHANICAL ROOMS AND CHASES ON HVAC DUCTS	11/5/2008
ROOFING SEALANT, GRAY	ROOF SYSTEM EXPANSION JOINT SEAMS PATCHING (SEE ALSO HM32, 34, 36)	11/5/2008
CONCRETE EXPANSION JOINT MATERIAL	EXTERIOR BRICK JOINTS	11/5/2008
TEXTURED CEILING MATERIAL	OFFICES AND LIVING QUARTERS THROUGHOUT	7/18/2002
ROOFING SEALANT, BLACK	ROOFING WALK PADS	11/5/2008
VINYL THRESHOLD MATERIAL	CENTER CORRIDORS AT LAUNDRY/ UTILITY	11/5/2008
ROOFING SEALANT, GRAY	ROOF PARAPET WALL PATCHING (SEE ALSO HM32, 36, 38)	11/5/2008
MUDDER FITTING(S)	MECH ROOMS, PIPE CHASES	7/18/2002

CLOTH LAGGING MATERIAL	THROUGHOUT THIS AND HOMOGENOUS BUILDINGS IN CHASE	9/20/2005
TRANSITE PANEL MATERIAL	NORTHWEST EXTERIOR GROUND DEBRIS UNCOVERED DURING RENOVATION EXCAVATIONS; ADDITIONAL DEBRIS MAY BE PRESENT AROUND EXTERIOR	9/5/2012
12" BLACK FLOOR TILE AND ADHESIVE	CENTRAL LOUNGES	7/18/2002
12" WHITE FLOOR TILE AND ADHESIVE	CENTRAL LOUNGES	7/18/2002
12" BEIGE FLOOR TILE AND ADHESIVE	THROUGHOUT OFFICES, LIVING QUARTERS, AND LOUNGES (UNDER OTHER)	7/18/2002
2'x2' CEILING TILE,	OFFICES, LOUNGES	7/18/2002
12" BEIGE FLOOR TILE AND ADHESIVE	SECOND FLOOR LOUNGE (UNDER CARPET/ TILE)	7/18/2002
12" BEIGE FLOOR TILE AND ADHESIVE	THROUGHOUT OFFICES, LIVING QUARTERS, AND LOUNGES (UNDER OTHER)	9/21/2005
12" BEIGE FLOOR TILE AND ADHESIVE	2ND FLOOR LOUNGE (UNDER CARPET/TILE)	11/5/2008
12" BEIGE FLOOR TILE AND ADHESIVE	3RD FLOOR LOUNGE	11/5/2008
12" BEIGE FLOOR TILE AND ADHESIVE	2ND FLOOR LOUNGE (UNDER CARPET/TILE)	9/21/2005
12" BEIGE FLOOR TILE AND ADHESIVE	3RD FLOOR LOUNGE	9/21/2005
12" BEIGE FLOOR TILE AND ADHESIVE	THROUGHOUT OFFICES, LIVING QUARTERS, AND LOUNGES (UNDER OTHER)	11/5/2008
ROOFING SEALANT, GRAY	ROOF SYSTEM EXPANSION JOINT SEAMS PATCHING (SEE ALSO HM32, 34, 36)	12/9/2013
ROOFING SEALANT, BLACK	ROOF VENTS AND PERIMETER FLASHINGS (SEE ALSO HM34, 36, 38)	9/5/2012
ROOFING SEALANT, GRAY	ROOF PARAPET WALL PATCHING (SEE ALSO HM32, 36, 38)	9/5/2012
MEMBRANE-TYPE ROOFING	MAIN ROOFING SYSTEM AT PERIMETER FLASHINGS (SEE ALSO HM32, 34, 38)	9/5/2012
ROOFING SEALANT, BLACK	ROOF VENTS AND PERIMETER FLASHINGS (SEE ALSO HM34, 36, 38)	12/9/2013
ROOFING SEALANT, GRAY	ROOF PARAPET WALL PATCHING (SEE ALSO HM32, 36, 38)	12/9/2013
MEMBRANE-TYPE ROOFING	MAIN ROOFING SYSTEM AT PERIMETER FLASHINGS (SEE ALSO HM32, 34, 38)	12/9/2013
ROOFING SEALANT, GRAY	ROOF SYSTEM EXPANSION JOINT SEAMS PATCHING (SEE ALSO HM32, 34, 36)	9/5/2012

HEALTH ASPECTS: ACM only presents a health hazard when asbestos fibers are airborne and inhaled. Avoid disturbance which will release fibers. The presence of asbestos does not constitute a health hazard.

- CONDITIONS TO AVOID:** Do not disturb or cause damage to ACM. Do not sand, grind or abrade materials or cause damage with any type of equipment.
- REPORTS OF DAMAGE:** Report any damage, dust or debris that may come from ACM or suspect ACM, or any change in the condition of materials, or accidental disturbance to the Asbestos Program Manager.
- RESPONSE ACTION:** Corrective action initiated to minimize fiber release and protect personnel.
- INSPECTION:** ACM will be inspected periodically to evaluate any changes in condition.
- RECORDKEEPING:** The Camp Lejeune Asbestos Program Manager maintains a copy of the survey for the building.

CAMP LEJEUNE Asbestos Program Manager:

Phone: (910) 451-5837

SAMPLES COLLECTED

Sample	HA	Description	Sample Date	Sample Location	Chr (%)	Amo (%)	Oth (%)
FC574-01-01	01	12" BLACK FLOOR TILE AND ADHESIVE	7/18/2002	1ST FL LOUNGE	0	0	0
FC574-01-02	01	12" BLACK FLOOR TILE AND ADHESIVE	7/18/2002	1ST FL LOUNGE	0	0	0
FC574-02-03	02	12" WHITE FLOOR TILE AND ADHESIVE	7/18/2002	1ST FL LOUNGE	0	0	0
FC574-02-04	02	12" WHITE FLOOR TILE AND ADHESIVE	7/18/2002	1ST FL LOUNGE	0	0	0
FC574-03-00ri05	03	12" BEIGE FLOOR TILE AND ADHESIVE TYPE I	9/21/2005	N/A	9	9	9
FC574-03-00ri07	03	12" BEIGE FLOOR TILE AND ADHESIVE TYPE I	11/5/2008	N/A	9	9	9
FC574-03-05	03	12" BEIGE FLOOR TILE AND ADHESIVE TYPE I	7/18/2002	1ST FL LOUNGE	8	0	0
FC574-03-06	03	12" BEIGE FLOOR TILE AND ADHESIVE TYPE I	7/18/2002	1ST FL LOUNGE	8	0	0
FC574-04-07	04	2'x2' CEILING TILE,	7/18/2002	1ST FL LOUNGE	0	0	0
FC574-04-08	04	2'x2' CEILING TILE,	7/18/2002	1ST FL LOUNGE	0	0	0
FC574-05-00ri05	05	12" BEIGE FLOOR TILE AND ADHESIVE TYPE II	9/21/2005	N/A	9	9	9
FC574-05-00ri07	05	12" BEIGE FLOOR TILE AND ADHESIVE TYPE II	11/5/2008	N/A	9	9	9
FC574-05-09	05	12" BEIGE FLOOR TILE AND ADHESIVE TYPE II	7/18/2002	2ND FL LOUNGE (UNDER CARPET)	10	0	0
FC574-06-00ri05	06	12" BEIGE FLOOR TILE AND ADHESIVE TYPE III	9/21/2005	N/A	9	9	9
FC574-06-00ri07	06	12" BEIGE FLOOR TILE AND ADHESIVE TYPE III	11/5/2008	N/A	9	9	9
FC574-06-10	06	12" BEIGE FLOOR TILE AND ADHESIVE TYPE III	7/18/2002	3RD FL LOUNGE	10	0	0
FC574-07-11	07	DUCT SEALANT, RED	7/18/2002	1ST FL MR	0	0	0
FC574-08-12	08	MUDDERED FITTING(S)	7/18/2002	1ST FL MR	0	0	0
FC574-08-13	08	MUDDERED FITTING(S)	7/18/2002	3RD FL MR	0	0	0

Sample	HA	Description		Sample Date	Sample Location	Chr (%)	Amo (%)	Oth (%)
FC574-09-14	09	TEXTURED CEILING MATERIAL		7/18/2002	1ST FL OFFICE	0	0	0
FC574-09-15	09	TEXTURED CEILING MATERIAL		7/18/2002	1ST FL OFFICE	0	0	0
FC574-10-10	10	CLOTH LAGGING MATERIAL	BLUE/ WHITE RUBBERY	9/20/2005	1ST FLOOR TOILET	0	0	0
FC574-11-10	11	EXTERIOR CAULKING,	GRAY	9/20/2005	SW RESTROOM WALL	0	0	0
FC574-12-10	12	DUCT SEALANT,	GRAY	9/20/2005	PIPE CHASE	0	0	0
FC574-13-10	13	TEXTURED CEILING MATERIAL		9/20/2005	1ST FL OFFICE	0	0	0
FC574-14-10	14	CONCRETE EXPANSION JOINT MATERIAL	GRAY	9/20/2005	1ST FL CENTER OFFICE	0	0	0
FC574-20-20	20	FLOOR TILE	BLACK	11/5/2008	1ST FL NORTH CHASE	0	0	0
FC574-21-20	21	INTERIOR CAULKING,	WHITE	11/5/2008	1ST FL NORTH WING, SW ROOM	0	0	0
FC574-21-21	21	INTERIOR CAULKING,	WHITE	11/5/2008	1ST FL SOUTH WING, CNTR ROOM	0	0	0
FC574-21-22	21	INTERIOR CAULKING,	WHITE	11/5/2008	1ST FL NORTH WING, NE ROOM	0	0	0
FC574-22-20	22	FIBROUS DEBRIS		11/5/2008	1ST FL SOUTH CHASE	0	0	0
FC574-23-20	23	MISCELLANEOUS FLOOR COVERINGS,	BROWN w/ADHESIVE	11/5/2008	1ST FLOOR	0	0	0
FC574-24-20	24	JOINT MATERIAL		11/5/2008	1ST FL CNTR OFFICES	0	0	0
FC574-24-21	24	JOINT MATERIAL		11/5/2008	1ST FL SE ROOM	0	0	0
FC574-24-22	24	JOINT MATERIAL		11/5/2008	1ST FL NE ROOM	0	0	0
FC574-24-23	24	JOINT MATERIAL		11/5/2008	2ND FL NW ROOM	0	0	0
FC574-24-24	24	JOINT MATERIAL		11/5/2008	2ND FL SW ROOM	0	0	0
FC574-24-25	24	JOINT MATERIAL		11/5/2008	2ND FL SE ROOM	0	0	0
FC574-24-26	24	JOINT MATERIAL		11/5/2008	3RD FL CNTR OFFICE	0	0	0
FC574-24-27	24	JOINT MATERIAL		11/5/2008	3RD FL NW ROOM	0	0	0
FC574-24-28	24	JOINT MATERIAL		11/5/2008	3RD FL SE ROOM	0	0	0

Sample	HA	Description		Sample Date	Sample Location	Chr (%)	Amo (%)	Oth (%)
FC574-25-20	25	DUCT SEALANT, BROWN		11/5/2008	1ST FL SOUTH MR	0	0	0
FC574-25-21	25	DUCT SEALANT, BROWN		11/5/2008	2ND FL NORTH MR	0	0	0
FC574-26-20	26	MISCELLANEOUS SEALANT	WHITE	11/5/2008	1ST FL SOUTH MR	0	0	0
FC574-26-21	26	MISCELLANEOUS SEALANT	WHITE	11/5/2008	2ND FL NORTH MR	0	0	0
FC574-27-20	27	DUCT SEALANT, GRAY		11/5/2008	1ST FL SW MR	0	0	0
FC574-28-20	28	HVAC DUCT INSULATION	INTERNAL	11/5/2008	1ST FL SE ROOM	0	0	0
FC574-29-20	29	VINYL THRESHOLD MATERIAL	BROWN	11/5/2008	2ND FL UTILITY	2	0	0
FC574-30-20	30	MISCELLANEOUS SEALANT	GRAY	11/5/2008	3RD FL NORTH MR	0	0	0
FC574-31-20	31	FIBROUS DEBRIS		11/5/2008	3RD FL NORTH CHASE, SOUTH	0	0	0
FC574-32-00ri12	32	ROOFING SEALANT, BLACK	METAL VENTS	9/5/2012	N/A	9	9	9
FC574-32-00ri13	32	ROOFING SEALANT, BLACK	METAL VENTS	12/9/2013	N/A	9	9	9
FC574-32-20	32	ROOFING SEALANT, BLACK	METAL VENTS	11/5/2008	NORTH STAIR ROOF PERIMETER	0	0	0
FC574-32-21	32	ROOFING SEALANT, BLACK	METAL VENTS	11/5/2008	CENTER ROOF VENT	6	0	0
FC574-33-20	33	ROOFING SEALANT, BLACK		11/5/2008	SOUTH CENTER PAD	0	0	0
FC574-34-00ri12	34	ROOFING SEALANT, GRAY		9/5/2012	N/A	9	9	9
FC574-34-00ri13	34	ROOFING SEALANT, GRAY		12/9/2013	N/A	9	9	9
FC574-34-20	34	ROOFING SEALANT, GRAY		11/5/2008	NW PARAPET, CNTR	4	0	0
FC574-35-20	35	PITCH POCKET TAR		11/5/2008	FLAT ROOF,NORTH	0	0	0
FC574-36-00ri12	36	MEMBRANE-TYPE ROOFING	BLACK	9/5/2012	N/A	9	9	9
FC574-36-00ri13	36	MEMBRANE-TYPE ROOFING	BLACK	12/9/2013	N/A	9	9	9

Sample	HA	Description		Sample Date	Sample Location	Chr (%)	Amo (%)	Oth (%)
FC574-36-20	36	MEMBRANE-TYPE ROOFING	BLACK	11/5/2008	SOUTH STAIR ROOF	0	0	0
FC574-36-21	36	MEMBRANE-TYPE ROOFING	BLACK	11/5/2008	WEST CENTER ROOF	2	0	0
FC574-36-40	36	MEMBRANE-TYPE ROOFING	BLACK	9/17/2019	ATTIC, SOUTH CNTR	0	0	0
FC574-37-20	37	ROOFING MATERIAL,	BLACK	11/5/2008	ROOF EAST CENTER	0	0	0
FC574-38-00ri12	38	ROOFING SEALANT, GRAY		9/5/2012	N/A	9	9	9
FC574-38-00ri13	38	ROOFING SEALANT, GRAY		12/9/2013	N/A	9	9	9
FC574-38-20	38	ROOFING SEALANT, GRAY		11/5/2008	ROOF EAST CENTER	10	0	0
FC574-39-20	39	CONCRETE EXPANSION JOINT MATERIAL	GRAY	11/5/2008	3RD FL WEST CNTR	0	0	0
FC574-40-00ri12	40	TRANSITE PANEL MATERIAL	GRAY	9/5/2012	N/A	9	9	9