

N6264926RL004 A0008

SPECIFICATION ITEM NO.: 634-21-001

PARA. NO.: 3.8/

TITLE: Flight Deck Nonskid; replace

QUESTION:

Please see concerns by one of the QP1 vendors, for your reference.

1. Our coating inspector are certified to AMPP Basic Coatings Inspector (BCI). They do not have minimum 2 years of marine coating experience however they have had vast experience with servicing Process Industry for clients (plant owners) like ExxonMobil, Aster Chemicals (FKA Shell), Advario, Tankstore and Singapore LNG. Please clarify if this is acceptable?

No, the requirements for QP-1 have to be met.

2. Our manpower (Spray Painters & Blasters) is not yet been certified to SSPC C-12, SSPC C-14, SSPC C-7, SSPC C-13. Ours is certified AMPP AS 3 ITO (Independent Training Organization) and conducts inhouse training for our manpower based on AMPP AS 3 standards. Our Trainer is certified to SSPC C-12 and AMPP Certified Coatings Inspector (CCI). Please clarify if this is acceptable?

3. We assume that GFM includes provisions of wastage as required for the application?

All GFM paint includes wastage as needed.

ANSWER: See above responses.

SPECIFICATION ITEM NO.: 456-00-001

PARA. NO.:

TITLE: RADOME AN/SPS-77(V) 3 Service Platform and Support Structure Repair and Preservation; accomplish

QUESTION:

Please provide the stated references 2.1~2.14.

ANSWER:

2.1 can be found online

2.2 has been sent out before

2.3 can be found online

2.4 has been sent out before

2.5 has been sent out before
2.6 attached in email
2.7 attached in email
2.8 attached in email
2.9 attached in email
2.10 attached in email
2.11 which one?
2.12 <https://www.ampp.org/standards/ampp-standards/about-ampp-standards>
2.13 attached in email
2.14 attached in email

SPECIFICATION ITEM NO.: 150-11-004 PARA. NO.: 1.1/3.6

TITLE: FORWARD PORT AND STBD CATWALK LADDER REPAIR AND PRESERVATION; ACCOMPLISH

QUESTION:

Please advise if the welding repairs can be covered with contract change, for our reference.

ANSWER: Welding is covered in this work item not sure what you're asking.

SPECIFICATION ITEM NO.: 441-11-001 PARA. NO.: 1.3

TITLE: A9 VHF Antenna Foundation Preservation; accomplish

QUESTION:

If possible, please provide the area for our reference.

ANSWER: Should be in the drawing 801-8494508

SPECIFICATION ITEM NO.: 441-11-003 PARA. NO.: 1.3

TITLE: GPS Antenna Foundation Preservation; accomplish

QUESTION:

If possible, please provide the area for our reference.

ANSWER: Should be in the drawing 801-8494508

SPECIFICATION ITEM NO.: 167-11-002

PARA. NO.: 3.4/5.0

TITLE: QUICK ACTING WATERTIGHT DOOR; REPAIR AND PRESERVE

QUESTION:

Please reconfirm that the new door will be provided as GFM including all materials/fittings to properly install the new door.

ANSWER: The door is being replaced in 167-11-001 not 167-11-002. The Door for 167-11-001 is on order.

SPECIFICATION ITEM NO.: 441-11-002

PARA. NO.: 1.3

TITLE: A8 Port VHF Antenna Foundation Preservation; accomplish

QUESTION:

If possible, please provide the area for our reference.

ANSWER: Should be in the drawing 801-8494508

SPECIFICATION ITEM NO.: 572-12-001

PARA. NO.: 1.2/3.1/4.6

TITLE: Truck, Pallet Electric Equipment Inspect and Weight Test; accomplish

QUESTION:

Please be advised that we have checked the website provided in Paragraph 4.6; however, there is no available facility in our country. We have previously carried out this work on the same vessel using one of our local vendors, who is a JLG-certified technician onboard.

Kindly confirm if this is acceptable.

ANSWER: You need to submit your plan of where and how you are going to complete the work like you did last time.