

Synopsis

1. Estimated issue date: 5/15/25, Estimated closing date: 6/15/25 5:00pm CST
2. RFP: FA8122-26-R-0003
3. PR: FD20302402262
4. Nomenclature/Noun: F108 Outer Nozzle Support Repair
5. NSN: 2840-01-453-9312PN and 2840-01-187-3054PN
6. PN:141M82P01/P02/P03, 9523M63G02, 1784M72P01, 1523M812P01, 1523M88G01, 1784M78G01, and 9999M78P06/P10
7. Application (Engine or Aircraft): F108 Engine/KC-135
8. AMC/AMSC: R1/C
9. History: Last buy: FA8122-21-D-0006 – 3/31/2021
10. Description: Outer support of HPT Nozzle assembly is mounted in the Combustion case. Carries portion of axial load through the HPT nozzle.

A five-year, fixed price, commercial, requirements type contract is contemplated, with a base year and four one-year option periods. Please refer to Appendix I for CLIN breakdown.

Year Estimated Dates and Quantities

Year	Estimated Dates	CLIN X001 (BEQ)	CLIN X002 (BEQ)
Base Year	31 Aug 2026 – 30 Aug 2027	75	5
Option Year I	31 Aug 2027 – 30 Aug 2028	75	5
Option Year II	31 Aug 2028 – 30 Aug 2029	75	5
Option Year III	31 Aug 2029 – 30 Aug 2030	75	5
Option Year IV	31 Aug 2030 – 30 Aug 2031	75	5
6-Month Ext (if necessary)	31 Aug 2031 – 02 Mar 2032	37	2
Total	31 Aug 2026 – 02 Mar 2032	412	27

Required Delivery: 7 EA every 30 calendar days. Early delivery is acceptable.

This is a competitive acquisition to qualified sources.

11. Mandatory Language: N/A

12. Export Control: N/A

13. Buyer:	Brock May 405-739-5462 brock.may@us.af.mil	Contracting Officer:	Brad Bonsall 405-582-5732 bradley.bonsall@us.af.mil
------------	--	----------------------	---

ALL SYNOPSES:

An Ombudsman has been appointed to hear concerns from offerors or potential offerors during the proposal development phase of this acquisition. The purpose of the Ombudsman is not to diminish the authority of the program director or contracting officer, but to communicate contractor concerns, issues, disagreements, and recommendations to the appropriate government personnel. When requested, the Ombudsman will maintain strict confidentiality as to source of the concern. The Ombudsman does not participate in the evaluation of proposals or in the source selection process. Interested parties are invited to call the Ombudsman at 405-736- 3273. **DO NOT CALL THIS NUMBER FOR SOLICITATION REQUESTS.**

Appendix I

Breakdown of CLIN Structure

CLIN	Description
0001 - 4001	Flange Repair
0002 - 4002	Flange Replacement
0003 - 4003	Over and Above
0004 - 4004	DATA