

ASBESTOS INSPECTION REPORT of:

Building # HP53

MCB CAMP LEJEUNE



Print Date

Tuesday, November 4, 2025

INSPECTION SUMMARY

BLDG #: HP53

YEAR BUILT: 1976

OCCUPANT: BEQ

ASBESTOS MANAGER: 910-451-5837

BUILDING COMMENTS:

HP53 HAZARD RANKING 0/ BLUE; NO ACM IDENTIFIED [AH MAR06]

ASBESTOS WAS NOT IDENTIFIED DURING THE INITIAL ASBESTOS INSPECTION.NO FURTHER ACTION REQUIRED

NOTIFICATION OF ACM IN BUILDING

NOTICE: The following asbestos-containing materials have been identified in this structure. Refer to survey findings for additional information or contact the Asbestos Program Manager. Please note ACM that is intact and undisturbed is not considered a significant health hazard to building occupants.

Friable ACM(s) identified

DESCRIPTION	LOCATION	Date	Quantity
No friable ACM records found in database			

Non-friable ACM(s) identified

DESCRIPTION	LOCATION	Date	Quantity
No non friable ACM records found in database			

Tested Non ACM or REMOVED Materials

DESCRIPTION	LOCATION	Date
EXTERIOR SURFACING MATERIAL, STUCCO	EXTERIOR	3/29/2006
TEXTURED CEILING MATERIAL	DORM ROOMS/OFFICES	3/29/2006
MISCELLANEOUS SEALANT	THROUGHOUT	3/29/2006
PLASTER CEILING	HALLWAYS	3/29/2006
WINDOW CAULKING	EXTERIOR	3/29/2006
DUCT SEALANT, RED	MECHANICAL ROOM	3/29/2006
DRYWALL	DORM ROOMS	3/29/2006
12" TAN FLOOR TILE AND ADHESIVE	DORM ROOMS	3/29/2006
BASE COVE/MASTIC,	DORM ROOMS	3/29/2006
2'x2' CEILING TILE,	OFFICES/LOUNGES	3/29/2006
12" WHITE FLOOR TILE AND ADHESIVE	LOUNGES	3/29/2006
ROOFING MATERIAL,	ATTIC	3/29/2006
MISCELLANEOUS SEALANT	MECHANICAL ROOM	3/29/2006

HEALTH ASPECTS:	ACM only presents a health hazard when asbestos fibers are airborne and inhaled. Avoid disturbance which will release fibers. The presence of asbestos does not constitute a health hazard.
CONDITIONS TO AVOID:	Do not disturb or cause damage to ACM. Do not sand, grind or abrade materials or cause damage with any type of equipment.
REPORTS OF DAMAGE:	Report any damage, dust or debris that may come from ACM or suspect ACM, or any change in the condition of materials, or accidental disturbance to the Asbestos Program Manager.
RESPONSE ACTION:	Corrective action initiated to minimize fiber release and protect personnel.
INSPECTION:	ACM will be inspected periodically to evaluate any changes in condition.
RECORDKEEPING:	The Camp Lejeune Asbestos Program Manager maintains a copy of the survey for the building.

CAMP LEJEUNE Asbestos Program Manager:

Phone: (910) 451-5837

SAMPLES COLLECTED

Sample	HA	Description	Sample Date	Sample Location	Chr (%)	Amo (%)	Oth (%)
HP53-01-01	01	TEXTURED CEILING MATERIAL	3/29/2006	ROOM 109	0	0	0
HP53-01-02	01	TEXTURED CEILING MATERIAL	3/29/2006	ROOM 110	0	0	0
HP53-01-03	01	TEXTURED CEILING MATERIAL	3/29/2006	ROOM 219	0	0	0
HP53-01-04	01	TEXTURED CEILING MATERIAL	3/29/2006	ROOM 218	0	0	0
HP53-01-05	01	TEXTURED CEILING MATERIAL	3/29/2006	ROOM 319	0	0	0
HP53-01-06	01	TEXTURED CEILING MATERIAL	3/29/2006	ROOM 318	0	0	0
HP53-01-07	01	TEXTURED CEILING MATERIAL	3/29/2006	ALPHA COMPANY	0	0	0
HP53-02-01	02	DRYWALL	3/29/2006	ROOM 109	0	0	0
HP53-02-02	02	DRYWALL	3/29/2006	ROOM 110	0	0	0
HP53-02-03	02	DRYWALL	3/29/2006	ROOM 219	0	0	0
HP53-02-04	02	DRYWALL	3/29/2006	ROOM 218	0	0	0
HP53-02-05	02	DRYWALL	3/29/2006	ROOM 319	0	0	0
HP53-03-01	03	12" TAN FLOOR TILE AND ADHESIVE	3/29/2006	ROOM 109	0	0	0
HP53-03-02	03	12" TAN FLOOR TILE AND ADHESIVE	3/29/2006	ROOM 219	0	0	0
HP53-04-01	04	BASE COVE/MASTIC,	3/29/2006	ROOM 110	0	0	0
HP53-04-02	04	BASE COVE/MASTIC,	3/29/2006	ROOM 219	0	0	0
HP53-05-01	05	2'x2' CEILING TILE,	3/29/2006	ALPHA COMPANY	0	0	0
HP53-05-02	05	2'x2' CEILING TILE,	3/29/2006	ALPHA COMPANY	0	0	0
HP53-05-03	05	2'x2' CEILING TILE,	3/29/2006	1ST FLOOR	0	0	0
HP53-06-01	06	12" WHITE FLOOR TILE AND ADHESIVE W/BROWN	3/29/2006	1ST FLOOR	0	0	0

Sample	HA	Description		Sample Date	Sample Location	Chr (%)	Amo (%)	Oth (%)
HP53-06-02	06	12" WHITE FLOOR TILE AND ADHESIVE	W/BROWN	3/29/2006	1ST FLOOR	0	0	0
HP53-07-01	07	ROOFING MATERIAL,		3/29/2006	ATTIC	0	0	0
HP53-07-02	07	ROOFING MATERIAL,		3/29/2006	ATTIC	0	0	0
HP53-08-01	08	MISCELLANEOUS SEALANT	GRAY	3/29/2006	1ST FLOOR	0	0	0
HP53-08-02	08	MISCELLANEOUS SEALANT	GRAY	3/29/2006	3RD FLOOR	0	0	0
HP53-08-03	08	MISCELLANEOUS SEALANT	GRAY	3/29/2006	3RD FLOOR	0	0	0
HP53-09-01	09	PLASTER CEILING		3/29/2006	1ST FLOOR	0	0	0
HP53-09-02	09	PLASTER CEILING		3/29/2006	2ND FLOOR	0	0	0
HP53-09-03	09	PLASTER CEILING		3/29/2006	3RD FLOOR	0	0	0
HP53-10-01	10	WINDOW CAULKING		3/29/2006	EXTERIOR	0	0	0
HP53-10-02	10	WINDOW CAULKING		3/29/2006	EXTERIOR	0	0	0
HP53-11-01	11	DUCT SEALANT, RED		3/29/2006	1ST FLOOR	0	0	0
HP53-11-02	11	DUCT SEALANT, RED		3/29/2006	2ND FLOOR	0	0	0
HP53-12-01	12	MISCELLANEOUS SEALANT		3/29/2006	1ST FLOOR	0	0	0
HP53-12-02	12	MISCELLANEOUS SEALANT		3/29/2006	1ST FLOOR	0	0	0
HP53-13-01	13	EXTERIOR SURFACING MATERIAL, STUCCO		3/29/2006	3RD FLOOR	0	0	0
HP53-13-02	13	EXTERIOR SURFACING MATERIAL, STUCCO		3/29/2006	3RD FLOOR	0	0	0