

Pre-award Synopsis: Sole Source – Kearfott Corporation (CAGE: 88818)

1. **Solicitation will be issued on or about:** 01 April 2026 and **closes** 30 April 2026
2. **Solicitation number:** FA8117-26-R-0026
3. **Purchase Request number:** FD2030-25-01609
4. **Nomenclature/Noun:** Repair of the B-2 Attitude Motion Sensor Set (AMSS) and Inertial Measurement Unit (IMU)
5. Input NSN: 6605-01-380-3681 / Input PN: K160A081-30
 Output NSN: 6605-01-380-3681 / Output PN: K160A081-30
 Input NSN: 6605-01-259-7094 / Input PN: K160A081-20
 Output NSN: 6605-01-259-7094 / Input PN: K160A081-20
 Input NSN: 6610-01-384-7512 / Input PN: K150A022-52
 Output NSN: 6610-01-384-7512 / Output PN: K150A022-52
6. **Application:** See PWS
Description: The Contractor is responsible for having the repair capabilities to include appropriate technical data repair documents, and license agreements, required to accomplish this Repair of the B-2 Attitude Motion Sensor Set (AMSS) and Inertial Measurement Unit (IMU) and the below NSNs. The Contractor is responsible for the scheduled delivery of a quality serviceable product. Please read PWS for contractor responsibility.

Purchase Request (CLIN Structure for Contract)					
Year	NOUN	NSN	CLIN	Qty	U/I
Base	IMU Repair Level 1 – 3681	6605-01-380-3681	0001	3	EA
Base	IMU Repair Level 2 - 3681	6605-01-380-3681	0002	1	EA
Base	IMU Repair Level 3 - 3681	6605-01-380-3681	0003	1	EA
Base	IMU No Fault Found (NFF) - 3681	6605-01-380-3681	0004	1	EA
Base	IMU Repair Level 1 – 7094	6605-01-259-7094	0005	1	EA
Base	IMU Repair Level 2 - 7094	6605-01-259-7094	0006	1	EA
Base	IMU Repair Level 3 - 7094	6605-01-259-7094	0007	1	EA
Base	IMU No Fault Found (NFF) - 7094	6605-01-259-7094	0008	1	EA
Base	AMSS Retrofit – 7512	6610-01-384-7512	0009	1	EA
Base	AMSS Major Repair Level 1 – 7512	6610-01-384-7512	0010	10	EA
Base	AMSS Medium Repair Level 2 – 7512	6610-01-384-7512	0011	1	EA
Base	AMSS Minor Repair Level 3 – 7512	6610-01-384-7512	0012	1	EA
Base	AMSS No Fault Found (NFF) - 7512	6610-01-384-7512	0013	1	EA
Base	AMSS Material Lay-In (Gyros) - 7512	6610-01-384-7512	0014	25	EA
Base	AMSS Material Lay-In (HVPS) – 7512	6610-01-384-7512	0015	5	EA
Base	AMSS Material Lay-In (Triad Cables) - 7512	6610-01-384-7512	0016	1	EA
Base	AMSS Material Lay-In (Isolators) – 7512	6610-01-384-7512	0017	15	EA
Base	AMSS Material Lay-In (Accelerometer) - 7512	6610-01-384-7512	0018	1	EA
Base	Over & Above (O&A)		0019	1	TBN
Base	Over & Above (O&A) – Surge Expedite Fee		0020	1	TBN
Base	Data		0021	1	NSP
OYI	IMU Repair Level 1 – 3681	6605-01-380-3681	1001	3	EA
OYI	IMU Repair Level 2 - 3681	6605-01-380-3681	1002	1	EA

OYI	IMU Repair Level 3 - 3681	6605-01-380-3681	1003	1	EA
OYI	IMU No Fault Found (NFF) - 3681	6605-01-380-3681	1004	1	EA
OYI	IMU Repair Level 1 – 7094	6605-01-259-7094	1005	1	EA
OYI	IMU Repair Level 2 - 7094	6605-01-259-7094	1006	1	EA
OYI	IMU Repair Level 3 - 7094	6605-01-259-7094	1007	1	EA
OYI	IMU No Fault Found (NFF) - 7094	6605-01-259-7094	1008	1	EA
OYI	AMSS Retrofit – 7512	6610-01-384-7512	1009	1	EA
OYI	AMSS Major Repair Level 1 – 7512	6610-01-384-7512	1010	10	EA
OYI	AMSS Medium Repair Level 2 – 7512	6610-01-384-7512	1011	1	EA
OYI	AMSS Minor Repair Level 3 – 7512	6610-01-384-7512	1012	1	EA
OYI	AMSS No Fault Found (NFF) - 7512	6610-01-384-7512	1013	1	EA
OYI	AMSS Material Lay-In (Gyros) - 7512	6610-01-384-7512	1014	25	EA
OYI	AMSS Material Lay-In (HVPS) – 7512	6610-01-384-7512	1015	5	EA
OYI	AMSS Material Lay-In (Triad Cables) - 7512	6610-01-384-7512	1016	1	EA
OYI	AMSS Material Lay-In (Isolators) – 7512	6610-01-384-7512	1017	15	EA
OYI	AMSS Material Lay-In (Accelerometer) - 7512	6610-01-384-7512	1018	1	EA
OYI	Over & Above (O&A)		1019	1	TBN
OYI	Over & Above (O&A) – Surge Expedite Fee		1020	1	TBN
OYI	Data		1021	1	NSP
OYII	IMU Repair Level 1 – 3681	6605-01-380-3681	2001	3	EA
OYII	IMU Repair Level 2 - 3681	6605-01-380-3681	2002	1	EA
OYII	IMU Repair Level 3 - 3681	6605-01-380-3681	2003	1	EA
OYII	IMU No Fault Found (NFF) - 3681	6605-01-380-3681	2004	1	EA
OYII	IMU Repair Level 1 – 7094	6605-01-259-7094	2005	1	EA
OYII	IMU Repair Level 2 - 7094	6605-01-259-7094	2006	1	EA
OYII	IMU Repair Level 3 - 7094	6605-01-259-7094	2007	1	EA
OYII	IMU No Fault Found (NFF) - 7094	6605-01-259-7094	2008	1	EA
OYII	AMSS Retrofit – 7512	6610-01-384-7512	2009	1	EA
OYII	AMSS Major Repair Level 1 – 7512	6610-01-384-7512	2010	10	EA
OYII	AMSS Medium Repair Level 2 – 7512	6610-01-384-7512	2011	1	EA
OYII	AMSS Minor Repair Level 3 – 7512	6610-01-384-7512	2012	1	EA
OYII	AMSS No Fault Found (NFF) - 7512	6610-01-384-7512	2013	1	EA
OYII	AMSS Material Lay-In (Gyros) - 7512	6610-01-384-7512	2014	25	EA
OYII	AMSS Material Lay-In (HVPS) – 7512	6610-01-384-7512	2015	5	EA
OYII	AMSS Material Lay-In (Triad Cables) - 7512	6610-01-384-7512	2016	1	EA
OYII	AMSS Material Lay-In (Isolators) – 7512	6610-01-384-7512	2017	15	EA
OYII	AMSS Material Lay-In (Accelerometer) - 7512	6610-01-384-7512	2018	1	EA
OYII	Over & Above (O&A)		2019	1	TBN
OYII	Over & Above (O&A) – Surge Expedite Fee		2020	1	TBN
OYII	Data		2021	1	NSP

OYIII	IMU Repair Level 1 – 3681	6605-01-380-3681	3001	3	EA
OYIII	IMU Repair Level 2 - 3681	6605-01-380-3681	3002	1	EA
OYIII	IMU Repair Level 3 - 3681	6605-01-380-3681	3003	1	EA
OYIII	IMU No Fault Found (NFF) - 3681	6605-01-380-3681	3004	1	EA
OYIII	IMU Repair Level 1 – 7094	6605-01-259-7094	3005	1	EA
OYIII	IMU Repair Level 2 - 7094	6605-01-259-7094	3006	1	EA
OYIII	IMU Repair Level 3 - 7094	6605-01-259-7094	3007	1	EA
OYIII	IMU No Fault Found (NFF) - 7094	6605-01-259-7094	3008	1	EA
OYIII	AMSS Retrofit – 7512	6610-01-384-7512	3009	1	EA
OYIII	AMSS Major Repair Level 1 – 7512	6610-01-384-7512	3010	10	EA
OYIII	AMSS Medium Repair Level 2 – 7512	6610-01-384-7512	3011	1	EA
OYIII	AMSS Minor Repair Level 3 – 7512	6610-01-384-7512	3012	1	EA
OYIII	AMSS No Fault Found (NFF) - 7512	6610-01-384-7512	3013	1	EA
OYIII	AMSS Material Lay-In (Gyros) - 7512	6610-01-384-7512	3014	25	EA
OYIII	AMSS Material Lay-In (HVPS) – 7512	6610-01-384-7512	3015	5	EA
OYIII	AMSS Material Lay-In (Triad Cables) - 7512	6610-01-384-7512	3016	1	EA
OYIII	AMSS Material Lay-In (Isolators) – 7512	6610-01-384-7512	3017	15	EA
OYIII	AMSS Material Lay-In (Accelerometer) - 7512	6610-01-384-7512	3018	1	EA
OYIII	Over & Above (O&A)		3019	1	TBN
OYIII	Over & Above (O&A) – Surge Expedite Fee		3020	1	TBN
OYIII	Data		3021	1	NSP
OYIV	IMU Repair Level 1 – 3681	6605-01-380-3681	4001	3	EA
OYIV	IMU Repair Level 2 - 3681	6605-01-380-3681	4002	1	EA
OYIV	IMU Repair Level 3 - 3681	6605-01-380-3681	4003	1	EA
OYIV	IMU No Fault Found (NFF) - 3681	6605-01-380-3681	4004	1	EA
OYIV	IMU Repair Level 1 – 7094	6605-01-259-7094	4005	1	EA
OYIV	IMU Repair Level 2 - 7094	6605-01-259-7094	4006	1	EA
OYIV	IMU Repair Level 3 - 7094	6605-01-259-7094	4007	1	EA
OYIV	IMU No Fault Found (NFF) - 7094	6605-01-259-7094	4008	1	EA
OYIV	AMSS Retrofit – 7512	6610-01-384-7512	4009	1	EA
OYIV	AMSS Major Repair Level 1 – 7512	6610-01-384-7512	4010	10	EA
OYIV	AMSS Medium Repair Level 2 – 7512	6610-01-384-7512	4011	1	EA
OYIV	AMSS Minor Repair Level 3 – 7512	6610-01-384-7512	4012	1	EA
OYIV	AMSS No Fault Found (NFF) - 7512	6610-01-384-7512	4013	1	EA
OYIV	AMSS Material Lay-In (Gyros) - 7512	6610-01-384-7512	4014	25	EA
OYIV	AMSS Material Lay-In (HVPS) – 7512	6610-01-384-7512	4015	5	EA
OYIV	AMSS Material Lay-In (Triad Cables) - 7512	6610-01-384-7512	4016	1	EA
OYIV	AMSS Material Lay-In (Isolators) – 7512	6610-01-384-7512	4017	15	EA
OYIV	AMSS Material Lay-In (Accelerometer) - 7512	6610-01-384-7512	4018	1	EA
OYIV	Over & Above (O&A)		4019	1	TBN
OYIV	Over & Above (O&A) – Surge Expedite Fee		4020	1	TBN
OYIV	Data		4021	1	NSP

7. **Contract Type and Length:** Firm Fixed Price Requirements type contract. Multi-year contract (Base plus four 1-Year Option) for the Repair of the B-2 Attitude Motion Sensor Set (AMSS) and Inertial Measurement Unit (IMU).
8. **IUID Note to Contractor:** If unit price exceeds \$5,000, then IUID requirements will apply.
9. Written procedures will be used for this solicitation. No telephone requests. Only electronic requests received directly from the requestor are acceptable. Only the responsible sole source solicited may submit a bid, proposal, or quotation, which shall be considered. Note: An Ombudsman has been appointed to hear concerns from offerors or potential offerors during the proposal development phase of this acquisition. The purpose of the Ombudsman is not to diminish the authority of the program director or contracting officer, but to communicate contractor concerns, issues, disagreements, and recommendations to the appropriate government personnel. When requested, the Ombudsman will maintain strict confidentiality as to the source of the concern. The Ombudsman does not participate in the evaluation of proposals or in the source selection process. Interested parties are invited to call Ombudsman at (405) 736-3273. **DO NOT CALL THIS NUMBER FOR SOLICITATION REQUESTS.**
10. All responsible sources may submit a capability statement, proposal, or quotation, which shall be considered by the agency.
11. **POC: Kristen Carter** at kristen.carter@us.af.mil, **NAICS:** 336413