Bhasin Auto Works

77, Oak Ganj, Satara-562588
GSTIN: 06DK2771H1Z1 | Ph: 01473210469

Invoice No.	INV/418/26	**Date**	2026-03-17
Customer	Chavvi Walla	**Vehicle**	Hyundai i20 Sportz
Reg. No.	HR89CW3496	**Job Card**	JC/6111

#	Description	Amount (Rs.)
1	Rear Bumper - replacement	8,440
2	Fender - replacement	6,460
3	Taillight - replacement	4,180
4	Painting and finishing	6,500
5	Labour charges	4,530
Subtotal		**30,110**
GST @ 18%		**5,420**
Total Payable		**35,530**

Payment due on delivery. Warranty on replaced parts as per manufacturer terms. This is a computer-generated invoice.