



Common stepper audible noise problem




Micro-stepping setting




www.orientalmotor.com

Step frequency setting




Sound pressure level plot


PWM frequency and current ripple



Microstepping Current vs STEP Input, Mixed Decay




Microstepping Current vs STEP Input, Slow Decay




Mixed Decay vs Smart Tune Ripple Control (STRC) at 1/256 Microstepping


Decay mode setting



Slow Decay on Increasing and Decreasing Steps




Smart tune ripple control decay




Smart tune dynamic decay


Zero-cross current error




Current Distortion Due to High Blanking Time



Smoothness of Zero-Cross at 1/16 Microstepping



Current Distortion Due to High OFF Time



Smoothness of Zero-Cross at 1/64 Microstepping

Reference

- 1. How to Reduce Audible Noise in Stepper Motors
- 2. DRV8711 Decay Mode Setting Optimization
- 3. Smart tune for quiet and smooth stepper motor operation
- 4. stepper motor overview
- 5. Minimizing Stepper Motor Vibration

To find more stepper driver technical resources and search products, visit ti.com/stepper



© Copyright 2018 Texas Instruments Incorporated. All rights reserved.

This material is provided strictly "as-is," for informational purposes only, and without any warranty. Use of this material is subject to TI's **Terms of Use**, viewable at TI.com