
(a)
alarms before t_1 (%)
75
50
25
0
(b)
$\beta_1 - 1$
0.0
−0.2
−0.4
−0.6
step
linear ramp
two-phase exponential
RMS detectors
detectors at 5% FAR
control charts
charts at 5% FAR