Streetwork compliance report (Video ID: test_video_1)

Checks:

BARRIER_CONTINUITY - Not Compliant

- [00:00 - 00:07] (high) There is a noticeable gap between the first and second barricade units, compromising the continuity of the barrier system.

PPE - Not Compliant

- [0 - 0] (high) Pedestrians are not wearing high-vis vests.
- [0 - 0] (high) Pedestrians are not wearing hard hats.

CHAPTER_8_SIGNAGE - Not Compliant

- [00:00 - 00:07] (low) The signage is present but lacks clarity due to poor visibility.

Recommendations:

- Verify that each unit is locked and properly aligned.
- Inspect signage compliance and enforce penalties for violations.
- Ensure all pedestrians comply with high-vis vest and hard hat requirements.
- Inspect the connection points between units to guarantee integrity.
- Verify that the signage complies with UK standards regarding size, color, and placement.
- Ensure the signage is clearly visible and legible by improving lighting or positioning.
- Provide training on mandatory PPE regulations.
- Ensure all barricade units are securely connected without any gaps.

Notes:

- Report aggregated from 3 sequential LVLM calls.

Evidence Frames:

BARRIER_CONTINUITY evidence frames

Timestamp: 0s



Timestamp: 7s



CHAPTER_8_SIGNAGE evidence frames

Timestamp: 0s



Timestamp: 7s