Note:

1. Above all measurements have been checked by GIS Mapping tool.

2. Seat efforts have been made to include BSN. Existing SSN-RTR OFC as shown in G

3.But BSN. Existing OFC has not been utilized because the OFC cable has sheady by editoring section or NTR fibers are not available.