

PLANT EQUIPMENT MAINTENANCE REPORT

ROUTINE & THERMAL INSPECTION LOG — PROCESSING UNIT 2

Machine ID	P-102	Inspection Date	25 August 2026
Machine Type	Industrial Water Pump (High-Flow)	Location	Processing Unit 2 - Sub-station B
Inspector Name	R. Sharma (Senior Maintenance Tech)	Operating Hours	4,250 hrs

Thermal Sensor Readings

Sensor ID	Location / Port	Measured Temp (°C)	Baseline Ref (°C)	Status
Sensor 1	Inlet Housing	82°C	65°C	Elevated
Sensor 2	Outlet Housing	85°C	65°C	Elevated
Sensor 3	Primary Bearing Assembly	91°C	70°C	Critical
Sensor 4	Motor Casing	88°C	70°C	Warning
Sensor 5	Secondary Bearing / Shaft	94°C	70°C	Critical

Observed Conditions & Physical Inspection Notes

Thermal Anomaly Detected

The pump has shown repeated overheating during continuous operation over the last 12-hour shift. Thermal imaging confirms localized heat spikes near the main bearing assembly.

Additional Field Observations:

- Abnormal acoustic vibration and high-frequency metallic chatter noticed during inspection.
- Slight fluid residue observed near shaft seal.
- Ambient room temperature: 31°C.

Technician Recommendation

Further detailed inspection and engineering analysis are strongly recommended before continuing full-load operation.

Approved by: Plant Operations Lead
Document Ref: REP-2026-08-P102

Status: PENDING ENG REVIEW
Sign-off Date: 25-Aug-2026