



Gulfstar Aero Technics

FAA Part 145 Repair Station GSTR451K | Houston, TX

TASK CARD T03

Work Package 7781

Customer:	Brazos Air	Registration:	N123AB
Aircraft Model:	A320-214	MSN:	6243
Location:	IAH - Hangar 2	Date Performed:	07/21/26
ATA:	32-31	Customer Ref:	PO 88-21974

1. DISCREPANCY (as reported)

LEAK OBSERVED LEFT MAIN GEAR ACTUATOR, HYDRAULIC FLUID ON STRUT AND IN WHEEL WELL.

2. RECTIFICATION

Replaced actuator rod seal kit. Leak check 15 min at system pressure, no leaks. Ops check good.

3. MATERIALS

Action	Part No.	Serial / Batch	Qty	Description
INSTALLED	SK-323141-02	Batch B4471	1	Actuator rod seal kit

4. REFERENCE DATA: AMM 32-31-41 (Rev 2026-04, customer-supplied)

CERTIFYING STAFF

J. Whitfield

A&P 3384712 07/21/26

QUALITY ASSURANCE

D. Nguyen

QA-118 07/21/26