



Customer:

Aircraft Model:

Location:

ATA:

Brazos Air

A321-231

IAH - Hangar 2

21-51

Registration:

MSN:

Date Performed:

Customer Ref:

N789EF

7019

08/18/26

PO 88-21974

1. DISCREPANCY (as reported)

PACK 2 OVHT ECAM REPEAT. REF PREVIOUS W/O BZ-26-05055.

2. RECTIFICATION

Replaced pack 2 compressor outlet temperature sensor. Ops check good, pack ran 30 min with no fault.

3. MATERIALS

Action	Part No.	Serial / Batch	Qty	Description
REMOVED	9600-04	TS-8821	1	Temp sensor, compressor outlet
INSTALLED	9600-04	TS-9310	1	Temp sensor, compressor outlet

4. REFERENCE DATA: AMM 21-63-15 (Rev 2026-04, customer-supplied)

CERTIFYING STAFF

J. Whitfield

A&P 3384712 08/18/26

QUALITY ASSURANCE

D. Nguyen

QA-118 08/18/26