Technical Bulletin 6 Cyl. 6 Subject Part Identifier Number Replace Cabriolet Locating Pins 6110 9513

ATTENTION: Service Manager / Service Technician

Models Affected: All 911 Models With Electrically Operated Cabriolet Top

Concern: When the Cabriolet top is opened, the locating pins may stick or bind in


the windshield frame guides.

General Information: If the Cabriolet top locating pins stick or bind in the windshield frame

guides, the Cabriolet top locating pins should be changed to the Targa soft top version (shorter) and the top should be re-adjusted accordingly.

Parts Information: Locating Pin (Targa)

911 565 074 40 (Qty. 2)



Vehicle Information: The shorter Targa version pins were installed in production as of May

24, 1995

Important Notice: Porsche Cars N.A Technical Bulletins are intended for use by professional technicians, not a "Do-it-yourselfer." They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Special tools may be required to perform certain operations identified in these bulletins. Use of tools and procedures other than those recommended in these bulletins may be detrimental to the safe operation of your vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your Porsche Dealer for information on whether your vehicle may benefit from the information. Part numbers listed in these bulletins are for reference only. Always check with your authorized Porsche dealer to verify correct part numbers.

The trademarks Porsche®, Targa®, Carrera®, Tiptronic®, Variocam® and the Porsche Crest are registered trademarks of Dr. Ing. h.c.F. Porsche AG and its affiliate, Porsche Cars North America, Inc.

