


 $\frac{M_{LE}}{M_{TE}}\frac{M_2}{M_1} = 1.800E + 00$ $\frac{M_{PEAK}}{M_{TE}} = 1.400E + 00$

 $\frac{M_{PRESS}}{M_{TE}} \frac{M_2}{M_1} = 1.000E + 00$ $\frac{L_{LE}}{L_{TOT}} = 1.000E-01$

 $\frac{L_{PRESS}}{I_{TOT}} = 4.000E-01$ xDist = 7.800E-02 $M_1 = 2.000E-01$

 $M_2 = 4.000E-01$ $\frac{M_1}{M_2} = 5.000$ E-01

 $M_{LE_{input}} = 9.000E-01$ $M_{PRESS_{input}} = 5.000E-01$



 $\frac{M_{LE}}{M_{TE}} \frac{M_2}{M_1} = 1.800E + 00$ $\frac{M_{PEAK}}{M_{TE}} = 1.400E + 00$

 $\frac{M_{PRESS}}{M_{TE}} \frac{M_2}{M_1} = 1.000E + 00$ $\frac{L_{LE}}{L_{TOT}} = 1.000E - 01$


 $\frac{L_{TOT}}{L_{TOT}} = 1.000\text{E-O1}$ $\frac{L_{PEAK}}{L_{TOT}} = 5.000\text{E-O1}$

xDist = 1.000E-01 $M_1 = 2.000E-01$ $M_2 = 4.000E-01$

 $\frac{L_{PRESS}}{I_{TOT}} = 4.000E-01$

 $\frac{M_1}{M_2} = 5.000E-01$

 $M_{LE_{input}} = 9.000\text{E-}01$ $M_{PRESS_{input}} = 5.000\text{E-}01$




 $\frac{M_{LE}}{M_{TE}}\frac{M_2}{M_1} = 1.800E + 00$ $\frac{M_{PEAK}}{M_{TE}} = 1.400E + 00$

 $\frac{L_{LE}}{L_{TOT}} = 1.000E-01$ $\frac{L_{PEAK}}{I_{TOT}} = 5.000E-01$

xDist = 1.500E-01 $M_1 = 2.000E-01$ $M_2 = 4.000E-01$

 $\frac{M_1}{M_2} = 5.000$ E-01 $M_{LE_{input}} = 9.000E-01$

 $M_{PRESS_{input}} = 5.000E-01$



 $\frac{M_{LE}}{M_{TE}}\frac{M_2}{M_1} = 1.800E + 00$ $\frac{M_{PEAK}}{M_{TE}} = 1.400E + 00$


 $\frac{M_{PRESS}}{M_{TE}} \frac{M_2}{M_1} = 1.000E + 00$ $\frac{L_{LE}}{L_{TOT}} = 1.000E-01$

xDist = 2.500E-01 $M_1 = 2.000E-01$ $M_2 = 4.000E-01$

 $\frac{L_{PRESS}}{I_{TOT}} = 4.000E-01$

 $\frac{M_1}{M_2} = 5.000$ E-01 $M_{LE_{input}} = 9.000E-01$

 $M_{PRESS_{input}} = 5.000E-01$




 $\frac{M_{LE}}{M_{TE}}\frac{M_2}{M_1} = 1.200E + 00$ $\frac{M_{PEAK}}{M_{TE}} = 1.400E + 00$

 $\frac{M_{PRESS}}{M_{TE}} \frac{M_2}{M_1} = 1.000E + 00$ $\frac{L_{LE}}{L_{TOT}} = 1.000E-01$


xDist = 7.800E-02 $M_1 = 2.000E-01$


 $M_2 = 4.000E-01$ $\frac{M_1}{M_2} = 5.000$ E-01

 $M_{LE_{input}} = 6.000E-01$ $M_{PRESS_{input}} = 5.000E-01$




 $\frac{L_{PEAK}}{I_{TOT}} = 5.000E-01$ $\frac{L_{PRESS}}{I_{TOT}} = 4.000E-01$ xDist = 7.800E-02 $M_1 = 2.000E-01$ $M_2 = 4.000E-01$ $\frac{M_1}{M_2} = 5.000$ E-01 $M_{LE_{input}} = 9.000E-01$ $M_{PRESS_{input}} = 4.000E-01$







 $\frac{L_{PEAK}}{I_{TOT}} = 5.000E-01$ $\frac{L_{PRESS}}{L_{TOT}} = 4.000E-01$ xDist = 7.800E-02 $M_1 = 1.000E-01$ $M_2 = 3.000E-01$ $\frac{M_1}{M_2} = 3.333E-01$ $M_{LE_{input}} = 6.000E-01$



 $\frac{L_{PEAK}}{I_{TOT}} = 5.000E-01$ $\frac{L_{PRESS}}{L_{TOT}} = 4.000E-01$ xDist = 7.800E-02 $M_1 = 1.000E-01$ $M_2 = 3.000E-01$ $\frac{M_1}{M_2} = 3.333E-01$ $M_{LE_{input}} = 4.000E-01$ $M_{PRESS_{input}} = 3.333E-01$



 $\frac{L_{PEAK}}{I_{TOT}} = 5.000E-01$ $\frac{L_{PRESS}}{L_{TOT}} = 4.000E-01$ xDist = 7.800E-02 $M_1 = 1.000E-01$ $M_2 = 3.000E-01$ $\frac{M_1}{M_2} = 3.333$ E-01 $M_{LE_{input}} = 6.000E-01$ $M_{PRESS_{input}} = 2.667E-01$



 $\frac{L_{PEAK}}{I_{TOT}} = 5.000E-01$ $\frac{L_{PRESS}}{L_{TOT}} = 4.000E-01$ xDist = 7.800E-02 $M_1 = 1.000E-01$ $M_2 = 3.000E-01$ $\frac{M_1}{M_2} = 3.333$ E-01 $M_{LE_{input}} = 4.000E-01$ $M_{PRESS_{input}} = 2.667E-01$