


## Report sheet appusbcar

### -Appusbcar 1Port:

1. Problem. The metal lateral contact does not fix with the housing correctly.

Look:



In the design:


The lateral metal contact fix in the housing for this system. In the mocke up this system doesn't exist.

Look.



Please solve this problem, it's dangerous if it make short circuit.

2. The spring should be into the box housign as picture...



Please, solve this problem.

3. The led is circular, but it should be rectangular for it can introduce in the led hole.  
OK?


As the led of this picture.



- **Appusbcar 2 ports:**

1. Problem. The metal lateral contact does not fix with the housing correctly.

Look:



In the design:


The lateral metal contact fix in the housing for this system. In the mocke up this system doesn't exist.

Look.



Please solve this problem, it's dangerous if it make short circuit.

2. The spring should be into the box housign as picture...



3. Please, as the logo it cannot put in the frontal sticker, put in the slick- screen:  
As illustrator file.

**Report technical department**

1. The red cable should be black in each cases
2. The Usbcar of two ports doesn't work, my partner applied 5 W of charge and the advice did not work.  
Please solve these problem...

