

Defect Detection Report (DDR)

Property Issue Summary

The property, a 11-floor flat (Flat No. 203), was inspected on 27.09.2022. The inspection revealed several defects and issues affecting various areas of the property. The defects are primarily related to dampness, leakage, and structural integrity.

Severity Table

Severity Level	Description
Critical	Immediate action required to prevent damage or harm
High	Urgent attention required to prevent significant damage or disruption
Medium	Attention required to prevent minor damage or disruption
Low	Minor issue, but still requires attention for maintenance purposes

Area wise Observations

Hall

- Skirting level dampness: Observed dampness at the skirting level of the Hall (Flat No. 103).
- Tile joints gaps: Observed gaps between the tile joints of the Common Bathroom of Flat No. 103.

Bedroom

- Skirting level dampness: Observed dampness at the skirting level of the Common Bedroom of Flat No. 103.
- Tile joints gaps: Observed gaps between the tile joints of the Common Bathroom of Flat No. 103.

Master Bedroom

- Skirting level dampness: Observed dampness at the skirting level of the Master Bedroom of Flat No. 103.
- Wall surface dampness & efflorescence: Observed dampness & efflorescence on the wall surface of Master Bedroom of Flat No. 103.
- External wall cracks: Observed cracks on the External wall of building near Master Bedroom of Flat No. 103.

Kitchen

- Skirting level dampness: Observed dampness at the skirting level of the Kitchen of Flat No. 103.

Common Bathroom

- Tile joints gaps: Observed gaps between the tile joints of the Common Bathroom of Flat No. 103.
- Leakage: Observed leakage at the Parking ceiling below Flat No. 103.
- Plumbing issue: Observed plumbing issue & gaps between the tile joints of Common Bathroom of

Flat No. 103.

Parking Area

- Leakage: Observed leakage at the Parking ceiling below Flat No. 103.

External Wall

- Cracks: Observed cracks on the External wall of building near Master Bedroom of Flat No. 103.
- Algae fungus and Moss: Observed algae fungus and Moss on external wall.
- Bird droppings condition: Observed bird droppings condition on external wall and Chajja.

Probable Root Cause

The probable root cause of the defects observed is related to:

- Water leakage: Water leakage from the parking area ceiling below Flat No. 103 is causing dampness and efflorescence on the walls and floors.
- Poor plumbing: Poor plumbing and gaps between tile joints are causing leakage and water damage.
- Structural issues: Cracks on the External wall of building near Master Bedroom of Flat No. 103 indicate structural issues.

Severity Assessment

Area Defect Severity Level

Hall Skirting level dampness Medium

Bedroom Skirting level dampness Medium

Master Bedroom Skirting level dampness, wall surface dampness & efflorescence High

Kitchen Skirting level dampness Medium

Common Bathroom Tile joints gaps, leakage, plumbing issue High

Parking Area Leakage High

External Wall Cracks, algae fungus and Moss, bird droppings condition High

Recommended Actions

1. Immediate repair: Repair the leakage at the parking area ceiling below Flat No. 103.
2. Plumbing repair: Repair the poor plumbing and gaps between tile joints in the Common Bathroom.
3. Structural repair: Repair the cracks on the External wall of building near Master Bedroom of Flat No. 103.
4. Waterproofing: Apply waterproofing to the walls and floors to prevent further water damage.
5. Regular maintenance: Regularly inspect and maintain the property to prevent minor issues from becoming major problems.


Additional Notes

- The property's age and previous structural audit and repair work are not available.
- The property's condition is affected by the presence of algae fungus and Moss on the external wall.
- The bird droppings condition on the external wall and Chajja requires immediate attention.

Missing or Unclear Information


- The property's previous structural audit and repair work are not available.
- The condition of the expansion joints, condition of corrosion/spalling of concrete/exposed reinforcement, and condition of wall mounted AC Frames, holes, drain pipes over the wall are not available.
- The condition of the substrate plaster, patchwork plaster required, and entire replaster required are not available.
- The condition of the separation cracks observed at beam-column junction and leakage observed from overhead water tank are not available.
- The condition of the loose plaster/hollow sound on external surfaces is not available.


Thermal Inspection Images:




27/09/22


Hotspot :	28.8 °C
Coldspot :	23.4 °C
Emissivity :	0.94
Reflected temperature :	23 °C





27/09/22		
	Hotspot :	26 °C
	Coldspot :	21 °C
	Emissivity :	0.94
	Reflected temperature :	23 °C





27/09/22

	Hotspot :	27.3 °C
	Coldspot :	22.3 °C
	Emissivity :	0.94
	Reflected temperature :	23 °C

