

Defect Detection Report (DDR)

Summary of Inspection

This Defect Detection Report (DDR) is based on the inspection conducted on September 27, 2022, at Flat No. 203. The inspection was carried out by Krushna & Mahesh, and the report highlights the observed defects and their severity levels.

Detected Defects

The following defects were detected during the inspection:

Area	Defect	Severity Level	Priority Level
Hall	Dampness at skirting level	Medium	Medium
Common Bathroom	Dampness at skirting level	Medium	Medium
Common Bedroom	Dampness at skirting level	Medium	Medium
Master Bedroom	Dampness at skirting level	Medium	Medium
Kitchen	Dampness at skirting level	Medium	Medium
Master Bedroom	Dampness & efflorescence on wall surface	High	High
Parking Area	Leakage at ceiling below	High	High
Common Bathroom	Mild dampness at ceiling	Medium	Medium
External Wall	Cracks near Master Bedroom	Medium	Medium
External Wall	Plumbing issue & gaps between tile joints	High	High

Severity Level Table

Severity Level Description

Low Minor defects that do not affect the structural integrity of the building.

Medium Defects that affect the aesthetic appeal of the building but do not compromise its structural integrity.

High Defects that compromise the structural integrity of the building or pose a significant risk to the occupants.

Critical Defects that pose an immediate risk to the occupants or the building's structural integrity.

Possible Causes

The possible causes of the detected defects are:

- 1. Water seepage due to cracks in the external wall.
- 2. Poor plumbing connections and leaks.
- 3. Inadequate ventilation and drainage in the bathrooms.
- 4. Dampness and efflorescence due to high humidity and poor ventilation.
- 5. Poor maintenance and repair of the building's structure.

Recommended Maintenance or Repair Actions

The following maintenance or repair actions are recommended:

1. Repair the cracks in the external wall to prevent water seepage.
2. Fix the plumbing leaks and connections to prevent water damage.
3. Improve ventilation and drainage in the bathrooms to prevent dampness and efflorescence.
4. Apply a waterproof coating to the external wall to prevent further damage.
5. Conduct regular maintenance and inspections to prevent future defects.

Grouped Observations by Area

1. Hall

Dampness at skirting level (Medium)

2. Common Bathroom

Dampness at skirting level (Medium)

Mild dampness at ceiling (Medium)

Plumbing issue & gaps between tile joints (High)

3. Common Bedroom

Dampness at skirting level (Medium)

4. Master Bedroom

Dampness at skirting level (Medium)

Dampness & efflorescence on wall surface (High)

5. Kitchen

Dampness at skirting level (Medium)

6. Parking Area


Leakage at ceiling below (High)

7. External Wall

Cracks near Master Bedroom (Medium)


Plumbing issue & gaps between tile joints (High)


Thermal Inspection Images:




27/09/22


Hotspot :	28.8 °C
Coldspot :	23.4 °C
Emissivity :	0.94
Reflected temperature :	23 °C





27/09/22		
	Hotspot :	26 °C
	Coldspot :	21 °C
	Emissivity :	0.94
	Reflected temperature :	23 °C





27/09/22

	Hotspot :	27.3 °C
	Coldspot :	22.3 °C
	Emissivity :	0.94
	Reflected temperature :	23 °C

