

South Central Railway



Office of the DRM/T/SC,
Sanchalan Bhavan,
Secunderabad.

No.C/T/187/SC/2025/11.

Date: 06.11.2025

All TIs/SMRs/SMs

OPERATING SAFETY CIRCULAR No.11/25

Sub: Detailed and clear instructions on T-806-Reg.

During a review meeting of Safety by the Railway Board on 15.10.2025, the following observation has been made about a case of derailment of loco at Hapur yard of Moradabad Division in NR on 10.10.2025. The derailment of Loco was happened while shunting load on PQRS siding.

In this context it is once again reiterated that during shunting operations, the shunting order (T-806) should contain detailed and clear instructions to provide unambiguous guidance to staff carrying out shunting operations.

Hence it is instructed that all supervisors to ensure that during shunting operations T-806 to be prepared legibly with clear instructions and issued to LP/TMR/Shunter duly obtaining the acknowledgement and also follow the instructions provided in GR&SR 5.13 and GR&SR 5.14 of SCR G&SR2020.

All TIs/SMRs to counsel the staff in this regard and ensure strict compliance.

(B. Sudheer Kumar)
DOM/Genl./SC

Copy to: DRM/SC for kind information
ADRM/O/SC for kind information
Sr.DOM/SC for kind information
Sr.DSO/SC for kind information
All DOMs & AOMs/ AOs for information