

YOUR INDEPENDENT PROPERTY QUALITY PARTNER

Property inspection report.

An illustrative example of clear reporting, defined severity and actionable recommendations.

Illustrative residential property, Nagpur

01 October 2026 (example date) · Fictional scope and findings

87 / 100

GOOD · INDICATIVE SCORE

108 / 120

INSPECTION POINTS ASSESSED

14

ILLUSTRATIVE DEFECTS

1

CRITICAL

4

MAJOR

6

MODERATE

3

MINOR

A good score does not override a Critical finding.

The example contains one Critical finding requiring prompt professional attention. The score is not a structural stability or absolute safety certification.

108 / 120 means points assessed, not points passed. Twelve points were not assessed in this example. The score is not the completion percentage and is not calculated here from the defect count.

The CivicQC Inspection Score is an indicative assessment based on the inspected components and defined inspection criteria. It is not a structural stability certificate, safety guarantee, or guarantee against concealed defects.

Indicative rating bands

90–100	Excellent
80–89	Good
70–79	Fair
60–69	Needs Attention
Below 60	Critical

FROM OBSERVATION TO ACTION

A finding you can understand.

D03 · Living room · Moisture at the window reveal



AI-GENERATED ILLUSTRATIVE PHOTOGRAPH. NOT CLIENT EVIDENCE.

MAJOR — Significant defect requiring corrective action.

Dampness indicators are noted at the wall-window junction in the illustrative scenario.

Recommended next step

Investigate the source and agree rectification before repainting.

How to read this report

Observations state what was accessible and observed within the agreed scope. Recommendations identify sensible next steps; they are not an instruction to carry out unsafe work or a guarantee of the exact root cause. Appropriate specialists should assess safety-related or technically complex concerns.

The sample photograph illustrates the reporting format only. Other rows in this sample are fictional text examples; no genuine client photographs or laboratory results are presented.

SYSTEMATIC. DOCUMENTED. INDICATIVE.

Observations 01–05

D01 / KITCHEN / CRITICAL

Unfinished electrical outlet

Exposed conductors are visible at an unfinished outlet in this fictional example.

Recommended next step: Do not use the point. Arrange prompt assessment and safe rectification by a qualified electrician.

D02 / BEDROOM / MAJOR

Hollow-sounding floor tiles

A cluster of tiles gives a hollow response during the example functional check.

Recommended next step: Ask the builder to assess adhesion and arrange appropriate rectification.

D03 / LIVING ROOM / MAJOR

Moisture at the window reveal

Dampness indicators are noted at the wall-window junction in the illustrative scenario.

Recommended next step: Investigate the source and agree rectification before repainting.

D04 / TERRACE / WET AREA / MAJOR

Persistent water pooling

Water remains near an accessible drainage junction in this example.

Recommended next step: Have the contractor review drainage and relevant surface details.

D05 / WALL JUNCTION / MAJOR

Visible crack requiring assessment

A visible crack at a junction merits a closer professional review in this example.

Recommended next step: Arrange appropriate professional assessment; do not infer structural adequacy from a visual inspection.

SYSTEMATIC. DOCUMENTED. INDICATIVE.

Observations 06–10

D06 / BATHROOM / MODERATE

Incomplete grout joints

Gaps are visible in selected grout joints.

Recommended next step: Have the affected joints prepared and made good with a suitable material.

D07 / KITCHEN / MODERATE

Leakage at accessible connection

Moisture is visible at an accessible pipe connection in the example.

Recommended next step: Have a competent plumber review the connection and verify the completed work.

D08 / BATHROOM / MODERATE

Incomplete sealant joint

Sealant continuity is incomplete at an accessible junction.

Recommended next step: Agree appropriate preparation and resealing after checking the underlying condition.

D09 / WINDOW / MODERATE

Visible sealing gaps

A localised gap is visible at the frame-to-wall seal.

Recommended next step: Request inspection of the joint and a suitable sealing repair.

D10 / BALCONY / MODERATE

Loose accessible fitting

A fitting shows movement during an accessible functional check.

Recommended next step: Have the fixing checked and rectified by the appropriate contractor.

SYSTEMATIC. DOCUMENTED. INDICATIVE.

Observations 11–14

D11 / BEDROOM / MODERATE

Uneven tile alignment

A noticeable level difference is recorded between adjacent tiles.

Recommended next step: Review the extent with the builder and agree appropriate correction.

D12 / BEDROOM / MINOR

Patchy paint finish

Uneven paint coverage is visible under the example inspection lighting.

Recommended next step: Prepare the surface and make good the finish.

D13 / LIVING ROOM / MINOR

Minor surface scratches

Local cosmetic scratches are visible on an accessible finish.

Recommended next step: Agree a suitable cosmetic repair and protect the finished surface.

D14 / ENTRANCE / MINOR

Stiff door latch

The latch operates with avoidable resistance in this illustrative example.

Recommended next step: Adjust the fitting and verify smooth operation.

CONSISTENT CRITERIA. CLEAR LIMITATIONS.

Severity & scope.

CRITICAL

Potentially serious safety or property concern requiring prompt professional attention.

MAJOR

Significant defect requiring corrective action.

MODERATE

Noticeable defect affecting quality or functionality.

MINOR

Low-impact or primarily cosmetic observation.

Inspection Disclaimer

CivicQC inspection services are intended to identify observable and instrument-assisted construction, workmanship, moisture, finishing and functional concerns within the defined inspection scope. An inspection does not guarantee the absence of concealed defects and should not be represented as a structural stability certificate or absolute safety certification unless a separately qualified service is specifically provided. Specialized laboratory testing and engineering assessments may be subject to separate scope and charges.

The CivicQC Inspection Score is an indicative assessment based on the inspected components and defined inspection criteria. It is not a structural stability certificate, safety guarantee, or guarantee against concealed defects.

After rectification

Keep the original findings and the builder's rectification information. A separately agreed Re-Inspection can record accessible rectification status and before/after comparisons where applicable. It does not guarantee that all concealed issues have been eliminated.

CivicQC Consultants · Nagpur, Maharashtra

Call / WhatsApp: +91 8275363060

Email: civicqc.consultants@gmail.com

All property details, dates, observations, counts and the score in this document are fictional examples. This sample must not be presented as an actual client inspection or certification.