

Diagnostics Report

2025-09-24 14:46:53

Customer Details Repair Details

Customer:

Telephone

Work Order 29682

Huggins Work Order Repair Order

Address Registration B19BUB

Vehicle 2019/Mitsubishi/L200 (KK#,KL#)/

VIN MMCJYKL10KH016167

Odometer 73607miles

Insurance

Report Type: pre-scan

Scan Overview

1 1 0 Fault Found Affected Modules Fault Cleared

Module Checklist

System	Status	DTC
MPI/GDI/Diesel	②	0
AT/CVT/A-MT/TC-SST	②	0
ABS/ASC/ASTC/WSS	②	0
SRS-Air Bag	②	0
Meter	②	0
Air Conditioner	②	0
Lane Keep ADAS	®	1
ETACS	②	0
KOS/OSS/IMMO/Keyless - without KOS	②	0
AUDIO	②	0

DTCs

C1706 Lane Departure Warning (LDW) camera adjustment not completed Active

DTC