

Diagnostics Report

2025-09-23 14:04:08

<u>Customer Details</u> <u>Repair Details</u>

Customer: Huggins Work Order 2950

Address Registration DL24EVN

Vehicle 2024/Vauxhall/COMBO LIFE VIN WOVEDYHT5RJ741068

Telephone Odometer 13688miles

Insurance

Repair Order

Report Type: pre-scan

Scan Overview

30 8 0
Fault Found Affected Modules Fault Cleared

Module Checklist

System	Status	DTC
Built-in Systems Interface (BSI) BSI2010_EV	⊗	22
Engine ECU CMM_MD1CS003_EURO6_4	(X)	1
ABS or ESP ESP90	\odot	0
Airbags and pretensioners ECU RBG_SPEED_UDS	(X)	1
Combination instrument DCS	(X)	1
Parking assist AAS_UDS_G6 ADAS	(X)	1
A/C BCC	\odot	0
AdBlue/DPF ECU SCR	\odot	0
Power steering DAE_UDS	×	1
Dynamic headlamp height adjuster BEMP_UDS ADAS	\odot	0
Overload indicator ECU OLVI	\odot	0
Controls under the steering wheel TCM	\odot	0
Steering wheel controls / Integral controls steering wheel VCI	\odot	0
Multi-function control panel FMUX	(X)	2
Seatbelt not fastened warning lamps unit TNB_2010	\odot	0
Rain/Light Sensor (RLS) CDPL_UDS_HELLA	\odot	0
Multi-function video camera (CMF) CVM_3 ADAS	❷	0
Touchscreen EMF_DGT_LVDS_BD	⊗	1

DTCs

Built-in Systems Interface (BSI) -- BSI2010_EV DTCs)

DTC	DTC Description	Status
U1FE6:87	No communication with radio frequency connectivity box	Intermittent
U1F3E:87	No communication with telematics ECU	Intermittent
B173D:86	Fault in identifying mechanical/electronic key or hands- free remote control present in reader Identifier Invalid	Intermittent
B2ED3:00	Loss of Built-in Systems Interface (BSI) time counter	Present
B116F:15	Right turn lamp repeater control fault Circuit open or short to positive	Intermittent



B116E:15	Fault in left turn lamp repeater control Circuit open or short to positive	Intermittent	
B1137:15	Right front low beam control fault Circuit open or short to positive	Intermittent	
B1138:15	Fault in left front low beam headlamp control Circuit open or short to positive	Present	
B118E:15	High beam activation relay control fault Circuit open or short to positive	Present	
B11F0:48	Traceability of the forcing of the maintaining of the low beam headlamps switch- on : Ignore this fault Software fault	Intermittent	
B162C:12	Accessories positive relay control and status inconsistent Relay not activated But Active	Intermittent	
B1710:11	Hinged rear door lock switch status fault Switch stuck or circuit short to ground	Intermittent	
B1717:64	Hinged rear door locking status fault Inconsistency with vehicle locking status	Present	
B171E:62	Hinged rear door lock fault Inconsistency	Intermittent	
B120A:62	Collision risk alert function fault Signal consistency fault	Intermittent	
B120D:68	Automatic braking at the risk of collision malfunction Incorrect information	Intermittent	
B1865:23	Inconsistency between status of engine starting switch and status of Built-in Systems Interface (BSI) engine starting authorization output	Intermittent	
B1805:62	Starter fault Consistency	Intermittent	
B1418:00	Fault in seatbelt fastening information status for determining presence of driver	Intermittent	
B132A:84	A/C circuit low pressure safety fault Signal below tolerance range	Intermittent	
U053B:81	Please refer to vehicle service manual.		
U1F16:08	ECU not communicating on the CAN	Intermittent	
DTC	DTC Description	Status	
U1218:81	Built-in Systems Interface (BSI) (CAN) Data received invalid	Intermittent	
B1400:64	CAN+ supply voltage Actuator present but not configured	Intermittent	
U1FA0:00	Low Voltage Differential Signaling (LVDS) signal response time incorrect Not characterized	Permanent	
B1250:05	Fault in left front lateral parking assist sensor Programming	Intermittent	
Power steering DAE_UDS (1 DTC)			
DTC	DTC Description	Status	
U1118:87	Built-in Systems Interface (BSI) Lost information	Permanent	



DTC	DTC Description	Status
U1F6C:00	No communication with the telematics unit control Not characterized	Intermittent
B1040:96	Internal fault of navigator Internal fault	Intermittent
U1FA0:00	Low Voltage Differential Signaling (LVDS) response time incorrect (Low Voltage Differential Signaling (LVDS))	Intermittent