

Diagnostics Report

2025-09-23 13:53:56

<u>Customer Details</u> <u>Repair Details</u>

Customer: AS Work Order 29505

Repair Order
Address -- Registration KV19BUC

Vehicle --/Benz/S (222)/ VIN WDD2221202A480670

Telephone Odometer 74971.54miles

Insurance

Report Type: post-scan

Scan Overview

0 0 0 Fault Found Affected Modules Fault Cleared

Module Checklist

| System | Status | DTC |
|--|----------|-----|
| ECM(Engine Control Unit) | ② | 0 |
| TCM(Transmission Control Unit) | ② | 0 |
| ESP(Electronically controlled vehicle stability braking system control unit) | ② | 0 |
| SRS(Supplemental Restraint System Control Unit) | ② | 0 |
| KI(Instrument Cluster) | ② | 0 |
| TPM(Tire Pressure Monitor Control Unit) | ② | 0 |
| PTS(Parking System) ADAS | ⊘ | 0 |
| SAMF(Front SAM signal acquisition control unit) | ② | 0 |
| LIN:ABF(Instrument Panel Switch) | ② | 0 |
| LIN:AU(Analog Clock) | ② | 0 |
| LIN:BSN(Battery Sensor) | ② | 0 |
| LIN:FSW(Wiper Motor) | ② | 0 |
| LIN:VCS(Rain/sunlight sensor) | ② | 0 |
| SAMR(Rear SAM signal acquisition control unit) | ② | 0 |
| LIN:SHM(Seat Heating/Ventilation) | ⊘ | 0 |
| EZS(Electronic Ignition Lock Control Unit) | ⊘ | 0 |
| ES(Electric Power Steering) | ⊘ | 0 |
| KLA(Air Conditioner Control Unit) | ⊘ | 0 |
| ADS(Suspension) | ⊘ | 0 |
| SCR(AdBlue control unit) | ⊘ | 0 |
| PTCU(Drivetrain Control Unit) | ⊘ | 0 |
| KG(Keyless Go Control Unit) | ⊘ | 0 |
| LIN:HSM(Rear Switching Control Unit) | ⊘ | 0 |
| SW-SW-R(Right Headlamp Control Unit) | ⊘ | 0 |
| SW-SW-L(Left Headlamp Control Unit) | ⊘ | 0 |
| SG-L-VR(Right front LED matrix light group control unit) | ⊘ | 0 |
| SG-L-VL(Left front LED matrix light group control unit) | ⊘ | 0 |
| LRE(Steering Wheel Electronics) | ⊘ | 0 |
| ABA(Collision Prevention Assist) | ⊘ | 0 |
| DMFL(Left Front Door Control Unit) | ⊘ | 0 |
| DMFR(Right Front Door Control Unit) | ⊘ | 0 |
| DMRR(Right Rear Door Control Unit) | ⊘ | 0 |
| DMRL(Left Rear Door Control Unit) | ⊘ | 0 |
| ZBE(Head Unit Display) | ② | 0 |



| TPAD(TPAD) | ② | 0 |
|---|----------|---|
| ZAN(Center Display Control Unit) | ② | 0 |
| SMFK(Multifunctional stereo camera) | ⊘ | 0 |
| RBTMFR(Right Front Seat Belt Tensioner Control Unit) | ② | 0 |
| RBTMFL(Left Front Seat Belt Tensioner Control Unit) | ⊘ | 0 |
| PSD(Sunroof Control Unit) | ⊘ | 0 |
| MTAS(Mobile Phone Cradle Control Unit) | ② | 0 |
| MRM(Steering Column Control Unit) | ❷ | 0 |
| HKS(Trunk Lid Control Unit) | ❷ | 0 |
| FSCU(Fuel Pump Control Unit) | ② | 0 |
| ESET-RR(Right Rear Seat Control Unit) | ❷ | 0 |
| ESET-RL(Left Rear Seat Control Unit) | ② | 0 |
| ESEP(Passenger Side Electric Seat Adjustment Control Unit) | ❷ | 0 |
| LIN:LSE-BFS(Front Passenger Seat Lumbar Support Control Unit) | ❷ | 0 |
| ESED(Driver Side Electric Seat Adjustment Control Unit) | ② | 0 |
| LIN:LSE-FS(Driver Seat Lumbar Support Control Unit) | ② | 0 |
| DTA(Telematics Service Control Unit) | ② | 0 |
| DBE(Sunroof Control Unit) | ② | 0 |
| LIN:AISP_2(Interior mirror) | ② | 0 |
| LIN:AS_2(Alarm Siren) | ② | 0 |
| AML(Ambient Lighting Lamp) | ⊘ | 0 |
| | | |

DTCs

DMRL(Left Rear Door Control Unit) (3 DTCs)

| DTC | DTC Description | Status |
|---------|---|-------------------------|
| B18B72A | Left rear power window' switch fault - no signal change | Active and stored |
| B22FE2A | Switch 'Roller sun blind for roof' has a malfunction. There is no signal change. | Active and stored |
| B22FF2A | Switch 'Roller sun blind for rear window' has a malfunction. There is no signal change. | Active and stored |